

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.03.2021

Time: 10:19:38

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305456369
REGN NO : SHC 360A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 01.03.2021 15:15
ACCIDENT DATE : 28.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G COVER-FR BUMPER#	1	430.90	20.00	344.72	RY
0002 04-01-0104-3813-G EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28	all
0003 04-01-0104-0574-G PANEL-FENDER LH#	1	588.80	20.00	471.04	RY

SUB-TOTAL : 837.04

JOB NATURE

0000 PB	PANEL BEATING	800.00	350.
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	850.

SUB-TOTAL : 1,450.00

TOTAL : 2,287.04

Jumani

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9741 5749
WR 2/3/21 @ 5pm
P/P Resurvey after repair
for the 1st time
2 days