



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20010398/T1qf3e2-1	
			Date: 11/03/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8721P	Veh. Inspected	SMQ 4732B	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20090406	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	05/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO SR	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KNAF5416ML5059944	Colour	WHITE	
Odometer	16714 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	NEXEN	6 mm	
L/H Front Tyre	225/45 R17	NEXEN	6 mm	
R/H Rear Tyre	225/45 R17	NEXEN	6 mm	
L/H Rear Tyre	225/45 R17	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2020	Inspection Date	29/09/2020	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	