

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/11/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1436E
Case Reference Number	BUS/02/21/7026
Registration Date	24/7/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Yau Minddin Bin Muhamad
Type of Accident	Side Swipe
Accident Date and Time	25/2/2021 8:00 AM
Accident Reported Date and Time	25/2/2021 7:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111226
Special Instruction to ARC,if any	SMB1436E - RIGHT CENTRE PORTION SGU7126G (TP) INSURED WITH NTUC
Prepared Date and Time	1/3/2021 10:01 AM
Chassis Number	WMAA22ZZ4E7002153
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$1,060.00
Total Spray Cost	\$878.00	\$786.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$1,440.00	\$0.00
TOTAL COST	\$3,643.00	\$1,846.00
Lump Sum Total	\$3,650.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	01/03/2021 10:06 AM	02/03/2021 1:52 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/11/2021

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,325.00	\$1,060.00
Total Labour	\$1,325.00	\$1,060.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	\$786.00
Total Spray Painting & Panel Beating	\$878.00	\$786.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$1,440.00	\$0.00
Total Other Costs	\$1,440.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009987	BODY RH	A01001-CW568	PANEL,SIDE:R6,FOR MAN A22 BUS	1.00	\$1,776.80	100.00	\$0.00	Repair	Repair
6009988	BODY RH	A01001-CW567	PANEL,SIDE:R7,FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	Repair
6009990	BODY RH	A01001-CW565	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	Repair
6009991	BODY RH	4000F06-ACCE4526	PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair
Total					\$3,565.70		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									