# MBM WHEELPOWER PTE LTD

Your Ref: SMP6171L Our Ref: SFK222Y

CC

Fax

To: BUDGET DIRECT / AGI

Date:

5/3/2021

From:

Danny

Fax:

64525333

Contact:

93288668

Make / Model:

TOYOTA ALPHARD 2.5

wheelpower

Chassis No.:

AGH309013690

Engine No.:

2AR2520173

Year of Make:

2020

Accident Date:

4 March 2021

**ESTIMATE FOR VEHICLE NO.:** 

SFK222Y

DESCRIPTION	QTY		List Price
FRONT RH DOOR	1	\$	2,078.00
FRONT RH DOOR HINGE UPP	1	\$	87.50
FRONT RH DOOR HINGE LOWER	1	\$	87.50
FRONT RH WEATHERSTRIP	1	\$	194.00
REAR RH DOOR	4	\$	2,856.80
REAR RH DOOR WEATHERSTRIP	1	\$	468.30
SIDE SKIRT GARNISH FRONT RH	1	\$	859.50
SIDE SKIRT GARNISH REAR RH	1	\$	812.70
	Tota	ıl: \$	7,444.30
	LESS 25	% \$	(1,861.08)
	Parts Tota	l: \$	5,583.23

#### LABOUR

English Services	
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$ 1,000.00
TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	\$ 300.00
TO APPLY ANTI RUST COATING	\$ 150.00
TO DISMANTLE & TRANSFER DOOR FITTINGS & MECHANISM TO NEW DOOR / FACILIATE REPAIR	\$ 260.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$ 80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$ 1,000.00
Total:	\$ 8,373.23
7% GST:	\$ 586.13
Grand Total:	\$ 8,959.35

Mbm wheelpower pte ltd 160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY t 62628888 f 64525333

Company Registration Number : 200204110W

# **SINGAPORE ACCIDENT STATEMENT**

#### IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
  2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance or this Form by insurance companies is not an admission of policy leading of the part of the insurance designation.

  5. Any false reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.

#### **ACCIDENT STATEMENT**

	05/03/2021 12:13 (SGT)
Date of Accident	04/03/2021 14:45 (SGT)
	Suntec City, Singapore
Additional Location Information	Suntec City Basement car park
Country/State of Loss	Singapore

Date of Accident  Exact Location of Accident  Additional Location Information  Country/State of Loss	04/03/2021 14:45 (SGT) Suntec City, Singapore Suntec City Basement car park Singapore
DETAILS OF	OWN VEHICLE
Vehicle Registration Number	SFK222Y
INSURED/POLICYHOLDER	
Is company?  Name Of Registered Owner  NRIC No  Email Address  Mobile Phone No  Alternative Phone No	No Kevin Lim Yeow Meng SXXXX228A K98716770@gmail.com (Phone) +65-81816848 (Home) +65-81816848
VEHICLE PARTICULARS	
Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category	Toyota Alphard - Private use No - Claiming third party Private car
INSURANCE COMPANY	
Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number	China Taiping Insurance Comprehensive No DMPCSNW00043502100 -
DRIVER	
Name of Driver	Sie Wei Wei Olivia SXXXX867J

19/06/1980 Indoor

Insurance Company of Other Vehicle Owned by Driver  GENERAL INFORMATION OF THE ACCIDENT  Type of Accident Collision - Clear Weather Conditions Clear Road Surface Dry  OTHER INFORMATION  Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1  Name Low Female	Major/Minor Rd
Type of Accident Weather Conditions Road Surface  OTHER INFORMATION  Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  No PASSENGER 1  Name Low Gender  Collision - Clear Dry	Major/Minor Rd
Weather Conditions Clear Road Surface Dry  OTHER INFORMATION  Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  PASSENGER 1  Name Low Gender Female	Major/Minor Rd
Was any foreign vehicle involved in the accident?  No Number of vehicles involved in the accident  Was anybody injured in the Accident?  Was any injured conveyed to hospital by ambulance?  Was any other material or property damaged?  Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  No PASSENGER 1  Name  Low Gender  Female	
Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  PASSENGER 1  Name Low Gender Female	
Name Low Female	
Gender	
DETAILS OF POLICE ACTION	
Was the accident reported to the police?  Was notice of intended Prosecution given?  If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
refer attached report.	
ATTACHMENT(S)	
Are accident photos available for attachment?  Was there any video captured by Car Camera?  No Was there any audio recorded?  No	

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMP6171L
Vehicle Manufacturer	-
Vehicle Model	•
Vehicle Variant	M*
Vehicle Colour	<del>-</del>
Vehicle Category	Private car
Name of Driver	Lau Chang Siong
NRIC No	SXXXX942F



Contact Number	(Phone) +65-90055573
Address	and the same of th
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	-

- LUNDON ON AND	
SKETCH PLAN  A B B B B B B B B B B B B B B B B B B	
100 In	W: SFK 2727
	R = SMP (0 3)U
-	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
The second secon	The state of the s
4 march 2001, around 14 45/117. In Suntec city Corpore, 1 vous drivin	absorpt tun
the exit , a stirulionary car in v	us car lot
I SMP GITTLE SUDDANDA JOH OPEN	hic by Angloy of
Mitting Into mex Car (driver side x taks	unger side) door.
(Refer to Carrera toctage)	and the second s
Driver got off admitted his faul	X INDAGO DO
Mis buttenions	
MR PARTICIONAL	The state of the s
	and the state of t
	and the second s
	and the second s
	and the control of th
The second secon	
	and the second s
The state of the s	
	and the second s
	The second secon
DECIARATION  Note deliarly the topogoing particulars are true in every respect.	
Policycolius & Signature Driver's Signature	Reporting Centre Parsname's Signature
Date & Time:    Date & Time:	Name: NRIC/FIS No :
Goldstandigogiese 34	, , , , , , , , , , , , , , , , , , ,

### > Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 228A

Vehicle Details

Vehicle No.: SFK222Y
Vehicle to be Exported: No

Intended Deregistration Date: 05 Mar 2021
Vehicle Make: TOYOTA

 Vehicle Model:
 ALPHARD 7-SEATER 2.5 SC CVT

 Primary Colour:
 Black

Manufacturing Year: 2020
Engine No.: 2AR2520173

 Engine No.:
 2AR2520173

 Chassis No.:
 AGH309013690

 Maximum Power Output:
 134.0 kW (179 bhp)

Open Market Value: \$53,171.00
Original Registration Date: 26 Feb 2021

First Registration Date: 26 Feb 2021
Transfer Count: 0

Actual ARF Paid: \$67,708.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Feb 2031

PARF Rebate Amount: \$50,781.00
Intended COE Rebate Details

COE Expiry Date: 25 Feb 2031

COE Category: E - Open - all except motorcycle

 COE Period(Years):
 10

 QP Paid:
 \$45,510.00

COE Rebate Amount: \$44,904.00
Total Rebate Amount: \$95,685.00

The information contained herein is correct as at 05 Mar 2021

ОК