

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305457528
Date : 10/03/21

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHA9832G

Date of Accident : 08/03/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG ASIA --- SFW3322J
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$55.00
 - (b) Labour Charges \$630.00
 - Total for Part-By-Part Repair Cost** \$685.00
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : TAUFIKH

Date : 8/4/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305457528
REGN NO : SHA9832G
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 08.03.2021 11:10
ACCIDENT DATE : 08.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS REAR NO.PLATE W/TRIM COVER 1 L 55.00 0.00 55.00

SUB-TOTAL : 55.00

JOB NATURE

0000 PB PANEL BEATING 350.00

0001 SP SPRAYPAINT CHARGE 250.00

0002 L R/I REVERSE SENSOR 30.00

SUB-TOTAL : 630.00

TOTAL : 685.00

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :