Messages

Claims



General & Workshop I	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Rat	io F	Parts & Labour	Miscellaneous		
		Summary							
General Details			Wo	Workshop Details					
Involving	TPVD I	HONDA CB400 (FBA6566R)		al Rebate	0				
Date of Loss	9 Janu	ary 2021	Am	ount					
Time of Loss	20:30		Net	t Loss Amount		-\$3,391.00			
Loss Description	SMQ52	2G (insd) c/w FB 6566R (tp)	Ass	Assigned Workshop LKK AUTO CONSULTANTS PTE LT			SULTANTS PTE LTD (TP)		
Comment				s of work		20			

Messages

Claims



					Miscellaneous
		Summary			
ils					
FBA6566R		Pur	chase Date	DD/MM/YYYY	
SINGAPORE		Reg	istration Date *	07/07/2006	
224454		Age	of Vehicle	14	
POLICY NFORMATION	ASSESSMENT INFORMATION	ON Dri	ver Details		
	2006		CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
			Driver Name	LEE JIANG YAO	
	FBA6566R SINGAPORE 224454 OLICY	FBA6566R SINGAPORE 224454 OLICY RFORMATION ASSESSMENT INFORMATION	FBA6566R Pur SINGAPORE Reg 224454 Age OLICY ASSESSMENT INFORMATION Dri 2006	FBA6566R Purchase Date SINGAPORE Registration Date * 224454 Age of Vehicle Driver Details CATEGORY	FBA6566R Purchase Date DD/MM/YYYY Registration Date * 07/07/2006 Age of Vehicle 14 Driver Details CATEGORY FNOL INFORMATION

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	TPVD HONDA	HONDA	Date of Birth	28 October 1993	DD/MM/YYYY
Model	CB400	CB400	Age	27	
Туре		•	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		JH2NC39996M200125	Driving Experience	0	
Engine No		NC23E3100140	Driver License #		
Engine Capacity		399	License Type		•
Sum Insured		0	License Issue Date		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	Singapore	
Address type	Personal Correspondence	~
Gender	Unknown	~
Marital status	Unknown	~
Identification #	SXXXXX309D	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summary			
Detailed Assessment		Co	ndition of Vehicle	e at time of surve	∍y	
Inspection Date *	09/03/2021		neral condition	Good		~
Total Loss	Yes No	Ste	ering (Serviceable)	Yes	No	
Towing Charges	0		otbrake rviceable)	Yes	No	
Voluntary Excess	0		ndbrake rviceable)	Yes	No	
Compulsory Excess	0	Eng	gine Modification	Yes	No	
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	-accident condition	Good		~

Other Excess	0

Tyre Condition

Age of Tyres	
Front Tyre Size	120/60R17
Front left side	PIRELLI4mm
Front right side	
Spare wheel	
Rear Tyre Size	160/60R17
Rear left side	PIRELLI4mm
Rear right side	

Messages

Claims



General & Workshop D	etails	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous			
					Summary				
Tax Eligibility & Addit	ional [Deduction for Parts							
Depr./Bttr%	0		Sa	vage%	0	0			
Discount%	10		Set	tlement%	100	100			
			Paint l	.abour/Material F	Ratio				
Paint Labour Ratio	20		Ca	sh Loss	Yes	No			
Paint Material Ratio	80		Pal	t Supplied by AXA	Yes	No			
						Save			

Messages

Claims



Add		Approve	Deny	Submit	All							
EDIT	SR NO	QUAN MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1	HANDLE BAR	Bent	0	130	No	0	10	0	0	117
	0	1	CLUTCH LEVER	Cut	0	68	No	0	10	0	0	61.2
	0	1	BALANCER	Missing	0	30	No	0	10	0	0	27
	0	1	MIRROR	Cut	0	55	No	0	10	0	0	49.5
	0	1	CRASH BAR	Cut	0	120	No	0	10	0	0	108
	0	1	GEAR PEDAL	Cut	0	68	No	0	10	0	0	61.2
	0	1	FRONT FOOTREST LH	Bent	0	35	No	0	10	0	0	31.5
	0	1	REAR FOOTREST LH	Cut	0	25	No	0	10	0	0	22.5

1 1	REAR FOOTREST BRACKET LH REAR SHOCK LH	Bent Bent	0	145	No	0	10	0	0	130.5
		Bent	0	480	No	0	10	0	0	432
1										
±	EXHAUST	Dented	0	1600	No	0	10	0	0	1440
1	FRONT MUDGUARD	Cracked	0	140	No	0	10	0	0	126
1	GEAR SOCK	Cut	0	10	No	0	10	0	0	9
Approve	Deny	Submit Al	ll							
	1 Approve	1 MUDGUARD 1 GEAR SOCK Approve Deny	1 MUDGUARD Cracked 1 GEAR SOCK Cut Approve Deny Submit Al	1 MUDGUARD Cracked 0 1 GEAR SOCK Cut 0 Approve Deny Submit All	1 MUDGUARD Cracked 0 140 1 GEAR SOCK Cut 0 10 Approve Deny Submit All	1 MUDGUARD Cracked 0 140 No 1 GEAR SOCK Cut 0 10 No Approve Deny Submit All	1 MUDGUARD Cracked 0 140 No 0 1 GEAR SOCK Cut 0 10 No 0 Approve Deny Submit All	1 MUDGUARD Cracked 0 140 No 0 10 1 GEAR SOCK Cut 0 10 No 0 10 Approve Deny Submit All	1 MUDGUARD Cracked 0 140 No 0 10 0 1 GEAR SOCK Cut 0 10 No 0 10 0 Approve Deny Submit All	1 MUDGUARD Cracked 0 140 No 0 10 0 0 1 GEAR SOCK Cut 0 10 No 0 10 0 0 Approve Deny Submit All

Add	Approve	Deny	Submit All						
FDIT	SR REPAIR/REPLACE NO (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0	FUEL TANK REPAINT	0	0	0	0	Deny		
	0	TAIL COVER REPAINT	0	100	0	0	Reviewing		
	0	LABOUR	0	200	0	0	Reviewing		



Messages

Claims



Assessment Details

General & Workshop Details Vehicle Condition Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary Add Submit All Approve Deny SR **ESTIMATED** ADJUSTED EDIT NAME COMMENT ACTION REMOVE NO AMOUNT AMOUNT

0

OF

REPAIR Reviewing 0

2

DAYS

DAYS





Messages

Claims



Assessment Details

General & Worksho	p Details Vehicle & Driver	Details Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary					
Estimated Claim Amount	\$0.00	A	djusted Claim Amoun	t \$2,915.40	
CATEGORY	ESTIMATE	ADJUSTED			
Spare Parts	\$0.00	\$2,615.40			
Labour	\$0.00	\$300.00			

Submit for Review



Messages

Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



Assessment Details

General & Workshop	o Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Ac	djusted Claim Amount	\$2,300.00	
CATEGORY		ESTIMATE	ADJUSTED			
Miscellaneous		\$0.00	\$2,300.00			

Submit for Review