

ASS. REC. BY:

REF: CS3/ASM21003086/Gtf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): TAN WAN CONG of AXA Date/Time: 9/3/2021 10:58 AM

Estimated Cost: Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 6892R Insured: SKT 2878K

at Workshop m/s MJE Motor Tel: 6454-2203

of Block 7 Sin Ming Industrial Estate Sector C #01-94 S(575642)

Policy No: Claim No: S1M034PH

Sum Insured: Excess:

Make of Veh: D.O.A. 05-03-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 09-03-2021 11.35A.M

Person Contacted: JOYCE Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SMK 6892R- X
	SKT 2878K - X