

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
 at Workshop m/s canfat layang


of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

GIA / PR Seen: _____

Est. Repairs: _____

Lum Sum: _____

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No SHD 404/P or Regn 3 Dec 2017
 Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai

Colour: Blue

Sp Reading: 368354

Eng/No: _____

C/No: KM1CB41UMN14098882

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 09-03-21

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format

Emp. Sign / Date

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp. (\$



Other (\$

Survey Fee:

Transportation:

3 + RS. \$

Photos

Other

Page 1

COMFORTDEL GRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.03.2021

Time: 17:25:17

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305457208
 REGN NO : SHD4041P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.12.2017
 DATE/TIME IN : 08.03.2021 10:15
 ACCIDENT DATE : 05.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0577-G	PANEL ASSY-TRUNK LID#	1 L	2,174.90	20.00	1,739.92	/ Buc
0002	04-01-0103-0786-G	EMBLEM-CRDI	1 L	52.40	20.00	41.92	/
0003	04-01-0103-0787-G	EMBLEM-I40	1 L	67.90	20.00	54.32	/
0004	04-01-0103-0800-G	SYMBOL MARK-TRUNK LID	1 L	63.10	20.00	50.48	/ abc.
0005	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.00-	30.00	/
0006	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	0.20	30.00	/
0007	04-01-0103-0584-G	LAMP ASSY-RR COMB I/S LH(	1 L	1,131.20	20.00	904.96	/ SR
0008	04-01-0103-0583-G	LAMP ASSY-RR COMB I/S RH(	1 L	1,131.20	20.00	904.96	/ OA
0009	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1 L	1,106.00	20.00	884.80	X Repair
0010	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ abc
0011	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	/ abc.
0012	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	0.20	135.70	X NN
0013	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1 L	228.00	20.00	182.40	X NN

4642.7

-20%: 3714.16

110

990

4814.16

-20%: 3850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305457208
REGN NO : SHD4041P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 08.03.2021 10:1
ACCIDENT DATE : 05.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 5,027.06

JOB NATURE

0000 L PANEL BEATING
0001 23-502 SPRAYPAINT ON AFFECTED AREA
0002 17-01 CHECK ALL LIGHTING
0003 20-22 REMOVE/REFIX REVERSE SENSOR

600.00

~~550.00~~ 420

550.00 500

50.00

30

80.00 40

SUB-TOTAL : 1,280.00

TOTAL : 6,307.06

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

3 Days
L/S
After repair photos.
Gua Qian
09/3/21

