

ASS. REC. BY:

REF: CS3/CTI21003108/T1vf3

Special Instruction:

Surveyor: TAUFIKH ASSIGNMENT (Office)

From (Person): ADELINE CHNG of CTI Date/Time: 9/3/2021 2:29 PM

Estimated Cost: _____ Bill to: _____

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFB 8998L Insured: SJW 233E

at Workshop m/s ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD Tel: 9176 5733

of 15 KAKI BUKIT ROAD 4 BARTLEY BIZ CENTER#01-53

Policy No: DMPCSNW00012012100 Claim No: SNM21D201295/C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08-03-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 09-03-21 3.02P.M Person Contacted: ALFIE Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SFB 8998L- CS/MSG16011464/Kvbn2 DOA :16/06/2016
	SJW 233E - X
12/3/21	Submit PRS,repair range \$4,000-\$5,000 (7 days)