



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21003119/Ktf3n2 Date: 05/05/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKX 4536M	Veh. Inspected	SMK 1574S	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009313/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	09/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MNTBBAB17Z0034965	Colour	METALLIC RED	
Odometer	74800 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	8 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2021	Inspection Date	10/03/2021	
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	