

ASS. REC. BY:

REF: AGWKenneth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Yee Auto

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Smk 15745 Yr Regn: 03, 19Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Sylphy c.c. 1598Colour: M. Red A/C: Insured / Std / NI / NASp. Reading: 74800 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MNT BBA178-0034985Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / Rlm orTyre Size: F: 195/80R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 8 mmL/Bal. 6 mmL/Bal. 8 mmD.O.A. 8/3/21D.O.A. 10/3/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. SI

Fares

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: AUTO & GENERAL INSURANCE (SINGAPORE)

190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2111

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 08/03/2021

TP Veh Reg No: SKX4536M

Estimate No: ES2100025

Date: 09 Mar 2021

Policy No:

Veh Reg No: SMK1574S

Make/Model: NISSAN SYLPHY 1.6
CVT

Chassis No: MNTBBAB17Z0034965

Engine No: HR16940669C

Reg. Date: 29/03/2019

Not Authorised
1/1 Imp &
Recovery After Police
Today

Estimate Repair Cost to Vehicle No :SMK1574S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00 X	
2 REVERSE SENSOR	350.00	1 SET	350.00 X	
			410.00	410.00
Spare Parts				
3 REAR ANTENA BUZZER SENSOR	195.00	1 PC	195.00 X	
4 BOOT EMBLEM 'SYLPHY'	88.90	1 PC	88.90 X	
5 BOOT EMBLEM 'LOGO'	88.90	1 PC	88.90 X	
6 BOOT HINGE - LH	131.80	1 PC	131.80 X	
7 BOOT HINGE - RH	131.80	1 PC	131.80 X	
8 BOOT LID TRIMBOARD	325.10	1 PC	325.10 X	
9 BOOT LID TRIMBOARD CLIP	50.00	1 SET	50.00 X	
10 BOOT LOCK	251.40	1 PC	251.40 X	
11 BOOT REFLECTOR LH	318.20	1 PC	318.20	
12 BOOT REFLECTOR RH	318.20	1 PC	318.20 X	
13 REAR BODY PANEL	503.30	1 PC	503.30 ?	
14 REAR BODY PANEL TOP GARNISH	200.76	1 PC	200.76 X	
15 REAR BODY PANEL TOP GARNISH CLIP	24.00	1 PC	24.00 X	
16 REAR BOOT LID	980.15	1 PC	980.15 X	
17 REAR BOOT LID WEATHERSTRIP	265.90	1 PC	265.90 X	
18 REAR BUMPER	955.10	1 PC	955.10	
19 REAR BUMPER BRACKET - LH	131.80	1 PC	131.80 X	
20 REAR BUMPER BRACKET - RH	131.80	1 PC	131.80 X	
21 REAR BUMPER CLIPS	50.00	1 SET	50.00	
22 REAR BUMPER REFLECTOR - LH	78.05	1 PC	78.05	
23 REAR BUMPER REFLECTOR GARNISH	78.05	1 PC	78.05 X	
24 REAR BUMPER SPONGE	382.00	1 PC	382.00 ?	
25 REAR BUMPER SIDE RETAINER - LH	102.50	1 PC	102.50	
26 REAR BUMPER SIDE RETAINER - RH	102.50	1 PC	102.50 X	
27 REAR CHASSIS MEMBER -LH	798.50	1 PC	798.50 X	
28 REAR FENDER - LH	1,189.50	1 PC	1,189.50	
29 REAR FENDER INNER TRIM - LH	369.50	1 PC	369.50 ?	
30 REAR TAIL LAMP CLIP - LH	33.80	1 PC	33.80	
31 REAR TAIL LAMP CLIP - RH	33.80	1 PC	33.80 X	
32 REAR TAILLAMP PANEL - LH	197.90	1 PC	197.90 ?	
33 REAR WINDSCREEN MOULDING	189.10	1 PC	189.10	
34 TAIL LAMP LH	428.25	1 PC	428.25	



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopte ltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : AUTO & GENERAL INSURANCE (SINGAPORE)
 190 CLEMENCEAU AVENUE
 #03-01 SINGAPORE SHOPPING CENTRE
 SINGAPORE 239924
 TEL: 6221 2111
 ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 08/03/2021
 TP Veh Reg No: SKX4536M

Estimate No: ES2100025
 Date: 09 Mar 2021
 Policy No:
 Veh Reg No: SMK1574S
 Make/Model: NISSAN SYLPHY 1.6
 CVT
 Chassis No: MNTBBAB17Z0034965
 Engine No: HR16940669C
 Reg. Date: 29/03/2019

Estimate Repair Cost to Vehicle No :SMK1574S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 TAIL LAMP RH	428.25	1 PC	428.25	X
36 REAR NUMBER PLATE LAMP - LH	85.15	1 PC	85.15	X
37 REAR NUMBER PLATE LAMP - RH	85.15	1 PC	85.15	X
			9,724.11	9,724.11
Labour				
38 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,200.00	1 JOB	2,200.00	7001
39 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,000.00	1 JOB	2,000.00	8001
40 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	160.00	1 JOB	160.00	301
41 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	1201
42 TO REMOVE/REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.	150.00	1 JOB	150.00	1001
43 TO REMOVE/REFIT FUEL TANK TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	X
			4,910.00	4,910.00
			Total	SS 15,044.11
			Add GST @ 7%	1,053.09
			Total Amount Payable	SS 16,097.20

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND NINETY SEVEN AND CENTS TWENTY ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/03/2021 16:34 (SGT)
Date of Accident	08/03/2021 09:00 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE towards Jurong
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK1574S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Lim Tao Liang Kelvin
NRIC No	SXXXX818F
Email Address	lim.kelvin2011@gmail.com
Mobile Phone No	(Phone) +65-94262086
Alternative Phone No	(Home) +65-94262086

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Sylphy
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

INSURANCE COMPANY

Name of Insurance Company	EQ
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCTHQ21-000010
Cover Note Number	-


DRIVER

Name of Driver	Lim Tao Liang Kelvin
NRIC No	SXXXX818F
Date Of Birth	26/01/1971
Occupation	Outdoor

SKETCH PLAN

(A) SMK 1574S (B) SKX 4536M

PIE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/3/2021 at 9:00 am. I was travelling my vehicle (A) SMK 1574S along PIE towards Jurong.

The vehicle in front stop and I also stop. Suddenly, the vehicle (B) SKX 4536M cannot stop in time and hit my vehicle rear portion.

* Kindly email my GIA Report to me and my workshop Yee Auto Pte Ltd yeeautopteltd@gmail.com

[Signature]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: