



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003127/Kvd3e2	
			Date: 05/05/2021	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLM 3239Z
	Policy No.	D20MTPV01008884	Coverage (\$)	0.00
	Claim No.	CMTD2100698/SYH	Excess (\$)	0.00
	Assign From	HWANG SHIANG YI	Assign Date	09/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E 200 (A)	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDD2120482A598779	Colour	METALLIC GREY
	Odometer	180137 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40Z R18	FALKEN	2 mm
	L/H Front Tyre	245/40Z R18	FALKEN	2 mm
	R/H Rear Tyre	265/35Z R18	FALKEN	0.5 mm
	L/H Rear Tyre	265/35Z R18	FALKEN	0.5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/03/2021	Inspection Date	10/03/2021
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		
5a. Remarks				
	A)THE MARKET VALUE IS S\$49,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	