



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                        |                 |                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------|-------------------------------|--|
| INDIA INTERNATIONAL INSURANCE PL<br>64 CECIL STREET<br>#05-02 IOB BUILDING SINGAPORE 049711                                            |                                                                                                        |                 | Ref: CS3/III20014574/Gvf3e2-1 |  |
|                                                                                                                                        |                                                                                                        |                 | Date: 23/04/2021              |  |
|                                                                                                                                        |                                                                                                        |                 | Code: III2                    |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                        |                 |                               |  |
| Insured Veh.                                                                                                                           | SH 9952B                                                                                               | Veh. Inspected  | SLM 3328A                     |  |
| Policy No.                                                                                                                             | MCOM0015                                                                                               | Coverage (\$)   | 0.00                          |  |
| Claim No.                                                                                                                              | MCT20120487/01                                                                                         | Excess (\$)     | 0.00                          |  |
| Assign From                                                                                                                            | CARINE KEK PHER SER                                                                                    | Assign Date     | 09/03/2021                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                        |                 |                               |  |
| Make & Model                                                                                                                           | VOLKSWAGEN GOLF 1.4                                                                                    | c.c             | 1395                          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                 | Year of Reg.    | 2017                          |  |
| Chassis No.                                                                                                                            | WVWZZZAUZHW109889                                                                                      | Colour          | WHITE                         |  |
| Odometer                                                                                                                               | 35308 KM                                                                                               | Steering        | IN ORDER                      |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                               | Modification    | SPORTS RIM                    |  |
| General                                                                                                                                | GOOD                                                                                                   |                 |                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                        |                 |                               |  |
|                                                                                                                                        | Size                                                                                                   | Make            | Balance                       |  |
| R/H Front Tyre                                                                                                                         | 225/35 R19                                                                                             | PIRELLI         | 6 mm                          |  |
| L/H Front Tyre                                                                                                                         | 225/35 R19                                                                                             | PIRELLI         | 6 mm                          |  |
| R/H Rear Tyre                                                                                                                          | 225/35 R19                                                                                             | PIRELLI         | 6 mm                          |  |
| L/H Rear Tyre                                                                                                                          | 225/35 R19                                                                                             | PIRELLI         | 6 mm                          |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                        |                 |                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.<br>DAMAGES SEE DETAILS.                                               |                                                                                                        |                 |                               |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                        |                 |                               |  |
| Accident Date                                                                                                                          | 24/12/2020                                                                                             | Inspection Date | 29/12/2020                    |  |
| Survey held at                                                                                                                         | GLATT AUTO KIT PTE LTD<br>NO. 1 KAKI BUKIT AVENUE 6<br>#01-53 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                 |                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                        |                 |                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                        |                 |                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                                        |                 |                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                        |                 | 10 Working Days               |  |