

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

		FRE-REPAIR INS	PECTION REPOR		
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21003156/T1vf3e2	
	8 SHENTON WAY TOWERSINGAPO		Date	: 17/03/2021	
	ATTN : RICHARD	ANG	Code	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 4525B	Veh. Inspected	SLS 60J	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M034RA	Excess (\$)	0.00	
	Assign From	RICHARD ANG	Assign Date	10/03/2021	
2.		Vehicle Part	iculars & Condition		
	Make & Model	MERCEDES BENZ C200 AMG	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	WDD2050772R441488	Colour	BLUE	
	Odometer	46204 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/35 R19	YOKOHAMA	6 mm	
	L/H Front Tyre	235/35 R19	YOKOHAMA	6 mm	
	R/H Rear Tyre	235/35 R19	YOKOHAMA	6 mm	
	L/H Rear Tyre	235/35 R19	YOKOHAMA	6 mm	
4.	•	Description of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE FRO	ONT PORTION.		
5. General Information					
	Accident Date	08/03/2021	Inspect Date / Time	11/03/2021 (03:18 PM)	
	Survey held at	GARAGE 13 PTE LTD	1		
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks				
	B) THE REPAIR E THE REPAIRER W C) ENCLOSED PL	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000			
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	<u> </u>				

Report Ref No. CS3/ASM21003156/T1vf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser