



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance and vehicle specifications for a KIA CERATO 1.6 A SR SX G335.

Summary table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include LAX0000, Credit, 10/03/2021/ 12:48, QUK, 282 / Kevin Leong, 30266.

Main itemized list table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like 'REPLACE FRT BUMPER', 'PAINT WORK ON FRT BUMPER', 'WHEEL ALIGNMENT', etc. Total amount 2400.00.

Estimate (large stylized watermark text)

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE) Reg No/Reg Date SMM1088T / 30/07/201 Date In/Mileage 10/03/2021/ 0 Chassis No KNAF3416MK5047682 Engine No G4FGKH741997 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	10/03/2021/ 12:48	QUK	282 / Kevin Leong	30266

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH-RADIATOR GRILLE / CRU	1.00	38.00	20.00	30.40
M COVER-FR BUMPER / BR	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER / X	1.00	485.00	20.00	388.00
M LAMP ASSY-FRONT FOG, LH / X	1.00	303.00	20.00	242.40
M LAMP ASSY-SIDE REPEATER, LH / X	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH / ?	1.00	14.00	20.00	11.20
M STIFFNER-FR BPR LWR / X	1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG / ? BR	1.00	22.00	20.00	17.60
M WIRING ASSY-BUMPER EXTENSION / ?	1.00	207.00	20.00	165.60
M ULTRASONIC SENSOR ASSY-P.A.S / X	1.00	163.00	20.00	130.40
M ORNAMENT-KIA NO.115 / X	1.00	32.00	20.00	25.60
M PANEL ASSY-FNDR APRON, LH / X R	1.00	538.00	20.00	430.40
M PNL-FENDER APRON UPR OTR, LH / X R	1.00	30.00	20.00	24.00
M BRACKET ASSY-FENDER & BPR MTG, / ?	1.00	14.00	20.00	11.20

Estimate

Steve CLKK) 00-NM AL
10/3/21, 2.00pm EXCESS ?
PIP
My R sy
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirm & accepted by: [Signature] (if any item(s) must be resurveyed and is subject to final approval from Insurance Company)

Acknowledged by Repairer
Signature:
Date:

Nett	10,326.40
7% GST on	722.85
Total Payable	11,049.25

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/03/2021 16:27 (SGT)
Date of Accident 06/03/2021 15:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information Yishun Seletar West Link toward Yishun Dam before turning to Yishun Ave 1
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMM1088T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner KEK LIET SHENG JUSTIN (GUO LIESHENG)
NRIC No S8902815I
Email Address justinkek@gmail.com
Mobile Phone No (Phone) +65-93213512
Alternative Phone No +65-96965371

VEHICLE PARTICULARS

Manufacturer Kia
Model Cerato
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only * change to 00
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1900113533
Cover Note Number -

DRIVER

Name of Driver KEK LIET SHENG JUSTIN (GUO LIESHENG)
NRIC No S8902815I
Date Of Birth 10/01/1989

Location
 Type of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

Indoor
 24/09/2009
 11 YEARS AND 6 MONTHS
 Male
 (Phone) +65-93213512
 +65-96965371
 justinkek@gmail.com
 152 CANBERRA DRIVE
 #07-11 SINGAPORE
 -
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Change/cross lane
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 3
 Yes

PASSENGER 1

Name
 Gender

Low Ying Xu
 Female

PASSENGER 2

Name
 Gender

Avery Kek Ting Xi
 Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

07189
 driving along Seletar West Link toward Yishun Dam. I was on the second lane of the road and was preparing to filter left to the lane as I wanted to exit on Yishun Ave 1. In front of me was a commercial lorry GBD9814P who was driving on lane 1. While filter the lorry slowed down and I could not react in time. As a result the left side of my bump collided with the right back corner of the lorry in a slow speed collision. After collision both vehicle drove 2 to 3m forward at the left side of the road. I checked my rear passengers and confirmed they did not suffer any injury from the slow speed collision. I came out of the vehicle and checked on the GBD9814P driver. The lorry driver Arumugam Selvakumar also alighted from his vehicle to check on me. I asked Selvakumar if he was fine from the collision and said yes he is fine. There was no other passenger on Selva's lorry. After confirming there was no personal injury we decided there was no need to call an ambulance and proceed to inspect the vehicle. After taking photos of the accident site I asked Selva if there was damage on his lorry or goods and he said no. This was because the collision occurred on the right back corner of the lorry where there was a slight protruding metal piece that my bumper had caught on. We subsequently took photos to prove that the lorry was fine and goods were intact. At this time a third vehicle stopped and driver Leonard came out. He asked if there was any injury and both Selvakumar and I replied no. After exchange our contacts for future correspondences Leonard offered to drive my rear passengers back while I wait for my vehicle to be towed. After Leonard left Selva drove off shortly to continue delivering his goods.

ATTACHMENT(S)


Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY:

Vehicle Registration Number GBD9814P
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour Goods vehicle
 Vehicle Category -
 Name of Driver (Phone) +65-87373865
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -



CH PLAN



PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KEK LIET SHENG, JUSTIN (GUO LIESHENG)
 Period of Insurance : 30 Jul 2019 To 29 Jul 2021
 Engine No. : G4FGKH741997
 Chassis No. : KNAF3416MK5047682

Vehicle No. : SMM1088T
 Policy No. : 1800113533
 Endorsement No. :
 Issued Date : 14 Aug 2019

ABOUT THE COVER

Make/Model : KIA Cerato
 Engine Capacity/Tonnage : 1,591.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2019
 Insuring with COE/PARF : Yes

* Only the person who is driving on the Policyholder's motor or with his/her permission
 should be included in the Policyholder or any authorised driver only if he/she meets the specified age condition
 and has to pay an additional sum of \$5,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and has less
 than 3 years of driving experience.

Age Condition : All Age Condition
 Limitation as to use* :
 * Limited to social, domestic and pleasure purposes and for the Policyholder's business
 use. The vehicle is not to be used for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods or for other purposes
 which are contrary to public policy or in contravention of Motor Trade
 Loss of Use 160000 - 160000
 * Excesses mentioned hereunder by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 138), Section 85 of the Road Transport Act, 1997 (Malaysia) and Road Transport
 (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0
 Section 2
 Fire - \$0 Own Damage - \$0
 Motor Vehicle - \$100

Uninsured Driver and Excess (where applicable)
 KEK LIET SHENG, JUSTIN (GUO LIESHENG) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 675723 67921000
 Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 209 Pandan Gardens Singapore 608030 65014591
 Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 119931 63270000
 Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 350 Ubi Rd 3 Singapore 400353 67441000
 For more Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6388 6200. Alternatively, you may refer to AIG web at www.aig.com.sg
 or AIG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play

IMPORTANT NOTES

The Purchase Company/Employer's Loan: MayBank
 This policy is issued under the policy to which this Certificate of Insurance refers in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 138), Road
 Transport Act, 1997 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third-Party Risks) Rules, 1969 (Malaysia).

06/08/2019
 0608082 - JAMES
 288 ALEXANDRA ROAD
 SINGAPORE 159300



AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.