

APP. REC. BY:

Steve

CSI AIG 21003160/Evf3

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 1900113533

Claims No. 0783541778SG


Sum Insured: \_\_\_\_\_ Excess: 300

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

BIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Sum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMM 1988T Yr Regn: 30/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato c.c. 1593

Colour: Black A/C: Insured / Std / Nil / N

Sp. Reading: 34239 T/Radio: Insured / Std / Nil / N

Eng/No: \_\_\_\_\_

C/No: KNAE3416MK5147082

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 6/3/21 D.O.I. 10/3/21

Survey held at cycle & carriage

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

F4 LH

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV-74K
27/5/21	Final fig \$9141.20 confirmed by email (Red 2534.40,21%)

Prell. Report Final Report

Days Of Repair: 12

Resurvey No. of Trip: 1

2/6/21-Typist

Add Fee: Site Insp (\$ Interview (\$ Tech. Invs (%) Wheeland (%)

Survey Fee:	
Transportation:	8 + RS 51
Phone:	
Others:	
TOTAL:	

Merimen \$9141.20



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for LCV10710/KEK LIET SHENG, JUSTIN (GUO LIE).

Summary table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include LAX00000, Credit, 10/03/2021/ 12:48, QUK, 282 / Kevin Leong, 30266.

Main itemized list table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like REPLACE FRT BUMPER, PAINT WORK ON FRT BUMPER, etc. Total amount 2400.00.

Estimate (large watermark text)

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a KIA CERATO 1.6 A SR SX G335.

Summary table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include LAX00000, Credit, 10/03/2021/ 12:48, QUK, 282 / Kevin Leong, 30266.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like GARNISH-RADIATOR GRILLE, COVER-FR BUMPER, etc.

Estimate

Handwritten notes: Steve CLKK) 10/3/21, 2.00pm, OO-NM AL EXCESS? P/P My R sy 10 dys

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
Confirm & accepted by:
Acknowledged by Repairer
Signature:
Date:

Summary of costs:
7% GST on 10326.40
Total Payable 11,049.25

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 08/03/2021 16:27 (SGT)  
Date of Accident ..... 06/03/2021 15:30 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... Yishun Seletar West Link toward Yishun Dam before turning to Yishun Ave 1  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMM1088T

INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... KEK LIET SHENG JUSTIN (GUO LIESHENG)  
NRIC No ..... S8902815I  
Email Address ..... justinkek@gmail.com  
Mobile Phone No ..... (Phone) +65-93213512  
Alternative Phone No ..... +65-96965371

## VEHICLE PARTICULARS

Manufacturer ..... Kia  
Model ..... Cerato  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Reporting only \* change to 00  
Vehicle Category ..... Private car

## INSURANCE COMPANY

Name of Insurance Company ..... AIG  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 1900113533  
Cover Note Number ..... -

## DRIVER

Name of Driver ..... KEK LIET SHENG JUSTIN (GUO LIESHENG)  
NRIC No ..... S8902815I  
Date Of Birth ..... 10/01/1989

Location  
 Type of Driving Pass  
 Driving experience  
 Gender  
 Mobile Number  
 Alt. Phone Number  
 Email Address  
 Address  
 Address complement  
 Postcode  
 Is the driver the policyholder?  
 If No, Relationship of the Driver with the Insured  
 Does Driver Own Other Vehicles?  
 Vehicle Registration Number of Other Vehicle Owned by Driver  
 Insurance Company of Other Vehicle Owned by Driver

Indoor  
 24/09/2009  
 11 YEARS AND 6 MONTHS  
 Male  
 (Phone) +65-93213512  
 +65-96965371  
 justinkek@gmail.com  
 152 CANBERRA DRIVE  
 #07-11 SINGAPORE  
 -  
 Yes  
 -  
 No  
 -  
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
 Weather Conditions  
 Road Surface

Collision - Change/cross lane  
 Clear  
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
 Number of vehicles involved in the accident  
 Was anybody injured in the Accident?  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged?  
 Number of Passengers (Including Driver)  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No  
 2  
 No  
 -  
 Yes  
 3  
 Yes

PASSENGER 1

Name  
 Gender

Low Ying Xu  
 Female

PASSENGER 2

Name  
 Gender

Avery Kek Ting Xi  
 Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?  
 Was notice of intended Prosecution given?  
 If yes, against whom?

No  
 No  
 -

CIRCUMSTANCES OF ACCIDENT

07189  
 driving along Seletar West Link toward Yishun Dam. I was on the second lane of the road and was preparing to filter left to the lane as I wanted to exit on Yishun Ave 1. In front of me was a commercial lorry GBD9814P who was driving on lane 1. While filter the lorry slowed down and I could not react in time. As a result the left side of my bump collided with the right back corner of the lorry in a slow speed collision. After collision both vehicle drove 2 to 3m forward at the left side of the road. I checked my rear passengers and confirmed they did not suffer any injury from the slow speed collision. I came out of the vehicle and checked on the GBD9814P driver. The lorry driver Arumugam Selvakumar also alighted from his vehicle to check on me. I asked Selvakumar if he was fine from the collision and said yes he is fine. There was no other passenger on Selva's lorry. After confirming there was no personal injury we decided there was no need to call an ambulance and proceed to inspect the vehicle. After taking photos of the accident site I asked Selva if there was damage on his lorry or goods and he said no. This was because the collision occurred on the right back corner of the lorry where there was a slight protruding metal piece that my bumper had caught on. We subsequently took photos to prove that the lorry was fine and goods were intact. At this time a third vehicle stopped and driver Leonard came out. He asked if there was any injury and both Selvakumar and I replied no. After exchange our contacts for future correspondences Leonard offered to drive my rear passengers back while I wait for my vehicle to be towed. After Leonard left Selva drove off shortly to continue delivering his goods.

ATTACHMENT(S)


Are accident photos available for attachment? ..... Yes  
 Was there any video captured by Car Camera? ..... No  
 Was there any audio recorded? ..... No

**DETAILS OF OTHER VEHICLE PROPERTY:**

Vehicle Registration Number ..... GBD9814P  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... Goods vehicle  
 Vehicle Category ..... -  
 Name of Driver ..... (Phone) +65-87373865  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... -  
 Details of property damaged in accident ..... -  
 No. Of Passenger (Including Driver) ..... -



CH PLAN



PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KEK LIET SHENG, JUSTIN (GUO LIESHENG)  
 Period of Insurance : 30 Jul 2019 To 29 Jul 2021  
 Engine No. : G4FGKH741997  
 Chassis No. : KNAF3416MK5047682

Vehicle No. : SMM1088T  
 Policy No. : 1800113533  
 Endorsement No. :  
 Issued Date : 14 Aug 2019

ABOUT THE COVER

Make/Model : KIA Cerato  
 Engine Capacity/Tonnage : 1,591.00 CC  
 Driver Restriction : NA  
 Person or Classes of Persons Entitled to Drive\* :  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2019  
 Insuring with COE/PARF : Yes

\* Only person who is driving on the Policyholder's motor or with his/her permission  
 should be included in the Policyholder or any authorised driver only if he/she meets the specified age condition  
 and has to pay an additional sum of \$5,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and has less  
 than 1 year of driving experience.

Age Condition : All Age Condition  
 Limitation as to use\* :  
 for social, domestic and pleasure purposes and for the Policyholder's business  
 use, but not for use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods or for other than specified purposes  
 and for any purpose in connection with Motor Trade

Loss of Use 160000 - 160000  
 Excesses mentioned hereunder by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 138), Section 85 of the Road Transport Act, 1997 (Malaysia) and Road Transport  
 Act 2019, are not to be included under these headings.

EXCESS

Section 1  
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0  
 Section 2  
 Fire - \$0 Own Damage - \$0  
 Motor Vehicle - \$0

Named Driver and Excess (where applicable)  
 KEK LIET SHENG, JUSTIN (GUO LIESHENG) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 675723 67921000  
 Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 209 Pandan Gardens Singapore 608030 65014591  
 Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 119931 63270000  
 Approved Reporting Centres/Authorized Service Centres (For accident reporting & windscreen claim only) Add: 350 Ubi Rd 3 Singapore 400353 67441000  
 For more Approved Reporting Centres/AIG Authorized Repairers, please contact our 24-hour accident emergency hotline at +65 6388 6200. Alternatively, you may refer to AIG web-site www.aig.com.sg  
 or AIG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play

IMPORTANT NOTES

The Purchase Company/Employer's Loan: MayBank  
 This policy is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 138), Road Transport Act, 1997 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third-Party Risks) Rules, 1969 (Malaysia).

06/08/2019  
 JAMES  
 288 ALEXANDRA ROAD  
 SINGAPORE 159300



AIG Asia Pacific Insurance Pte. Ltd.  
 AUTHORISED REPRESENTATIVE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.