

ASS. REC. BY:

REF: CS3/CTI21003175/Gvf3

Special Instruction:

Surveyor: GQ ASSIGNMENT (Office)

From (Person): IRENE TAY HUI PING of CTI Date/Time: 10/3/2021 4:35 PM

Estimated Cost: _____ Bill to: _____

OD: WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GY 5288P Insured: YN 9822R

at Workshop m/s MJE Motor Tel: 91056323

of Block 7 Sin Ming Industrial Estate Sector C #01-94 S(575642)

Policy No: DMCVSNW00100042001 Claim No: SNM21D201298/C02/TANKL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06-03-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 10-03-21 4.49P.M Person Contacted: JOYCE Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	YN 9822R - X
	GY 5288P - X
12/3/21	Submit PRS, repair range \$3,000-\$4,000 (4 days)