

Sun Pin
*PRS

CS/41421003190 / Qvd3

Veron


CoE Exp = 27/02/2026

ASSIGNMENT

From _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 2039 R Yr Regn: 28/02/2011
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: BMW 523i 2.5 c.c. 2447

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 155261 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAFP320X0C863825

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R18

R: 245/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 08/03/2021

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 10/03/2021

Survey held at Elite Auto

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Repair dy - 11 days

Date / Time Action / Instruction

MV : 56,000

PV : 22,643

Nett : 33,357

Date/Time. File Pass to?

☐ : Preli. Report

Days Of Repair: 11

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + PS. 31

Fuel:

Other:

Taxi:

12/3/21-Typist

Artid Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Wheel stud (\$

Report Form 4: DAR

Imp. Sum / 1000

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|------------------------|
| Date of Submission | 09/03/2021 14:27 (SGT) |
| Date of Accident | 08/03/2021 18:00 (SGT) |
| Exact Location of Accident | ECP, Singapore |
| Additional Location Information | ECP towards Changi |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SMF2039R |
|-----------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------|----------------------|
| Is company? | No |
| Name Of Registered Owner | Quek Kong Hua |
| NRIC No | SXXXX182C |
| Email Address | quek27@gmail.com |
| Mobile Phone No | (Phone) +65-98753250 |
| Alternative Phone No | +65-98753250 |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | BMW |
| Model | 523i |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |

INSURANCE COMPANY

| | |
|---------------------------|-----------------|
| Name of Insurance Company | Sompo |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | D21MTPV01003265 |
| Cover Note Number | - |

DRIVER

| | |
|----------------|---------------|
| Name of Driver | Quek Kong Hua |
| NRIC No | SXXXX182C |
| Date Of Birth | 27/01/1982 |
| Occupation | Indoor |

| | |
|--|--------------------------------|
| Date Of Driving Pass | 13/10/2016 |
| Driving experience | 4 YEARS AND 5 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-98753250 |
| Alt. Phone Number | +65-98753250 |
| Email Address | quek27@gmail.com |
| Address | 161A Jalan Loyang Besar #01-08 |
| Address complement | - |
| Postcode | 509409 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|-----------------|
| Type of Accident | Chain Collision |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 3 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other material or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | GBJ8750P |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | Ong Wei Peng Kelvin |
| NRIC No | SXXXX508Z |
| Contact Number | (Phone) +65-91130941 |
| Address | - |
| Address complement | - |
| Postcode | - |

| | |
|---|---|
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|---|----------------------|
| Vehicle Registration Number | XD5549X |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | Wei Guosheng |
| Passport No/FIN | GXXXX569R |
| Contact Number | (Phone) +65-98965703 |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | - |

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature

Date & Time:

- 9 MAR 2021

Driver's Signature

(If driver is not the policyholder)

Date & Time:



 Reporting Centre Personnel's Signature

Name:

Jenny Lim

NRIC/FIN No.:

SKETCH PLAN



ECP Towards Changi

Vehicle A: SMF 2039R

B: 4BJ 8750P

C: XD5549X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along ECP Towards Changi on 8/3/21 @ 6:00pm. Suddenly vehicle C (XD5549X) jam brake and I can stopped in time. The vehicle B (4BJ 8750P) came from behind and hit onto rear portion of my vehicle, because the impact my vehicle jerk forward hit onto front vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

- 9 MAR 2021

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Jenny Lim

MOTOR CAR (Fr)

Front Portion

Vehicle No: SMF 2039R

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--|-----|----|-----|
| 1001 | 991886 | Frt Number Plate | SCR | 1 | |
| 1002 | 991887 | Frt Number Plate Base | SCR | 1 | |
| 1003 | 991889 | Frt Number Plate Garnish | | | |
| 1004 | 991300 | Frt Bumper | CRU | 1 | |
| 1005 | 992341 | Frt Bumper Clips | NEC | 1 | |
| 1006 | 991325 | Frt Bumper Bracket | | | |
| 1007 | 991462 | Frt Bumper Side Retainer | BR | 1 | |
| 1008 | 991433 | Frt Bumper Reinforcement | | | |
| 1009 | 991318 | Frt Bumper Beam | | | |
| 1010 | 991468 | Frt Bumper Sponge | CRU | 1 | |
| 1011 | 991427 | Frt Bumper Protector | | | |
| 1012 | 991420 | Frt Bumper Pad | | | |
| 1013 | 991363 | Frt Bumper Grille upper | CRU | 1 | |
| 1014 | 991301 | Frt Bumper Moulding | | | |
| 1015 | 991407 | Frt Bumper Lower Spoiler | | | |
| 1016 | 991438 | Frt Bumper Sensor | | | |
| 1017 | 995100 | Frt LH Bumper Fog Lamp Cover | | | |
| 1018 | 991355 | Frt RH Bumper Fog Lamp Cover | | | |
| 1019 | 995079 | Frt LH Bumper Fog Lamp | | | |
| 1020 | 995080 | Frt RH Bumper Fog Lamp | | | |
| 1021 | 991793 | Frt Grille inner Airguide | CRU | 1 | |
| 1022 | 991328 | Frt Grille Emblem | | | |
| 1023 | 991799 | Frt Grille Chrome Moulding | | | |
| 1024 | 991222 | Frt Apron Panel | | | |
| 1025 | 992013 | Frt Support Panel | BT | 1 | |
| 1026 | 992025 | Frt Support Panel Top Garnish Cover | CRU | 1 | |
| 1027 | 992416 | Horn | | | |
| 1028 | 991277 | Frt Brace Panel | | | |
| 1029 | 995153 | Frt LH Headlamp Assy | | | |
| 1030 | 991821 | Frt RH Headlamp Assy | CRU | 1 | |
| 1031 | 995088 | Frt LH Side Lamp | | | |
| 1032 | 995089 | Frt RH Side Lamp | | | |
| 1033 | 990248 | Bonnet | CRU | 1 | |
| 1034 | 991328 | Bonnet Emblem | | | |
| 1035 | 990287 | Bonnet Lock | Jam | 2 | |
| 1036 | 990285 | Bonnet Insulator | NEC | 1 | |
| 1037 | 990273 | Bonnet Hinge | | | |
| 1038 | 990261 | Bonnet Damper | | | |
| 1039 | 990305 | Bonnet Rubber | NA | 1 | |
| 1040 | 990252 | Bonnet Cable | | | |
| 1041 | 990311 | Bonnet Stand | | | |
| 1042 | 990119 | Air Con Condenser | CRU | 1 | |
| 1043 | 990122 | Air Con Fan Assy | | | |
| 1044 | 990134 | Air Con Suction Pipe (Low Pressure) | | | |
| 1045 | 990118 | Air Con Suction Hose | | | |
| 1046 | 990133 | Air Con Discharge Pipe (High Pressure) | | | |
| 1047 | 990114 | Air Con Discharge Hose | | | |
| 1048 | 990149 | Air Con Liquid Pipe | | | |
| 1049 | 995066 | Air Con Receiver Drier | | | |
| 1050 | 990111 | Air Con Compressor Assy | | | |
| 1051 | 995294 | Air Con Belt | | | |
| 1052 | 995074 | Radiator | CRU | 1 | |
| 1053 | 992738 | Radiator Cowling | CRA | 1 | |
| 1054 | 992742 | Radiator Fan Assy | Def | 1 | |
| 1055 | 992745 | Radiator Fan Clutch | | | |
| 1056 | 992758 | Radiator Hose Top | | | |
| 1057 | 992757 | Radiator Hose Bottom | | | |
| 1058 | 992741 | Radiator Expansion Tank | | | |
| 1059 | 990151 | Air Duct | CRU | 1 | |
| 1060 | 990070 | Air Cleaner Assy | | | |
| 1061 | 990056 | Air Cleaner Hose | | | |
| 1062 | 990089 | Air Cleaner Resonator | | | |
| 1063 | 991712 | Frt Exhaust Manifold | | | |
| 1064 | 991713 | Frt Exhaust Manifold Cover | | | |
| 1065 | 991054 | Frt Exhaust Manifold Sensor (Oxygen) | | | |
| 1066 | 991714 | Front Exhaust Pipe | | | |
| 1067 | 990219 | Battery | | | |
| 1068 | 990224 | Battery Cover | | | |
| 1069 | 990223 | Battery Bracket | | | |
| 1070 | 990229 | Battery Tray | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|------------------------------|-----|----|-----|
| 1071 | 992205 | Fuse Box | | | |
| 1072 | 994011 | Relay Box | | | |
| 1073 | 995053 | Wiper Washer Tank | | | |
| 1074 | 995052 | Wiper Washer Tank Motor | | | |
| 1075 | 990159 | Alternator Assy | | | |
| 1076 | 990160 | Alternator Belt | | | |
| 1077 | 992688 | Power Steering Pump | | | |
| 1078 | 992669 | Power Steering Belt | | | |
| 1079 | 994431 | Power Steering Cooler Pipe | | | |
| 1080 | 992692 | Power Steering Hose | | | |
| 1081 | 990010 | ABS Pump Control Unit | | | |
| 1082 | 990427 | Brake Master Pump Assy | | | |
| 1083 | 990403 | Brake Booster Pump Assy | | | |
| 1084 | 991005 | Engine Top Cover | | | |
| 1085 | 991011 | Engine Under Cover | | | |
| 1086 | 990948 | Engine Mounting | | | |
| 1087 | 990949 | Engine Mounting Frt | | | |
| 1088 | 990950 | Engine Mounting LH | | | |
| 1089 | 990952 | Engine Mounting RH | | | |
| 1090 | 990951 | Engine Mounting Rear | | | |
| 1091 | 992234 | Gear Box Mounting | | | |
| 1092 | 991520 | Frt LH Chassis Member | | | |
| 1093 | 991520 | Frt RH Chassis Member | | | |
| 1094 | 990728 | Frt Vertical Cross Member | | | |
| 1095 | 991863 | Frt Lower Cross Member | | | |
| 1096 | 995070 | Frt LH Fender | | | |
| 1097 | 995072 | Frt LH Fender Inner Panel | | | |
| 1098 | 995147 | Frt LH Fender Lamp | | | |
| 1099 | 995148 | Frt LH Fender Protector | | | |
| 1100 | 991740 | Frt LH Fender Inner Shield | | | |
| 1101 | 995179 | Frt LH Mudflap | | | |
| 1102 | 995170 | Frt LH Wheel Rim | | | |
| 1103 | 994025 | Frt LH Rim Cover | | | |
| 1104 | 995065 | Frt LH Tyre | | | |
| 1105 | 995071 | Frt RH Fender | CRU | 1 | |
| 1106 | 991739 | Frt RH Fender Inner Panel | | | |
| 1107 | 991744 | Frt RH Fender Lamp | | | |
| 1108 | 991752 | Frt RH Fender Protector | | | |
| 1109 | 991740 | Frt RH Fender Inner Shield | | | |
| 1110 | 991884 | Frt RH Mudflap | | | |
| 1111 | 992087 | Frt RH Wheel Rim | | | |
| 1112 | 994025 | Frt RH Rim Cover | | | |
| 1113 | 995065 | Frt RH Tyre | | | |
| 1114 | 992093 | Frt Windscreen Glass | | | |
| 1115 | 992117 | Frt Windscreen Rubber | | | |
| 1116 | 992108 | Frt Windscreen Moulding | | | |
| 1117 | 992098 | Frt Windscreen Sealant | | | |
| 1118 | 991019 | ERP Bracket | | | |
| 1119 | 991020 | ERP Unit | | | |
| 1120 | 992140 | Frt Wiper Arm | | | |
| 1121 | 992142 | Frt Wiper Blade | | | |
| 1122 | 995045 | Wiper Panel Garnish | | | |
| 1123 | 991126 | Firewall Panel | | | |
| 1124 | 990753 | Dashboard Assy | | | |
| 1125 | 992282 | Glove Box Cover | | | |
| 1126 | 992281 | Glove Box Compartment | | | |
| 1127 | 994483 | Steering Wheel Airbag | | | |
| 1128 | 994485 | Steering Wheel Airbag Sensor | | | |
| 1129 | 990749 | Dashboard Airbag | | | |
| 1130 | 990750 | Dashboard Airbag Sensor | | | |
| 1131 | 990029 | Airbag Control Unit | | | |
| 1132 | 990864 | Frt Driver Seat | | | |
| 1133 | 991923 | Frt RH Seat Belt Assy | | | |
| 1134 | 991899 | Frt Passenger Seat | | | |
| 1135 | 995182 | Frt LH Seat Belt Assy | | | |
| 1136 | 990247 | Sticker | | | |
| | | RH Front Headlamp bracket | CRU | 1 | |
| | | RH Front Headlamp stay | BT | 1 | |

No of Items:

23

Attended:

Sam Pn

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(7)Deformed (8)Shifted (9)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (R) (3)Check (C)
(4)Not Consistent (N/C)

Rear Portion

Vehicle No: **SMF 2039R**

| NAC | INC | Item | CON | AC | Qty |
|------|--------|-----------------------------|-------|----|-----|
| 1137 | 993626 | Rear Number Plate | SCR | 1 | |
| 1138 | 993627 | Rear Number Plate Base | SCR | 1 | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | CRU | 1 | |
| 1142 | 993085 | Rear Bumper Upper inner | CRU | 1 | |
| 1143 | 993017 | Rear Bumper Lower inner | CRU | 1 | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | Nec | 1 | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | BR | 2 | |
| 1149 | 993045 | Rear Bumper Reinforcement | BT | 1 | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad undercover | CRU | 1 | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector RH | CRA | 1 | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | short | 1 | |
| 1159 | 993327 | Rear End Panel | DP | 1 | |
| 1160 | 993339 | Rear End Panel Top Garnish | CRU | 1 | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | | | |
| 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | DP | 1 | |
| 1171 | 991328 | Bootlid Emblem | Nec | 1 | |
| 1172 | 990356 | Bootlid Handle | CRA | 1 | |
| 1173 | 995250 | Bootlid Moulding | | | |
| 1174 | 990376 | Bootlid Reflector | CRA | 2 | |
| 1175 | 995222 | Bootlid Lamp LH | | | |
| 1176 | 992899 | Bootlid Lamp RH | | | |
| 1177 | 995243 | Bootlid Lock | Tam | 1 | |
| 1178 | 990377 | Bootlid Rubber | CRU | 1 | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

| NAC | INC | Item | CON | AC | Qty |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | SCR | 1 | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1136 | 990247 | Sticker | | | |

No of Items: 20

Assessor: Sun Pin