

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.03.2021

Time: 08:28:07

Page: 1

Aig Asia

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305457975
REGN NO : SHA4666C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.01.2017
DATE/TIME IN : 10.03.2021 14:40
ACCIDENT DATE : 10.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	de
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	Ry
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	wee
0004 09-01-9999-0068-A	REVERSE SENSOR	1	135.70	2.00	135.70	X No sensor

SUB-TOTAL : 1,220.50

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00	ny
0001 20-05	Rear Bumper Adv.Sticker	50.00	ant
0002 PB	PANEL BEATING	300.00	280
0003 SP	SPRAYPAINT CHARGE	300.00	250
0004 L	R/I REVERSE SENSOR	120.00	X

SUB-TOTAL : 970.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.03.2021

REPAIR ESTIMATE

Time: 08:28:07

Page: 2

Arg Abia

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305457975
REGN NO : SHA4666C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.01.2017
DATE/TIME IN : 10.03.2021 14:40
ACCIDENT DATE : 10.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Lamp

TOTAL : 2,190.50

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanphu 27495749
11/3/21 @ 5pm
02 days
4> Moving after repair
Tanphu @ Tanphu.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:


JC NO.: 305457975

OWNER	REGN NO.: SHA4666C	MILEAGE
AS OWNER NO. 7010045	MAKE: HYUNDAI	FUEL E.....1/2.....F
RESS 383 SIN MING DRIVE Singapore SINGAPORE 575717	MODEL I-40	DATE/TIME IN 10.03.2021 14:40
(R) 65508755 (O)	YR OF MANU. 25.01.2017	TARGET DATE
(P)	CHASSIS CODE KMHLB41UMHU098289	COMPLETION DATE/TIME:
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 10.03.2021
NATURE: 3P 10.03.2021

S/NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Checklist/Check Slip

Exit Pass

No.: **SHA4666C** **LIMITS**

Vehicle No.: **SHA4666C**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard