

LAWRENCE LEE & CO

Advocates & Solicitors

李伟平律师楼

UEN: 53159236K

133 New Bridge Road #13-10
Chinatown Point Singapore 059413
tel: 6533 3680 fax: 6533 3689
email: info@lawrencelee.com.sg

Your ref: (Please advise)
Our ref: LWP/KHM/4644A/21/sm

19 August 2021

This is a letter of claim issued pursuant to
the Non-Injury Motor Accident Practice
Direction of the State Courts

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Gas Building
Singapore 575717

CERTIFICATE OF POSTING

Dear Sirs

ACCIDENT ALONG ANCHORVALE LANE ON 26.02.21 INVOLVING JNF7614 & SHA2204R (OWNER'S CLAIM)

We act for Mr Chan Kuan Tatt, owner of the above vehicle JNF7614.

We are instructed to claim damages against you in connection with the above road traffic accident involving our client's vehicle and vehicle SHA2204R owned by you and driven by your servant/agent one Ow Ah Lon at the material time.

We are instructed that the accident was caused by your servant/agent's negligent driving, management and/or control of your vehicle; for whose actions you are vicariously liable.

As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:

Particulars

1.	Cost of repairs	\$ 3,100.00
2.	Loss of use (11 days x \$50pd)	\$ 550.00

Disbursements

3.	Survey fee	\$ 666.00
4.	LTA fee	\$ 7.49
5.	TP fee	\$ 30.00
6.	Legal costs	\$ 700.00
7.	Miscellaneous	\$ 100.00

A copy of each of the following documents is enclosed with the copy of this letter to your insurer:

1. LTA search with receipt;
2. Our client's certificate of insurance;
3. Our client's rider's TP report with tax invoices;
4. Invoice no. TP/02/21 dated 29.07.21 from Keng Hock Motor; &
5. Survey report with 166 color photographs and invoice no. POS093/21 from Pro-Option Services.

Please note that:

- a. If you are insured and you wish to claim under your insurance policy, you should immediately pass this letter to your insurer.
- b. You or your insurer should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.
- c. If you have any witnesses, photographs of the accident scene, video and GIA/TP reports of the accident, please let us have them within 14 days of your receipt of this letter.
- d. If you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.
- e. In the event that your vehicle had been driven by someone not in the capacity as your servant/agent, please inform us in writing within 14 days otherwise we will name you as a defendant in the Writ that may be issued and you may be liable for legal costs.

Yours faithfully



LEE WEE PENG LAWRENCE
Paralegal: Ms Lim Suk Mei
Email: suknei@lawrencelee.com.sg

Encs by email only

Cc AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
(Insurer of SHA2204R)

POST/EMAIL

Cc Client

Enquire Vehicle Owner Details (As At 26 Feb 2021 / 00:45:00)

Vehicle Owner Details

Owner ID Type:	Owner ID:
Company	199303821R
Owner Name:	Registered Address Type:
COMFORT TRANSPORTATION PTE LTD	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	Registered Street Name:
383	SIN MING DRIVE
Registered Unit No.:	Registered Building Name:
-	GAS BUILDING
Registered Postal Code:	
575717	

Vehicle Insurance Details

Vehicle No.:	Make Description/Model:
SHA2204R	TOYOTA / PRIUS HYBRID 1.8 CVT
Insurance Company Name:	
AXA INSURANCE PTE LTD	

Printed on 18 Mar 2021 15:46:15

Copyright © Land Transport Authority of Singapore 2021



Thank you

Lee Wee Peng Lawrence has successfully logged out.

Your last login date and time was 10 Mar 2021, 17:36:44.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SHA2204R	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	10 Mar 2021 / 17:38:11
2	-	-	-	20.14 Change Password for VRL User Account	-	10 Mar 2021 / 17:37:26



Certificate of Insurance/Sijil Insuran

ORIGINAL

ROD TRANSPORT ACT, 1987 (MALAYSIA) / AKTA PENGALUTAN KENDERAAN 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1952 (MALAYSIA) / PERATURAN PERALUTAN KENDERAAN BERJINJA (RISKO BAGI PIHAK KETIGA) 1952 (MALAYSIA)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 188) (REPUBLIC OF SINGAPORE) / PERALUTAN KENDERAAN BERJINJA (RISKO BAGI PIHAK KETIGA DAN PEMERIKSAAN) AKT (CAP 188) (REPUBLIK SINGAPURA)
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1950 (REPUBLIC OF SINGAPORE) / PERATURAN PERALUTAN KENDERAAN BERJINJA (RISKO BAGI PIHAK KETIGA DAN PEMERIKSAAN) PERATURAN 1950 (REPUBLIK SINGAPURA)
 MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 80) (NEGARA BRUNEI DARUSSALAM) / PERATURAN PERALUTAN KENDERAAN BERJINJA (RISKO BAGI PIHAK KETIGA) PERAKTAN 1950 (NEGARA BRUNEI DARUSSALAM)

CERTIFICATE NO. / NO SIJIL: 017020JEZ000133

C.I Code / Kod Sijil Insuran: M.Y.3

Agent Code: 37965-01-C

Agent Name: CHOO SWEE HWA

1. Registration No. / No. Pendaftaran: JNF7614

Cover Type / Jenis Perlindungan: COMPREHENSIVE

2. Name of Policyholder / Nama Pemegang Polisi: CHAN KUAN TATT

3. Excess/Lebiham: RM100.00 Sum Insured/Jumlah Dilnsuranskan: RM3,000.00

NCB / DTT: 25.00%

4. Hire Purchase / Sewa Beli:

Wef: 29-12-2020

5. Effective Date and Time of Commencement of Insurance for the purpose of the Ordinance / : 29-12-2020 09:45am

Tarikh dan Masa Permulaan Insurance bagi tujuan Ordinan

6. Date and Time of Expiry of the Insurance / Tarikh dan Masa Tamat Insuran: 28-12-2021 12:00am

7. Person or Classes or Persons entitled to drive / :

Orang atau Kelas Orang yang Layak memandu

(a) The Policyholder.

(b) Any other person who is riding on the Policyholder's order or with his permission.

(a) Pemegang Polisi.

(b) Sesiapa yang menunggang di atas arahan Pemegang Polisi atau dengan kebenarannya.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by a Court of Law or by reason of any enactment or Regulations in behalf from driving the Motor Vehicle. / Dengan syarat orang tersebut dibenarkan memandu kenderaan yang ditunggang atau undang-undang lain atau peraturan untuk memandu kenderaan bermotor tersebut atau telah dibenarkan dan tidak disifatkan tidak layak memandu kenderaan bermotor oleh sebab mana-mana enakmen atau peraturan daripada memandu kenderaan bermotor tersebut.

8. Limitation as to use* / Had Penggunaan

Use for social domestic and pleasure purposes and by the Policyholder in connection with his business or profession. The policy does not cover:-

(1) Use for hire or reward.

(2) Use for racing, pacemaking, reliability trial speed-testing.

(3) Use for the carriage of goods (other than samples) in connection with any trade or business.

(4) Use for any purpose in connection with the Motor Trade.

Digunakan untuk tujuan sosial, domestik dan persiaran oleh Pemegang Polisi sendiri berkaitan dengan perniagaan atau pekerjaannya.

Polisi tidak melindungi:-

(1) Kegunaan untuk sewaan atau ganjaran.

(2) Kegunaan untuk mengkadar kelajuan, ujian kebolehpercayaan atau ujian kelajuan.

(3) Kegunaan untuk membawa barangan (selain dari sampel) berkaitan apa-apa pekerjaan atau perniagaan.

(4) Kegunaan untuk apa-apa tujuan yang berkaitan dengan Perdagangan Motor.

* Limitation rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 6 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 188) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Ordinance 1950 (Republic of Singapore) and The Motor Vehicles Insurance (Third Party Risks) Enactment 1950 (State of Brunei Darussalam) are not included under this heading. / Penghadapan di atas tidak berkuat kuasa oleh Seksyen 95 Akta Pengangkutan Jalan 1987 (Malaysia) dan Section 6 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 188) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Ordinance 1950 (Republic of Singapore) dan Insuran Kenderaan Berjinja (Risiko Bagi Pihak Ketiga) Enakmen 1950 (Negara Brunei Darussalam).

I/We hereby certify that the Policy to which the Certificate relates is issued in accordance with the Provisions of Part IV of the Road Transport Act, 1987 (Malaysia), The Motor Vehicles (Third Party Risks and Compensation) Ordinance 1950 (Republic of Singapore) and The Motor Vehicles Insurance (Third Party Risks) Enactment 1950 (State of Brunei Darussalam) and/or in accordance with the provisions of the Motor Vehicles Insurance (Third Party Risks) Ordinance 1950 (Republic of Singapore) and The Motor Vehicles Insurance (Third Party Risks) Enactment 1950 (State of Brunei Darussalam).

You are required to read the Notice in regard to your Personal Data or Sensitive Personal Data. The notice is in Our Website. Please go to www.pacific-orient.com. Anda dikehendaki untuk membaca Notis berkenaan Data Peribadi atau Data Peribadi Sensitif anda. Notis tersebut boleh didapati di Laman Sesawang kami. Sila lawat www.pacific-orient.com.

THIS IS A COMPUTER GENERATED DOCUMENT AND IT DOES NOT REQUIRE SIGNATURE. THIS DOCUMENT SHALL NOT BE INVALIDATED SOLELY ON THE GROUND THAT IT IS NOT SIGNED. / IN ADALAH DOKUMEN YANG DIHUTANGKAN OLEH KOMPUTER DAN TANDATANGAN TIDAK DIPERLUKAKAN. DOKUMEN INI TIDAK HARUS DITAKHLAHKAN SEMATA-MATA ATAS ALASAN IA TIDAK DITANDATANGKAN.

MOTOR POLICY SCHEDULE.....(2 of 2)

3 G01 006



**SINGAPORE
POLICE FORCE**



T/20210307/2049

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20210307/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/03/2021 16:35		Vide Report No.:		Station Diary No.: 46	
Informant's Particulars					
Name of Informant: LEAN SIEW BOON			Address: 15 DUKU ROAD SINGAPORE 429165		
ID Type / ID No.: FIN NO / G2547669M			Contact No.: Home/Office: Mobile: 82875091		
Nationality: MALAYSIAN			Email:		
Sex: Female	Age: 28	Date of Birth: 11/12/1992	Type of Informant: Rider		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Chef			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/02/2021 00:45	Type of Location: T-Junction
Location: ANCHORVALE LANE				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision:			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JNF7614	Motorcycle				Slightly Damaged	0
SHA2204R	taxi					0



**SINGAPORE
POLICE FORCE**



T/20210307/2049

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20210307/2049

CONTINUATION OF REPORT

Brief Details.

On 26/02/2021 at about 0045hrs, I was riding my motorbike with vehicle no. JNF 7614 from Anchorvale Lane towards Hougang. While I was riding my motorbike along the junction and going straight, suddenly there was a Comfortdelgro taxi with vehicle no. SHA 2204R come from the opposite and wanted to turn right into junction. As such, the taxi hit onto the right side of my motorbike which caused me to flunk infront towards the left. I am conscious at that point of time. The taxi driver approached me and asked whether I am okay. I did not managed to get his particulars.

Subsequently, Ambulance and Traffic Police came down to the accident location. Traffic Police advised me to lodge a traffic police accident report after discharged. I suffered from fracture on the left toe and femur shaft and open wound on the heel. Ambulance then conveyed me to Khoo Teck Puat Hospital and was hospitalized for 10 days and was given hospitalization leave for 42 days from 26/02/2021 to 08/04/2021. I am not sure the damages of my motorbike as it is still being towed away.



SINGAPORE
POLICE FORCE



T/20210307/2049

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20210307/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 NUR KHAIRIAH BINTE KHAIRIL ANWAR

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SYED MUHAMMAD BIN SYED
FARID ALBAR

Contact No.: 65476200

Authentication Stamp

NP108

Signature Of Informant:

Date/Time:

07/03/2021 16:35

Classification Of Case:



**SINGAPORE
POLICE FORCE**

PAYMENT

TAX INVOICE

Invoice No : SPF2021031801000460

Date/Time:

18/03/2021 15:57:02

Application Paid Via:

Master

GST Reference No:

MG-8400000-5

Transaction Ref No:

TP000141234

	Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1	Police Document	Document Fee	0050000002386735	16.00	0.00	1	16.00
Total (S\$)							16.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION





**SINGAPORE
POLICE FORCE**

PAYMENT

TAX INVOICE

Invoice No : SPF2021031801000172

Date/Time:

18/03/2021 11:15:36

Application Paid Via:
GST Reference No:

Master
MG-8400000-5

Transaction Ref No:

TP000141234

	Service Type	Service Fee	eService Reference No	Unit Price (S\$)	GST (S\$)	Qty	Amount (S\$)
1	Police Document	Search Fee	0050000002386557	14.00	0.00	1	14.00
Total (S\$)							14.00

This is a computer-generated invoice. No signature is required.

Please print a copy of the invoice for your reference.

A FORCE FOR THE NATION



Keng Hock Motor

188 Yio Chu Kang Road Singapore 545635
TEL: 6 8442855, H/P: 96959080

INVOICE

Chan Kuan Tatt
c/o 188 Yio Chu Kang
Singapore 545635

Invoice No: TP/02/21
Date: 29 July 2021
Vehicle No: JNF7614
Make/Model: Yamaha 135LC ES
Accident Date: 26 February 2021

<u>Sr. No</u>	<u>Description</u>	<u>Amount (\$)</u>
1	Cost of repair for carrying out accident repair to the above mentioned vehicle.	\$3,100.00

Total Amount Payable: \$3,100.00
(Dollars: Three Thousand and One Hundred only)

Keng Hock Motor

Keng Hock Motor
(R.N. 54115837)

188 Yio Chu Kang Road, Singapore 545635
Tel: +65 6844 2855
H/P: +65 9695 9080

Authorized Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Email: mirage1195@gmail.com; Mobile: 9061 0543

Chan Kuan Tatt
c/o 188 Yio Chu Kang Road
Singapore 545635

INVOICE

Invoice no:	POS093/21
Date:	28 July 2021
Report no:	93M0321.KHM
Vehicle :	JNF7614

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Professional charges for the inspection and assessment of the damages sustained by the above accident vehicle, photographs and transport charges.			666.00
SGD(\$): Six Hundred and Sixty-six only			Grand Total:	666.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



Authorised signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Email: mirage1195@gmail.com; Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 93M0321.KHM
Vehicle no : JNF7614

1 REFERENCE

Date of inspection : 25 March 2021
Requested by : Chan Kuan Tatt
c/o 188 Yio Chu Kang Road
Singapore 545635
Type of survey : Independent
Repairer : Keng Hock Motor
188 Yio Chu Kang Road Singapore 545635
Date of accident : 26 February 2021

2 VEHICLE DATA

Make/model : Yamaha 135LC ES
Chassis no : PMYKG0550B0012082
Engine no : G3A1EE012082
Year of manufacture : 2011
Engine capacity : 135 cc
Colour : White
Odometer reading : 65213 km

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : Affected
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>mm/MAKE</u>	<u>SIZE</u>
Front tread	: 5 mm/Maxxis	70/90-17
Rear tread	: 5 mm/Maxxis	80/90-17

5 BRIEF DESCRIPTION OF DAMAGE

Front fender abraded, front LH & RH leg shield scraped/broken, front forks bent, steering stem bent/distorted, rear swing arm bent/distorted, handlebar bent, brake lever abraded/bent, exhaust pipe dented/abraded/bent, front and rear rims scraped, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$3,100.00 (lump suum)
Estimated no of days : Seven (7)

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 93M0321.KHM

Vehicle no: JNF7614

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
Front fender	1	abraded	58.00	58.00
RH front leg shield	1	broken	95.00	95.00
RH air grille	1	broken	40.00	40.00
LH front leg shield	1	cracked	95.00	95.00
Headlamp base panel	1	broken	58.00	58.00
LH side centre cover	1	scraped	55.00	55.00
RH side centre cover	1	broken	55.00	55.00
RH rear side board	1	broken	85.00	85.00
Handlebar	1	bent	55.00	55.00
Handlebar end balancer set	1	abraded	36.00	36.00
Brake lever	1	abraded/bent	18.00	18.00
Mirror set	1	scraped	58.00	58.00
Front fork assy L/R	2	bent/scraped	594.00	594.00
Steering stem	1	bent/distorted	185.00	185.00
Steering con/bearing set – upper	1	necessary	36.00	36.00
Steering con/bearing set - lower	1	necessary	42.00	42.00
Front brake disc	1	bent/distorted	115.00	115.00
Front brake caliper assy	1	abraded	150.00	150.00
Front rim	1	to repair	295.00	SN \$100.00
Front rim axle bolt	1	bent	35.00	35.00
Radiator assy	1	bent/distorted	228.00	228.00
Front frame inner cover (black)	1	cracked	80.00	80.00
Front footrest bar	1	bent/distorted	52.00	52.00
Front footrest assy RH	1	bent	35.00	35.00
Rear suspension swing arm	1	bent/distorted	255.00	255.00
Rear suspension swing arm bush	1	necessary	35.00	35.00
Rear rim	1	to repair	290.00	SN \$100.00
Exhaust pipe assy	1	abraded/dented/bent	280.00	280.00
Exhaust pipe front cover	1	dented/abraded	35.00	35.00
Exhaust pipe protection cover	1	abraded	45.00	45.00
Exhaust pipe end cap	1	abraded	28.00	28.00
Subtotal of the above			3,523.00	2,938.00
Discount 10%			352.30	293.80
<u>(Special nett)</u> Subtotal 1:			3,170.70	2,644.20
Add SN items above			--	200.00
Front sticker number plate set	1	necessary	30.00	30.00
Radiator grille	1	bent/distorted	45.00	45.00
Radiator coolant	1	necessary	15.00	15.00
Rear box	1	dislodged/missing	195.00	195.00
Rear box rack	1	bent	125.00	125.00
Subtotal 2:			410.00	610.00
Total cost of parts:			3,580.70	3,254.20

B LABOUR

Towing fee (2x)	70.00	60.00
-----------------	-------	-------

Report no: 93M0321.KHM
Vehicle no: JNF7614

Labour for dismantle and remove all damaged parts, renew and install new parts. 600.00 500.00

To check wiring. 30.00 20.00

Total cost of labour: 700.00 580.00

Total cost of repair: 4,280.70 3,834.20

7 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is \$3,834.20

(a) The recommended cost of repair based on lump sum repairs would be \$3,100.00

(b) The estimated number of days for the repairs would be Seven (7)
(1st Re-inspection conducted on 28 May 2021)
(Post Repair Inspection conducted on 6 July 2021)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Yours faithfully



.....
Liaw Leong San
Licensed Automotive Appraiser

Dated: 28 July 2021

Report no: 93M0321.KHM

Vehicle no: JNF7614




Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614




Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614




Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614




Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614




Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614




Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614





POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614



POST REPAIR

Report no: 93M0321.KHM

Vehicle no: JNF7614

