

ASS. REC. BY:

REF: CS3/ASM21003272/R1vf3

Special Instruction:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): WINNIE HO of AXA Date/Time: 11/3/2021 4:42 PM

Estimated Cost: Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 5930Y Insured: XE 810T

at Workshop m/s Hock San Motor Works Pte. Ltd. Tel: 63974285

of 7 Soon Lee St #05-08 Ispace S627608.

Policy No: Claim No: S1M034J1

Sum Insured: Excess:

Make of Veh: D.O.A. 03-03-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 12-03-2021 2.34P.M. Person Contacted: LUQI Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (X) Estimate
	XE 5930Y- X
	XE 810T- X
16/3/21	Send IA via Smart Claim (PRS)
16/3/21	Submit PRS, repair range \$3,000-\$4,000 (4 days)