

ASS. REC. BY:

REF: CS3/ASM21003344/Qvf3

Special Instruction:

Surveyor: SUN PIN

ASSIGNMENT (Office)

From (Person): WONG WEE FU of AXA Date/Time: 15/3/2021 11:28 AM

Estimated Cost: Bill to:

OD ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 5619E Insured: SMX 3344H

at Workshop m/s HIAP LEK AUTOMOBULE TRADING Tel: 64531743

of 160 Sin Ming Drive #05-07

Policy No: Claim No: S1M035DA

Sum Insured: Excess:

Make of Veh: D.O.A 12-03-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement:

Date/Time: 15-03-2021 2.57P.M Person Contacted: HAN WEI Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SJP 5619E- ☒
	SMX 3344H - ☒
17/3/21	Send IA (PRS) via Smart Claim
17/3/21	Submit PRS, repair range \$3,000-\$4,000 (5 days)