

ASS. REC. BY: Sun Pin.

REF:

NTUC

NS/INC21003358/T1qd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1124028-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	N/S	<input checked="" type="checkbox"/>	O/S
<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMB1547T Yr Regn: 17/12/2014Type: M.Car / M.Cycle (Bus) Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MAN NL 320F c.c. 10518Colour: Multicolour A/C: Insured / Std / NI / NASp. Reading: 414603 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM1AA22 Z26F7002494Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A / Rim orTyre Size: F: 275/70 R22.5R: 275/70 R22.5BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm / R/Bal. 6 mmL/Bal. 6 mm / L/Bal. 6 mmD.O.A. _____ D.O.I. 12/01/2021Survey held at SMNT.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*Pending Workshop h2A

10/06/21 @ 4.23pm confirmed with Catherine LS \$3850, 3 days. (Red \$1627.90, 30%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 14/06 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: TPLump Sum 1124028-002 3850Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp. (\$ 12.0)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	63685592
Estimator Telephone Number	68662623
Accident Reporting Number	68662672


Date Generated : 12/03/2021

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB1547T
Case Reference Number	BUS/03/21/7006
Registration Date	17/12/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Oh Cheng Chuan
Type of Accident	Side Swipe
Accident Date and Time	9/3/2021 2 24 PM
Accident Reported Date and Time	9/3/2021 4 45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC if any	SMB1547T-left rear portion Unknown lorry-right rear portion
Prepared Date and Time	12/3/2021 9:02 AM
Chassis Number	WMAA22ZZ6F7002494
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$2,323.05	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$4,621.05	\$0.00
Lump Sum Total	\$4,600.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	12/03/2021 9:09 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 12/03/2021

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1,030
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	446
Total Spray Painting & Panel Beating	\$708.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010502	DOOR		GLASS,EXIT DOOR:FOR MAN A22 BUS	1.00	\$510.00	10.00	\$459.00	Replace	/SCR
6010568	DOOR		FRAME,EXIT DOOR:FOR MAN A22 BUS	1.00	\$440.00	10.00	\$396.00	Replace	/BT
6010498	DOOR	GV124M03	RUBBER,EXIT DOOR:FOR MAN A22 BUS	1.00	\$750.00	10.00	\$675.00	Replace	/CRU
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	/NRC
6010173	GLASS	4001X01-GLASS5176	GLASS,SIDE L4,FOR MAN A22 BUS	1.00	\$1,060.90	10.00	\$954.81	Replace	/B H
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	/NRC
4006314			SEALANT SIKAFLEX	7.00	\$37.00	0.00	\$259.00	Replace	/NRC
Total					\$2,957.90		\$2,903.81		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 3 days

L/S
After painting photo

Sim Pini Lkk)
12/03/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB1547T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Mar 2021
Vehicle Make:	MAN
Vehicle Model:	NL 320F (A22) 11L AUTO ABS TURBO
Primary Colour:	Multicolor
Manufacturing Year:	2014
Engine No.:	50338932903902
Chassis No.:	WMAA22ZZ6F7002494
Maximum Power Output:	-
Open Market Value:	\$249,995.00
Original Registration Date:	17 Dec 2014
First Registration Date:	17 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 15 Mar 2021

OK