

ASS. REC. BY: TGlin

REF:

CS/CT121003362/Btf 3Denise**ASSIGNMENT**From: _____ Date: 17/3/2021

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SMX 7934Dat Workshop m/s Dean Auto proof 160 Sun Ming Dr #01-14Insured: GBK 9282LPolicy No. DMCVSNA00016792100Claims No. SNM21D201422

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 128,000/2

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 8 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMX 7934D Yr Regn: 29/1/2021Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Joyota Noah Hybrid C.C. 1797Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 3739 T/Radio: Insured / Std / NI / NAEng/No: ZERO F4889C/No: ZWR80-0440379Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65/15R: 195/65/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/3/2021 D.O.I. 17/3/2021Survey held at Dean Auto proDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range 6000/2 - 7,000/2</u>
	<u>(Red. 1244830 . 65%)</u>
	<u>Recommended COR is 4/5 \$6450/2 TGlin</u>
	<u>MV 128,000/2 13/04/21 - COR renewed. To proceed</u>
	<u>PV 57,259/2</u>
	<u>NV 70,041/2</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 8

1)

☒ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Rep. Format:

Lump Sum / B/L: \$6450/2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	194N
Vehicle Details	
Vehicle No.:	SMX7934D
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2021
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 1.8 X CVT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	2ZR0F45889
Chassis No.:	ZWR800440379
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,394.00
Original Registration Date:	29 Jan 2021
First Registration Date:	29 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$25,152.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2031
PARF Rebate Amount:	\$18,864.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2031
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,889.00
COE Rebate Amount:	\$39,095.00
Total Rebate Amount:	\$57,959.00

The information contained herein is correct as at 09 Apr 2021

OK

MV 128,000/-
PV 57,959/-
NV 70,041/-

TOTAN

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/03/2021 10:47 (SGT)
Date of Accident	12/03/2021 10:35 (SGT)
Exact Location of Accident	Near 235 Bukit Batok East Ave 5, Singapore 650235
Additional Location Information	JUNC OF BUKIT BATOK EAST AVE 3 / BUKIT BATOK ST 21 / BUKIT BATOK EAST AVE 4
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX7934D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Company Reg No	1XXXXX194N
Email Address	rental@skyway.com.sg
Mobile Phone No	(Phone) +65-63336333
Alternative Phone No	+65-63336333

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Noah
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

INSURANCE COMPANY

Name of Insurance Company	MSIG
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	A400000480MCX
Cover Note Number	-

DRIVER

Name of Driver	PANG NGIT KONG JOSEPH
NRIC No	SXXXX279Z
Date Of Birth	15/08/1968

Occupation	Indoor
Date Of Driving Pass	09/07/1993
Driving experience	27 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94876773
Alt. Phone Number	-
Email Address	josephpangnk@outlook.com
Address	BLK 466 SEGAR ROAD #08-174
Address complement	-
Postcode	670466
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	MR
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Clementi Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008729999
Alt. Police Station Phone No	(Fax) +65-68728039
Police Station Address	No. Singapore 129858
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK9282L
Vehicle Manufacturer	Toyota
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MUHAMMAD ARHAM BIN MOHAMED SAHLAN
NRIC No	SXXXX735I
Contact Number	(Phone) +65-91254049
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

BUKIT BATOK
EAST WAVE II

BUKIT BATOK
ST 21



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police Report. (Report No: T/20210312/2068)

The car front bumper got scratches and
side
left mirror has cracked

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SJE :	_____	Vehicle Nos :	SMX 7934 D
Date of Survey :	_____	Model :	Toyota Noah
Date of ReSurvey:	After-Paint:	Year :	_____
Contacts :	_____	Chassis No :	_____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ **Working Day:** _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,258.00	\$ 1,258.00	DD✓
2	Tailgate emblem 'HYBRID'	1	\$ 87.90	\$ 55.00 87.90	NECV
3	Tailgate outer chrome garnish	1	\$ 598.00	\$ 315.25 598.00	CUTV
4	Tailgate inner lock	1	\$ 380.00	\$ 366.70 380.00	JMV
5	Tailgate inner lock sticker	1	\$ 45.00	\$ 45.00	NDX
6	Tailgate inner trim board	1	\$ 492.50	\$ 492.50	NDX
7	Tailgate inner handle	1	\$ 48.00	\$ 48.00	NDX
8	Tailgate weatherstrip	1	\$ 395.00	\$ 299.20 395.00	TNV
9	Tailgate number plate lamp	2	\$ 88.00	\$ 176.00	NDX
10	Tailgate buzzer	1	\$ 165.00	\$ 165.00	NSX
11	Tailgate antenna sensor	1	\$ 180.00	\$ 180.00	NSX
12	Tailgate windscreen moulding	1	\$ 132.00	\$ 36.21 132.00	NECV
13	Rear bumper	1	\$ 840.00	\$ 798.20 840.00	CRAV
14	Rear bumper side retainer	2	\$ 58.00 98.00	\$ 116.00 196.00	NECV
15	Rear bumper bracket	2	\$ 160.00	\$ 320.00	NSX
16	Rear bumper lower bracket	2	\$ 65.20	\$ 130.40	NSX
17	Rear bumper reflector	LH 1 2	\$ 114.00	\$ 68.70 228.00	BRV
18	Rear bumper tow cap	1	\$ 65.00	\$ 28.00 65.00	MIS✓
19	Rear end panel	1	\$ 981.00	\$ 562.40 981.00	DD✓
20	Rear end panel top garnish	1	\$ 278.00	\$ 235.00 278.00	BRV
21	Rear floor panel	1	\$ 892.00	\$ 798.40 892.00	DD✓
22	Rear fender LH	1	\$ 1,200.00	\$ 1,200.00	NDX
23	Rear fender inner trim board	LH 1 2	\$ 525.00 650.00	\$ 525.00 1,300.00	BRV
24	Rear fender side glass moulding LH	1	\$ 650.00	\$ 650.00	NDX
25	Taillamp	2	\$ 781.00 815.60	\$ 1562.00 1,631.20	CUTV
26	Taillamp lower panel	2	\$ 195.00	\$ 390.00	NDX
27	Taillamp lower panel retainer	2	\$ 151.00	\$ 302.00	NDX
Parts Sub Total :				\$ 13,361.00	
Discount 25% :				\$ 2,672.20	
PARTS TOTAL :				\$ 10,688.80	

7024.06
@ 25%
1756.02
5268.05

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 40.00 100.00	} NEC ✓
3	Tailgate outer chrome garnish clips	1	\$ 50.00	\$ 20.00 50.00	
4	Tailgate inner trim board clips	1	\$ 50.00	\$ 30.00 50.00	
5	Tailgate reflector sticker	2	\$ 30.00	\$ 60.00	NSX
6	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00 100.00	} NEC ✓
7	Tailgate windscreen inner seal	1	\$ 80.00	\$ 30.00 80.00	
8	Tailgate windscreen primer & cleaner	1	\$ 60.00	\$ 60.00	NNX
9	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC ✓
10	Rear bumper reflector sticker	2	\$ 30.00	\$ 60.00	NSX
11	Rear end panel sealant	1	\$ 100.00	\$ 30.00 100.00	NEC ✓
12	Rear end panel top garnish clips	1	\$ 50.00	\$ 20.00 50.00	} NEC ✓
13	Rear floor panel sealant	1	\$ 100.00	\$ 30.00 100.00	
14	Rear fender sealant	1	\$ 100.00	\$ 100.00	NNX
15	Rear fender inner trim board clips	LH 1 2	\$ 50.00	\$ 30.00 100.00	NEC ✓
16	Rear fender side glass sealant	1	\$ 100.00	\$ 100.00	NNX
17	Rear fender side glass inner seal	1	\$ 80.00	\$ 80.00	NNX
18	Rear fender side glass primer & cleaner	1	\$ 60.00	\$ 60.00	NNX
19	Taillamp clips	2	\$ 50.00	\$ 20.00 100.00	NEC ✓
20	Taillamp seal	2	\$ 60.00	\$ 120.00	NSX
21	Taillamp lower panel clips	2	\$ 50.00	\$ 100.00	NSX
22	Reverse camera	1	\$ 480.00	\$ 480.00	NDX
23	Reverse sensor	2	\$ 250.00	\$ 200.00 500.00	NEC ✓
SPECIAL NETT TOTAL :				\$ 2,680.00	

520.00

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 80.00 150.00	✓
2	R&R tailgate windscreen	\$ 120.00 250.00	
3	R&R reverse sensor	\$ 60.00 100.00	✓
4	R&R reverse camera	\$ 100.00	
5	R&R rear fender side glass	\$ 250.00	NNX
6	Check wiring	\$ 30.00 100.00	} NNX
7	Upholstery	\$ 300.00	
8	Conduct water leak test	\$ 180.00	
9	Diagnostic reset fault code	\$ 300.00	
10	Panel beating	\$ 1000.00 1,800.00	✓
11	Rust proofing	\$ 30.00 200.00	
12	Spray painting	\$ 1000.00 1,800.00	
LABOUR TOTAL :		\$ 5,530.00	

2320.00

PARTS TOTAL : \$ 10,688.80
SPECIAL NETT TOTAL : \$ 2,680.00
LABOUR TOTAL : \$ 5,530.00
GRAND TOTAL : \$ 18,998.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Survey 17/3/2021 Resurvey 18/3/2021

1030hrs

1015

Tan Min

Tan Min

Lump sum repair
Repair days 8

L/S 6450/2

PARTS 5268.05
S/N 520.00
LABOUR 2320.00
8108.05
1621.61
6486.44

@ 20%