

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003363/AVY3M4**Date:** 26/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00072732003	
Claimant Vehicle No :	FBE9759K	Insured Vehicle No :	GBA5128D	
Date of Loss:	30/01/2021	Nature of Claim:	TP	Claim No: SNM21D200593/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE9759K		Engine No:	4S3304308
Make & Model:	YAMAHA X-1R, 135cc (M)		Chassis No:	4S3304308
Reg. Date:	09/12/2010 (Man. Year: 2010)		Odometer:	30142 km
Colour:	Black			
Engine Capacity:	135 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90R17	Rear Tyre Size:	70/90R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/03/2021	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875
Date Inspected:	16/03/2021 Inspected At:	
Estimated Period of Repair:	0.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value : \$6,000.00

OMV : \$1,964.00

PARF Rebate (1) : \$0

Quota Premium Paid : \$3,670.00

COE Rebate (2) : \$3,471.00

Total Rebate (1) + (2) = : \$3,471.00

The total amount incurred will be Market Value \$6,000.00 minus Total Rebate \$3,471.00 = \$2,529.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 May 2023)	
Parts:	N/A	YAMAHA X-1R 135cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE9759K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >