



Your Ref : SNM21D200593/C02

Date: 26th May 2023

Our Ref : CS/CTI21003363/Avy3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBE 9759K
INSURED VEHICLE: GBA 5128D
ACCIDENT ON 30/01/2021**

Instruction was received to inspect the vehicle Reg. No. FBE 9759K. The inspection was conducted on 16/03/2021 at the premises of M/s Car Auto Pte Ltd, 8 Kaki Bukit Avenue 4 #01-07 Premier @ Kaki Bukit, Singapore 415875.

The following vehicle information was recorded:

Registration Number	: FBE 9759K
Make/Model	: Yamaha X-1R
Year of Registration	: 2010
Body Colour	: Black
Chassis Number	: 4S3304308
Engine Capacity	: 135 cc
Speedometer Reading	: 30142 km

The vehicle sustained damages at the front portion, o/s and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 6,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 3,471.00)
Nett Liability	<u>S\$ 2,529.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.