



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21003374/Uqd3n2 Date: 12/04/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 477R	Veh. Inspected	SML 271S	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009424/ST	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	15/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MNTBBAB17Z0035737	Colour	RED	
Odometer	33302 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	8 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	8 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	8 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/03/2021	Inspection Date	16/03/2021	
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	