

# **ComfortDelGro Engineering Pte Ltd**

59 Loyang Drive Singapore 508969

| Our Ref | 305458925 |  |  |
|---------|-----------|--|--|
|         | 1 -0 -1   |  |  |
| Date    | 160321    |  |  |

Via Fax

GY 3146D

Time of Fax

Your Insured
Date of Acc

160321

Attn: Motor Claims Department

Hig Asia

Dear Sirs

# SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

CS101D

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Lim Kwok Eng
 Jumani Bin Masudin
 Lim Tien Siong
 Chiang Liat Choon
 Tel: 6214 8355 or HP: 9824 0811
 Tel: 6214 8315 or HP: 9635 5305
 Tel: 6214 8398 or HP: 9635 8546
 Tel: 6214 8314 or HP: 9296 6006

limts@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President Taxi Accident Repair

## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE** 

Date: 16.03.2021

Time: 15:17:25 Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

**SINGAPORE SINGAPORE 575717** 

65508755

JOB NO 305458925 REGN NO : SHC8101D MILEAGE MAKE MODEL

: 0000000000 : HYUNDAI

: I-40

DATE OF REGN : 07.08.2014 DATE/TIME IN : 16.03.2021 : 16.03.2021 10:15

ACCIDENT DATE : 16.03.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0103-0573-A FRT FENDER RH 1 663.00 20.00 530.40

0002 04-01-0103-0592-G FRT DOOR RH 1 2,256.40 20.00 1,805.12

0003 04-01-0103-0594-G WING MIRROR RH 1 670.00 20.00 536.00

0004 28-01-0103-0003-A Frt Door ComfortDelGro RH 1 75.00 2-00- 75.00

SUB-TOTAL : 2,946.52

## JOB NATURE

| 0000 PB    | PANEL BEATING-W/Screen Pillar | 400.00  |
|------------|-------------------------------|---------|
| 0001 SP    | SPRAYPAINT-Frt Bumper ETC     | 1200.00 |
| 0002 17-01 | CHECK ALL LIGHTING            | 40.00   |
| 0003 20-00 | TUFF COAT ON AFFECTED PARTS.  | 60.00   |
| 0004 L     | TRANSFER OF DOOR              | 120.00  |

SUB-TOTAL : 1,820.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.03.2021

Time: 15:17:25 Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

**CUSTOMER: 7010045** 

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

**SINGAPORE SINGAPORE 575717** 

65508755

JOB NO REGN NO MILEAGE MAKE

305458925 : SHC8101D : 0000000000 HYUNDAI

MODEL

: I-40

DATE OF REGN DATE/TIME IN

07.08.2014 : 16.03.2021 10:15

ACCIDENT DATE

: 16.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

**AUTHORISED: YES/NO** 

TOTAL : 4,766.52

**MVA NAME & SIGNATURE** 

DATE:

**SURVEYOR NAME & SIGNATURE** 

DATE:

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission 16/03/2021 13:59 (SGT) Date of Accident 16/03/2021 10:20 (SGT)

Exact Location of Accident AYE, Singapore

Additional Location Information TOWARDS LOWER DELTA ROAD

Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SHC8101D

INSURED/POLICYHOLDER

Is company? Yes

Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD

Company Reg No 1XXXXX821R **Email Address** 

fleetsafety@cdgtaxi.com.sg Mobile Phone No (Phone) +65-96211031

Alternative Phone No. (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer Hyundai Model

140 Variant

Exact purpose for which vehicle was being used at time of Private hire

Are you claiming under your own insurance policy for repair to your vehicle?

No - Claiming third party Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company Axa Type of Coverage ThirdPartyFireTheft

Fleet Policy

Policy Number VFX/P2419138 Cover Note Number

DRIVER

Name of Driver **CHUA CHEW SOO** 

Outdoor

NRIC No SXXXX919J Date Of Birth 16/01/1949 Occupation

Accident report SJ04213G0006

**Date Of Driving Pass** 

04/02/1974 Driving experience 47 YEARS AND 1 MONTH

Gender

Mobile Number

Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

PASSENGER 1

Name

Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 16/3/21 AT ABOUT 1020HRS, I WAS DRIVING VEHICLE A (SHC8101D) ALONG AYE TOWARDS LOWER DELTA RD WITH ONE FEMALE PASSENGER. I WAS AT SECOND LANE, WHEN VEHICLE TYRE PUNCTURED (REAR RIGHT) AND I FILTER TO ROAD SHOULDER. I CALLED COMFORT AND COMFORT STAFF ADVISED ME TO CALL EMAS TO TOW TO NEAREST CARPARK. AS I WAS WAITING FOR TOWING, SUDDENLY VEHICLE B (GY3146D) FROM RIGHT HIT ONTO MY VEHICLE RIGHT SIDE MIRROR AND RIGHT FRONT FENDER. UNABLE TO EXCHANGE PARTICULARS. NO INJURY.

(Phone) +65-96211031

0512

Hirer

Side Swipe

Clear

Dry

No

Yes

2

No

UNKNOWN

Female

No

No

2

No

No

fleetsafety@cdgtaxi.com.sg

BLK 715 CLEMENTI WEST STREET 2 #07-99

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes No

Yes

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Accident report SJ04213G0006

GY3146D

Page 2 of 19

| Vehicle Category Name of Driver         | Commercial vehicle |
|---|--------------------|
| ·                                       | •                  |
| Gontact Number                          | 553                |
| Address                                 | 1 <del>7</del> 7   |
| Address complement                      | <b>=</b> 9         |
| Postcode                                | 4                  |
| Insurance Company Name                  | -                  |
| Nature Of Damage                        | 3                  |
| Details of property damaged in accident | 2                  |
| No. Of Passenger (Including Driver)     | 1                  |
|   |                    |

### SKETCH PLAN

# IMPORTANT NOTICE


- t. Rease report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful mistepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my w orkshop and the General haurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and discuse and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the hourers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my daims including the settlemental the claims and any necessary investigations relating to the claims:
- (ii) Investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mains of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering processing, handling and/or dealing with my claims.

(collectively the 'Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GM to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



| Describe Circumstances of           | I the Accident  |
|-------------------------------------|---|
| ON 16/3/21                          | MT ABOUT 1020 HER, I was DRIVING UKHICLEA   |
| (8Hz 81010) ho~                     | S AVE YOURNES LOVER DELTH RO. WITH ONE FEMALE MONTH   |
|                                     | AT SECOND LINE, WHEN VEHICUE TYPE PENTURED AND  |
|                                     |   |
|                                     | SHOULDER. I CHURD CONFORT AND CONFERT STAFF HOUSED  |
| ME TO CALL EMA-                     | s to force tow to heavest cuppark. As I was   |
|                                     | 4, Suspensy VEHICLE & (GY3/46D) FROM LIGHT HIT  |
| anto my Vetticle                    | SIDE MAROR AND LEFT RIGHT FRONT FENDER. WASLE   |
| to EXCHANGE PRATICA                 | ulang. no my  |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
|                                     |   |
| claration                           | 9 · * *   |
| e declare the foregoing particulars | are true in every respect.  |
|                                     | A. co   |
|                                     | CAN W   |
|                                     | Driver's Signature (If driver is not the oplicyholder) / Date & Time  Witnessed by Conting Centre Personnel |
|                                     | 16k/21/1200 Ary brungs  |