

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.03.2021

Time: 15:17:25

Page: 1/2 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305458925
 REGN NO : SHC8101D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 07.08.2014
 DATE/TIME IN : 16.03.2021 10:15
 ACCIDENT DATE : 16.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
1	663.00	20.00	530.40	ht-
1	2,256.40	20.00	1,805.12	Ry
1	670.00	20.00	536.00	bw-
1	75.00		75.00	ny-
SUB-TOTAL :				2,946.52

1333
1066.40
5475

JOB NATURE

0000 PB	PANEL BEATING-W/Screen Pillar	400.00	350
0001 SP	SPRAYPAINT-Frt Bumper ETC	1200.00	800
0002 17-01	CHECK ALL LIGHTING	40.00	30
0003 20-00	TUFF COAT ON AFFECTED PARTS.	60.00	44
0004 L	TRANSFER OF DOOR	120.00	44
SUB-TOTAL :		1,820.00	

2321.40
4541850
2days.#

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: