

ASS. REC. BY:

REF: CS3/ASM21003415/Qqf3

Special Instruction:

Surveyor: SUN PINASSIGNMENT (Office)From (Person): CHEN XIN YOU of AXA Date/Time: 16/3/2021 10:21 AM

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGD 5595M Insured: SKJ 4696Hat Workshop m/s HIAP LEK AUTOMOBULE TRADING Tel: 9660 1347of 176 Sin Ming Drive #02-03 176 Sin Ming Drive #02-03Policy No: _____ Claim No: S1M035A4

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/03/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 16-03-21 11.15A.M Person Contacted: HAN WEI Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SGD 5595M- ☒
	SKJ 4696H - CC3/AIG16001227/Fwb3q2 DOA :19/01/2016