HEF: CS/9m021003418/Trued3. ASSIGNMENT SMG 5853G, Yr Regn: 2015, OU. Veh No: From: Date: **Estimated Cost:** Truck / Trailer or OD ITP I WS I TP RES I OD RES I EVA I INV I MV 40LI To Inspect Vehicle No: Make: Insured / Std / NI / NA A/C: Colour at Workshop m/s T/Radio: Insured / Std / N1 / NA Sp.Reading Eng/No: Insured: 2200 50997 C/No: Policy No. Gen. Cond: Good / Fair / Poor / Burnt Claims No. Steering: Inokder / Jammed / Leaked / Burnt or Excess: Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: Nil (S/Rim / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU(PIR / SUMI / O/S N/S Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO or Rear Front Bal. or Market Value: R/Bal. mm R/Bal. Consistent?: Yes or No IDAC Accident Rport: L/Bal. mm L/Bal. Consistent?: Yes or No GIA / PR Seen: D.O.A. Res.: Yes or No days Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages: Frt & Reat / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN/OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Action / Instruction Date / Time SUBMIT LUMP SUM \$15200, 7DAYS RED: 13609.59: 39% Days Of Repair: Date/Time, File Pass to? : Prell. Report Resurvey No. of Trip: Survey Fee: Final Report Date/Time, File Return to? Transportation: Add Fee: : Site Insp S+RS. SI Interview **Photos** Tech. Irivs 🕸 Repeat Formet: Others Lump Sum / LB.E. C. Weelland (\$

TOTAL



AP AUTOMOTIVE SERVICES PTE LTD ROC: 202022890H BLOCK 9008 TAMPINES STREET 93 #01-202 SINGAPORE 528840 TEL: 6784 4465 FAX: 6787 4886

Estimation

Date

15/3/2021

Vehicle Make/Model SMG 5853G BMW 740i

Chassis No.

WBA7E22000GD99721

No.	Description	Unit	U	nit Price	Ar	mount
	Parts Replacment					
1	REAR BOOTLID	1	\$	2,181.55	5 h6/	2,181.55
2	REAR BOOTLID LOGO	1	\$	71.95	\$ new	71.95
3	REAR BOOTLID CHROME	1	\$	145.20	saf	145.20
4	REAR BOOTLID CHROME GARNISH	1	\$	233.45	\$ de	233.45
5	REAR BOOTLID CHROME GARNISH NUMBER PLATE LAMP	SET	\$	54.45	\$ K	108.90
6	REAR BOOTLID CHROME GARNISH OPENER	1	3.1		\$ K	
7	REAR BOOTLID CHROME GARNISH REAR CAMERA	1	\$	725.60	\$ 🗶	725.60
8	REAR BOOTLID INNER TRIM	1	\$	134.70	\$ 1	134.70
9	REAR BOOTLID EMBLEM '740i	1	\$	64.75	\$ na-	64.75
10	REAR BOOTLID LAMP L+R	2	\$	565.85	\$ cma	1,131.70
11	REAR BOOTLID WEATHERSTRIP	1	\$	129.35	\$ int	129.35
12	REAR TAILLAMP L+R	2	\$	808.40	\$ LH-00-	KHX1,616.80
13	REAR TAILLAMP CLIPS L+R	2	\$	23.00	\$ LHNU	R4X 46.00
14	REAR BUMPER	12	\$	1,755.35	\$de/	3,510.70
15	REAR BUMPER RETAINER L+R	2	\$	162.25	\$ <	324.50
16	REAR BUMPER REFLECTOR L+R	2	\$	39.05	\$ 04-	78.10
	REAR BUMPER REVERSE SENSOR	4	\$	251.40	\$ dis/	1,005.60
	REAR BUMPER SIDE CHROME L+R	2	\$	43.75	sut	87.50
	REAR BUMPER LOWER CHROME	1	\$	40.75	\$ and/	40.75
20	REAR BUMPER LOWER CHROME L+R	2	\$	86.75	\$ 66	173.50
	REAR BUMPER EXHAUST CHROME TIP L+R	2	\$	248.80	\$ bt	497.60
	REAR BUMPER REINFORCEMENT BAR	1	\$	976.10	sht	976.10
	REAR BUMPER SPONGE	1	\$	82.60	\$ ×	82.60
	REAR BUMPER CENTER BRACKET	1	\$	67.80	\$ 04/	67.80
	REAR KICK SENSOR	1	\$	51.20	5 Mu	51.20
	REAR OPENER SENSOR	1	\$	46.55	s dis-	46.55
	REAR FENDER L+R	2	†	REPAIR		REPAIR
	REAR FENDER INNER TRIM L+R	2	\$	352.25	+	704.50
	REAR FENDER COWLING L+R	2	5	181.80		363.60
	END PANEL	1	\$	1,763.20	1 / 2	1,763.20
	END PANEL TOP GARNISH	1	\$	113.00	1 1	113.00
	SPARE WHEEL PANEL	1	\$	352.25	+	
	SPARE WHEEL PANEL TOP BOARD	1	\$	704.45		352.25
	REAR EXHAUST PIPE		\$		+	704.45
	REAR EXHAUST HEAT SHIELD	$\frac{1}{1}$	+	2,537.70	7	2,537.70
	REAR EXHAUST GASKET	$\frac{1}{1}$	\$	80.35		80.35
	FRONT SEATBELT L+R	1	+	1.000.00	\$ 7	
	I HOW SEATBLET LAK	2	\$	1,029.65	\$ act	2,059.30

38 GRONT HEADING				
38 FRONT HEADREST L+R - Ph- 10.	2	\$ 940.85	\$ aut	1,881.70
	Ĭ			
		Total	\$	24,092.50
		Less 5%	\$	1,204.63
		Total	\$	21,683.25

DEAD DOOR OF THE STATE OF THE S				1		
REAR BOOTLID INNER TRIM CLIPS	SET	\$	120.00	\$	×	120.00
REAR BUMPER CLIPS	SET	\$	120.00	\$	30na -	120.00
REAR END PANEL SEALANT	1	\$	120.00	\$	5 Ones	120.00
REAR END PANEL TOP GARNISH CLIPS	SET	\$	120.00	\$	1000	120.00
REAR FENDER INNER TRIM CLIPS	SET	\$	120.00	\$	X	120.00
REAR FENDER COWLING CLIPS	SET	\$	120.00	\$	K	120.00
				2		
			Fadal	<u> </u>		720.00
-	REAR END PANEL SEALANT REAR END PANEL TOP GARNISH CLIPS REAR FENDER INNER TRIM CLIPS	REAR END PANEL SEALANT REAR END PANEL TOP GARNISH CLIPS REAR FENDER INNER TRIM CLIPS SET	REAR END PANEL SEALANT 1 \$ REAR END PANEL TOP GARNISH CLIPS SET \$ REAR FENDER INNER TRIM CLIPS SET \$ REAR FENDER COWLING CLIPS SET \$	REAR END PANEL SEALANT 1 \$ 120.00 REAR END PANEL TOP GARNISH CLIPS SET \$ 120.00 REAR FENDER INNER TRIM CLIPS SET \$ 120.00	REAR END PANEL SEALANT 1 \$ 120.00 \$ REAR END PANEL TOP GARNISH CLIPS SET \$ 120.00 \$ REAR FENDER INNER TRIM CLIPS SET \$ 120.00 \$ REAR FENDER COWLING CLIPS SET \$ 120.00 \$	REAR END PANEL SEALANT 1 \$ 120.00 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$

PANEL BEATING ON AFFECTED AREAS						
	1	\$	1,200.00	Ś	700.	1,200.00
PRAY PAINT ON AFFECTED AREAS	1	\$	1,200.00	Ś	700	1,200.00
O RNR REAR EXHAUST	1	<u> </u>		5		2 hope 400.00
O CHECK WIRING AND BOOTLID LAMP FUNCTION	1	Ś		<u> </u>		120.00
O CHECK WIRING AND TAIL LAMP FUNCTION	1	\$	120.00	Ś.	3/0	120.00
O RNR REAR INNER TRIM AND UPHOISTERY	1	\$	400.00	Ś	60.	400.00
O RNR REAR KICK SENSOR AND TEST FUNCTION	1		250.00	Ś	60	250.00
O CHECK WATER LEAK	1					120.00
O PERFORM DIAGNOSTIC AND CLEAR FAULTS	1					1,200.00
O RNR REAR BOOTLID MECHANISM	1					
O PNR REAR REVERSE SENSOR AND CHECK FUNCTION	1			<u> </u>		200.00
O PERFORM RUST PROOFING	1					250.00
O RNR REAR HEADREST AND TEST FUNCTION	1			<u> </u>		120.00
	 	<u> </u>	300.00	٠,	7 00.	500.00
					40	
					\$1 	
					ď.	
	O CHECK WIRING AND BOOTLID LAMP FUNCTION O CHECK WIRING AND TAIL LAMP FUNCTION O RNR REAR INNER TRIM AND UPHOISTERY O RNR REAR KICK SENSOR AND TEST FUNCTION O CHECK WATER LEAK O PERFORM DIAGNOSTIC AND CLEAR FAULTS O RNR REAR BOOTLID MECHANISM O PERFORM RUST PROOFING	O CHECK WIRING AND BOOTLID LAMP FUNCTION O CHECK WIRING AND TAIL LAMP FUNCTION O RNR REAR INNER TRIM AND UPHOISTERY O RNR REAR KICK SENSOR AND TEST FUNCTION C CHECK WATER LEAK O PERFORM DIAGNOSTIC AND CLEAR FAULTS O RNR REAR BOOTLID MECHANISM O PERF REAR REVERSE SENSOR AND CHECK FUNCTION 1 O PERFORM RUST PROOFING 1	O CHECK WIRING AND BOOTLID LAMP FUNCTION 1 \$ O CHECK WIRING AND TAIL LAMP FUNCTION 1 \$ O RNR REAR INNER TRIM AND UPHOISTERY 1 \$ O RNR REAR KICK SENSOR AND TEST FUNCTION 1 \$ O CHECK WATER LEAK 1 \$ O PERFORM DIAGNOSTIC AND CLEAR FAULTS 2 RNR REAR BOOTLID MECHANISM 1 \$ O PERFORM REAR REVERSE SENSOR AND CHECK FUNCTION 1 \$ O PERFORM RUST PROOFING 1 \$	O CHECK WIRING AND BOOTLID LAMP FUNCTION O CHECK WIRING AND TAIL LAMP FUNCTION O RNR REAR INNER TRIM AND UPHOISTERY O RNR REAR KICK SENSOR AND TEST FUNCTION O CHECK WATER LEAK O PERFORM DIAGNOSTIC AND CLEAR FAULTS O RNR REAR BOOTLID MECHANISM O PRIN REAR REVERSE SENSOR AND CHECK FUNCTION O PRIN REAR REVERSE SENSOR AND CHECK FUNCTION O PERFORM RUST PROOFING O PERFORM RUST PROOFING	O CHECK WIRING AND BOOTLID LAMP FUNCTION O CHECK WIRING AND TAIL LAMP FUNCTION O RNR REAR INNER TRIM AND UPHOISTERY O RNR REAR KICK SENSOR AND TEST FUNCTION O RNR REAR KICK SENSOR AND TEST FUNCTION O CHECK WATER LEAK O PERFORM DIAGNOSTIC AND CLEAR FAULTS O RNR REAR BOOTLID MECHANISM O RNR REAR BOOTLID MECHANISM O PERFORM RUST PROOFING O PERFORM RUST PROOFING O RNR REAR BOOTLID TEST SUNCTION O PERFORM RUST PROOFING O PERFORM RUST PROOFING O RNR REAR BOOTLID SECTIONS TO	O CHECK WIRING AND BOOTLID LAMP FUNCTION O CHECK WIRING AND TAIL LAMP FUNCTION O RNR REAR INNER TRIM AND UPHOISTERY O RNR REAR KICK SENSOR AND TEST FUNCTION O CHECK WATER LEAK O PERFORM DIAGNOSTIC AND CLEAR FAULTS ORNR REAR BOOTLID MECHANISM O PRIN REAR REVERSE SENSOR AND CHECK FUNCTION O PERFORM RUST PROOFING O PERFORM RUST PROOFING O RNR REAR HEADREST AND TEST FUNCTION O RNR REAR HEADREST AND TEST FUNCTION

Parts Replacement Amount \$ 6,080.00 \$ 22,403.25

Total Amount \$ 28,483.25

Tanfor 97475749

WI 18/3/218 Spn

U/5 Rosyn offen nepal

fourfline (Ishantorcon.

6- Faleys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part s) during resurvey
- Parts prices are intrect to agrif motion.
- Third part, survey and Warn to ejudice" basis
- No illegal miditation since Aid
- Supplementation outsition resultance d and is subject to the company

Acknowled Acknowler Signature:

Date:

4

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

384Z

Vehicle Details

Vehicle No.:

SMG5853G

Vehicle to be Exported:

No

Intended Deregistration Date:

30 Mar 2021

Vehicle Make:

B.M.W.

Vehicle Model:

740LISR LED NAV HUD

Primary Colour:

Grey

Manufacturing Year:

2015

Engine No.:

22879348B58B30A

Chassis No.:

WBA7E22000GD99721 240.0 kW (321 bhp)

Maximum Power Output: Open Market Value:

\$84,493.00

Original Registration Date:

28 Oct 2015

First Registration Date:

28 Oct 2015

Transfer Count:

2

Actual ARF Paid:

\$124,088.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Oct 2025

PARF Rebate Amount:

\$86,861.00

Intended COE Rebate Details

COE Expiry Date:

27 Oct 2025

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$59,889.00

COE Rebate Amount:

\$27,384.00

Total Rebate Amount:

\$114,245.00

The information contained herein is correct as at 15 Mar 2021



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any withil misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

15/03/2021 19:04 (SGT) 13/03/2021 18:30 (SGT) Penjuru Rd, Singapore BEFORE PENJURU FLYOVER Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMG5853G

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No TAN CHEE KONG SXXXX384Z davetan9869@gmail.com (Phone) +65-93808373 +65-93808373

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purposes for which vehicle was being used at time of account.

Fig. vol. distring under your own insurance policy for repair to year to the leaf

BMW 740li

Private use

No - Claiming third party Private car

MCCACHE, JAHANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

China Taiping Insurance Comprehensive No DMPCSNW00152562000

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

TAN CHEE KONG SXXXX384Z 20/10/1981 Outdoor Date Of Driving Pass Driving experience Gender Mobile Number

Alt, Phone Number **Email Address**

Address

Address complement

Postcode

Is the driver the policyholder?

If No. Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Was the accident reported to the police?

Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

20/04/2005

15 YEARS AND 11 MONTHS

Male

(Phone) +65-93808373

+65-93808373

davetan9869@gmail.com

BLK 742 YISHUN AVENUE 5 #10-450

760742

Yes

No

Collision - Head to Rear

Clear Dry

No

2

Yes No

Yes

No

DETAILS OF POLICE ACTION

Police Station Name Police Station Phone No Alt. Police Station Phone No

Yes

Clementi Division Headquarters (Phone) +65-18007740000 (Fax) +65-67741705

20 Clementi Avenue 5 Singapore 129858

No

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT D/20210314/7030

A. Tachilde L. (C)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

EDETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Was there any audio recorded?

Vehicle Manufacturer Vehicle Model Vehicle Variant

Vehicle Colour Vehicle Category

Name of Driver Contact Number XE5410G

Commercial vehicle



Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Yes Was this injured conveyed to hospital by ambulance?

TAN CHEE KONG

BACK AND NECK PAIN SMG5853G

No

9

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any willul misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Formby insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GA Records Management Centre established by the General Insurance Association of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims,
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (w) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes

Policy holder's Signature / Date & Driver's Signature (8 driver is not the policyholder) / Date

With A: Sm G 5853G

Veh A: Sm G 5853G

Veh S: XB 5410 G

•	On	the	state	d date	and	time		ven.c	ce l	wa
			on the							
			ehad					•		
port	ion	. The	impact	wal	30 9	reot	41/0-4	my	ye!	hicle
carl	y 100-	st	art at	all a	ut ter	the				

Poli	ily 1	CHAR	וכיוכלע ד	03/4/7	030	***************************************				
							1			
	~~~~									
							1			
							/			
						/	<i>,</i>			
			*****			/	5/			
						/				
						_/				
				The State of the S		<u>/</u>				denoted the second
				-	/					
					_/_					
					<del>/</del>				····	
					/					
									Anna Carrie Marie Carrier	
				_/						
				7						

#### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature 7 Date & Time

Driver's Signature (# driver is not the poticyholder) / Date & Time

Witnessed by Reporting Centre Personnel



## 0/20210314//030

1 of 1

Report No. D/20210314/7030

### **POLICE REPORT (NP299)**

Police Station Of Origin Clementi Division HQ 20 Clementi Avenue 5 SINGAPORE 129858 Tel No:1800-7740000

Date/Time Report Made	Vide Re	Vide Report No.				
14/03/2021 22 48	5					
Name Of Informant	Address					
TAN CHEE KONG	742 YIS	HUN AVEN	UE 5 #10-450 SIN	<b>IGAPORE 760742</b>		
ID Type / ID No. NRIC NO / S8155384Z	Contact No. Home/Office:		Mobile: 93808373			
Nationality MALAYSIAN	Email Address DAVETAN9869@GMAIL.COM					
Occupation	Sex	Age	Date of Birth	Race		
Self employed	Male	39	20/10/1981	Chinese		
Institution/School Name	Language English					
Date/Time Of Incident 13/03/2021 18:30	Location Of Incident PENJURU ROAD					
Brief details.				aadeen nistaalaan meessa rii in mahaallassa rii saahii sahan gaha muun sahaliin shehariin 1,5 sheystallassi So Tara		

On the stated date and time I vehicle SMG5853G was stationary on the stated venue. Suddenly vehicle XE5410G came from behind and hit onto my vehicle rear portion. Due to the impact I suffered neck and back pain. I then proceeded to Unihealth 24hr clinic jurong East to seek treatment and was given 3 days MC.

Signature Of Officer Recording The Report:	Signature Of Informant: The identity of the person making this
Not applicable	report has been authenticated by SingPass. No signature is required
Signature Of Interpreter: Not applicable	Date/Time: 14/03/2021 22 48
Officer in-Charge Of Case:	Classification Of Case:
Authentication Stamo	The comment of the co

**Financial** 

## BMW 7 Series 740Li Luxury Sunroof

Accessories

Price \$178,888 Depreciation (?) \$24.740 /vr Reg Date 06-Nov-2015 View models with similar depre (4yrs 7mths 19days COE left) Mileage 83,740 km (15.6k /yr) Manufactured (?) 2015 Road Tax 🗇 \$2,384 /yr **Transmission** Auto Dereg Value ② \$116,355 as of today (change) OMV (7) \$86,721 COE (?) ARF ① \$128,098 \$57,501 240.0 kW (321 bhp) **Engine Cap** 2,998 cc Curb Weight ① 1,770 kg No. of Owners

Similar

Research

**Photos** 

Мар

#### Features

Type of Vehicle

Overview

View specs of the BMW 7 Series

Luxury Sedan

#### Accessories

Carbon Core, Sunroof, BMW Touch Command, Gesture Control, Electric Massage Seats, Soft Closing, 360 Camera/Sensors, Electric Tailgate, Roller Blind.

#### Description

Lowest Depreciation. Fully PML Unit. Serviced And Maintained By PML Till End 2020. Wear And Tear Changed. Loan Available.

#### Category

PARF Car, Direct Owner Sale

#### Status

Available for sale. Shortlist this car to get alerted whenever the price or availbility changes.

#### Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



**Vehicle Evaluation** 

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 14-Mar-2021 | Last Updated on: 15-Mar-2021

Upfront Payment		<ul><li>rnore Financial info</li></ul>
Transfer Fee	\$25	
Down Payment ⑦	\$71,555 (change) Maximum 60% Loan	
1st Instalment ⑦	\$2,173 Based on 2.48% interest rate  Get your loan approved now in 60 seconds. T&Cs apply.  Learn More	OCBC Bank
Total Upfront Payment 🗇	\$73,753 Check with seller for exact figure (excluding insurance)	









DIRECT OWNER










100% FREE PAPERWORK SUPPORT FOR BOTH BUYER & SELLER







① Compare

Propert Error

· More

Seller Information	
Contact Person(s)	Tan Jasper
Contact No.	98388249 🕒
Enquiry	Contact Seller
ESSENTIAL TRANSACT	TION FORMS
» Indemnity form	» Sales agreement
» Receipt	» Hand-over form
» Ownership Transfer	
GET HELF PAPERV	E IE SIM IM P.E. II