

ASS. REC. BY: Tauji

REF: CS/smo21003418/TUE d3.

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: 9174K.  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS WP

Date: \_\_\_\_\_ Person Contacted: John  
Vehicle: IN / OUT

Veh No: SMG8853G Yr Regn: 2015, 04.  
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 740LI SR c.c. 2998  
Colour: Grey A/C: Insured / Std / NI / NA  
Sp. Reading: 137951 T/Radio: Insured / Std / NI / NA  
Eng/No: WBA7E 22000 61099721  
C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40R19  
R: 275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 12/3/20  
Survey held at AP Auto  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / F.B.F. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

# AP Automotive Services

AP AUTOMOTIVE SERVICES PTE LTD  
ROC: 202022890H  
BLOCK 9008  
TAMPINES STREET 93 #01-202  
SINGAPORE 528840  
TEL: 6784 4465  
FAX: 6787 4886

## Estimation

Date 15/3/2021  
Vehicle SMG 5853G  
Make/Model BMW 740i  
Chassis No. WBA7E22000GD99721

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	REAR BOOTLID	1	\$ 2,181.55	\$ <i>ht</i> 2,181.55
2	REAR BOOTLID LOGO	1	\$ 71.95	\$ <i>nei</i> 71.95
3	REAR BOOTLID CHROME	1	\$ 145.20	\$ <i>at</i> 145.20
4	REAR BOOTLID CHROME GARNISH	1	\$ 233.45	\$ <i>de</i> 233.45
5	REAR BOOTLID CHROME GARNISH NUMBER PLATE LAMP	SET	\$ 54.45	\$ <i>x</i> 108.90
6	REAR BOOTLID CHROME GARNISH OPENER	1		\$ <i>x</i> -
7	REAR BOOTLID CHROME GARNISH REAR CAMERA	1	\$ 725.60	\$ <i>x</i> 725.60
8	REAR BOOTLID INNER TRIM	1	\$ 134.70	\$ <i>x</i> 134.70
9	REAR BOOTLID EMBLEM '740i	1	\$ 64.75	\$ <i>na</i> 64.75
10	REAR BOOTLID LAMP L+R	2	\$ 565.85	\$ <i>one</i> 1,131.70
11	REAR BOOTLID WEATHERSTRIP	1	\$ 129.35	\$ <i>int</i> 129.35
12	REAR TAILLAMP L+R	2	\$ 808.40	\$ <i>LH-RH-X</i> 1,616.80
13	REAR TAILLAMP CLIPS L+R	2	\$ 23.00	\$ <i>LH-RH-X</i> 46.00
14	REAR BUMPER	<i>1.2</i>	\$ 1,755.35	\$ <i>de</i> 3,510.70
15	REAR BUMPER RETAINER L+R	2	\$ 162.25	\$ <i>x</i> 324.50
16	REAR BUMPER REFLECTOR L+R	2	\$ 39.05	\$ <i>one</i> 78.10
17	REAR BUMPER REVERSE SENSOR	4	\$ 251.40	\$ <i>dis</i> 1,005.60
18	REAR BUMPER SIDE CHROME L+R	2	\$ 43.75	\$ <i>at</i> 87.50
19	REAR BUMPER LOWER CHROME	1	\$ 40.75	\$ <i>one</i> 40.75
20	REAR BUMPER LOWER CHROME L+R	2	\$ 86.75	\$ <i>bt</i> 173.50
21	REAR BUMPER EXHAUST CHROME TIP L+R	2	\$ 248.80	\$ <i>bt</i> 497.60
22	REAR BUMPER REINFORCEMENT BAR	1	\$ 976.10	\$ <i>bt</i> 976.10
23	REAR BUMPER SPONGE	1	\$ 82.60	\$ <i>x</i> 82.60
24	REAR BUMPER CENTER BRACKET	1	\$ 67.80	\$ <i>one</i> 67.80
25	REAR KICK SENSOR	1	\$ 51.20	\$ <i>one</i> 51.20
26	REAR OPENER SENSOR	1	\$ 46.55	\$ <i>dis</i> 46.55
27	REAR FENDER L+R	2	REPAIR	<i>x</i> REPAIR
28	REAR FENDER INNER TRIM L+R	2	\$ 352.25	\$ <i>x</i> 704.50
29	REAR FENDER COWLING L+R	2	\$ 181.80	\$ <i>x</i> 363.60
30	END PANEL	1	\$ 1,763.20	\$ <i>ht</i> 1,763.20
31	END PANEL TOP GARNISH	1	\$ 113.00	\$ <i>one</i> 113.00
32	SPARE WHEEL PANEL	1	\$ 352.25	\$ <i>x</i> 352.25
33	SPARE WHEEL PANEL TOP BOARD	1	\$ 704.45	\$ <i>x</i> 704.45
34	REAR EXHAUST PIPE	1	\$ 2,537.70	\$ <i>?</i> 2,537.70
35	REAR EXHAUST HEAT SHIELD	1	\$ 80.35	\$ <i>?</i> 80.35
36	REAR EXHAUST GASKET	1		\$ <i>?</i> -
37	FRONT SEATBELT L+R	2	\$ 1,029.65	\$ <i>at</i> 2,059.30



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	384Z

### Vehicle Details

Vehicle No.:	SMG5853G
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Mar 2021
Vehicle Make:	B.M.W.
Vehicle Model:	740LI SR LED NAV HUD
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	22879348B58B30A
Chassis No.:	WBA7E22000GD99721
Maximum Power Output:	240.0 kW (321 bhp)
Open Market Value:	\$84,493.00
Original Registration Date:	28 Oct 2015
First Registration Date:	28 Oct 2015
Transfer Count:	2
Actual ARF Paid:	\$124,088.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2025
PARF Rebate Amount:	\$86,861.00

### Intended COE Rebate Details

COE Expiry Date:	27 Oct 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,889.00
COE Rebate Amount:	\$27,384.00
<b>Total Rebate Amount:</b>	<b>\$114,245.00</b>

The information contained herein is correct as at 15 Mar 2021

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	15/03/2021 19:04 (SGT)
Date of Accident	13/03/2021 18:30 (SGT)
Exact Location of Accident	Penjuru Rd, Singapore
Additional Location Information	BEFORE PENJURU FLYOVER
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG5853G
INSURED POLICY HOLDER	
Is company?	No
Name Of Registered Owner	TAN CHEE KONG
NRIC No	SXXXX384Z
Email Address	davetan9869@gmail.com
Mobile Phone No	(Phone) +65-93808373
Alternative Phone No	+65-93808373

## VEHICLE PARTICULARS

Manufacturer	BMW
Model	740li
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

## INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00152562000
Cover Note Number	-

## DRIVER

Name of Driver	TAN CHEE KONG
NRIC No	SXXXX384Z
Date Of Birth	20/10/1981
Occupation	Outdoor

Date Of Driving Pass	20/04/2005
Driving experience	15 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93808373
Alt. Phone Number	+65-93808373
Email Address	davetan9869@gmail.com
Address	BLK 742 YISHUN AVENUE 5 #10-450
Address complement	-
Postcode	760742
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Clementi Division Headquarters
Police Station Phone No	(Phone) +65-18007740000
Alt. Police Station Phone No	(Fax) +65-67741705
Police Station Address	20 Clementi Avenue 5 Singapore 129858
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT D/20210314/7030

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	XE5410G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-



Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
-  
-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	TAN CHEE KONG
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BACK AND NECK PAIN
Injured person in which vehicle?	SMG5853G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

Sketch Plan

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



Veh A: 8mG 5853G

Veh B: XB 5410G



Describe Circumstances of the Accident


On the stated date and time I vehicle A was stationary on the stated venue. Suddenly vehicle B came from behind and hit onto my vehicle's rear portion. The impact was so great that my vehicle could not start at all after that.


POLICE REPORT D/20210314/7030

Declaration

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
15/03/2021  
Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



D/20210314/7030

1 of 1

**POLICE REPORT (NP299)**

**Report No. D/20210314/7030**

Police Station Of Origin  
Clementi Division HQ  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-7740000

Date/Time Report Made 14/03/2021 22:48	Vide Report No.	Station Diary No.
Name Of Informant TAN CHEE KONG	Address 742 YISHUN AVENUE 5 #10-450 SINGAPORE 760742	
ID Type / ID No. NRIC NO / S8155384Z	Contact No. Home/Office:	Mobile: 93808373
Nationality MALAYSIAN	Email Address DAVETAN9869@GMAIL.COM	
Occupation Self employed	Sex Male	Age 39
Institution/School Name	Date of Birth 20/10/1981	Race Chinese
Date/Time Of Incident 13/03/2021 18:30	Location Of Incident PENJURU ROAD	

**Brief details.**

On the stated date and time I vehicle SMG5853G was stationary on the stated venue. Suddenly vehicle XE5410G came from behind and hit onto my vehicle rear portion. Due to the impact I suffered neck and back pain. I then proceeded to Unihealth 24hr clinic Jurong East to seek treatment and was given 3 days MC.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required
Signature Of Interpreter: Not applicable	Date/Time: 14/03/2021 22:48
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

# BMW 7 Series 740Li Luxury Sunroof

- Overview
- Financial
- Accessories
- Similar
- Research
- Photos
- Map

DIRECT OWNER

Price	\$178,888		
Depreciation <sup>?</sup>	\$24,740 /yr View models with similar depre	Reg Date	06-Nov-2015 (4yrs 7mths 19days COE left)
Mileage	83,740 km (15.6k /yr)	Manufactured <sup>?</sup>	2015
Road Tax <sup>?</sup>	\$2,384 /yr	Transmission	Auto
Dereg Value <sup>?</sup>	\$116,355 as of today (change)	OMV <sup>?</sup>	\$86,721
COE <sup>?</sup>	\$57,501	ARF <sup>?</sup>	\$128,098
Engine Cap	2,998 cc	Power	240.0 kW (321 bhp)
Curb Weight <sup>?</sup>	1,770 kg	No. of Owners <sup>?</sup>	2
Type of Vehicle	Luxury Sedan		


Features  
View specs of the BMW 7 Series


Accessories  
Carbon Core, Sunroof, BMW Touch Command, Gesture Control, Electric Massage Seats, Soft Closing, 360 Camera/Sensors, Electric Tailgate, Roller Blind.

Description  
Lowest Depreciation. Fully PML Unit. Serviced And Maintained By PML Till End 2020. Wear And Tear Changed. Loan Available.


Category  
PARF Car, Direct Owner Sale


Status  
Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources  
 **Car Valuation - Free**  
Find out the market value of your existing car for free. Get started

 **Vehicle Evaluation**  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 14-Mar-2021 | Last Updated on: 15-Mar-2021

Upfront Payment		» more Financial info
Transfer Fee	\$25	
Down Payment <sup>?</sup>	\$71,555 (change) Maximum 60% Loan	
1st Instalment <sup>?</sup>	\$2,173 Based on 2.48% interest rate Get your loan approved now in 60 seconds. T&Cs apply. Learn More	
Total Upfront Payment <sup>?</sup>	\$73,753 Check with seller for exact figure (excluding insurance)	



**Seller Information**

Contact Person(s) Tan Jasper

Contact No. 98388249 

Enquiry  Contact Seller

**ESSENTIAL TRANSACTION FORMS**

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» Ownership Transfer

 GET HELP WITH PAPERWORK

 SGEARMART CONNECT

SGEARMART Connect handles your transaction paperwork