


K9f3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/INV
 To Inspect Vehicle No: GBE 116A
 at Workshop m/s AK Lim
 of _____
 Insured: GX 1685H
 Policy No. DMCVSNA00018512102C02
 Claims No. SNM21D201440
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 2.30pm

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 07 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBE 116A Yr Regn: 08, 15
 Type: M.Car / M.Cycle / Bus / Van / Lotus / Taxi / Prime Mover /
 Truck / Trailer or Lotus
 Make: NIS Cabstar C.C. 2953
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 315386 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JNISC 2F248 0857586
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NIS / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15X8
 R: 155R12X8(10)
 BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
 TOYO/YOKO or

Front Rear
 R/Bal. 8 mm R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 10/3/21 D.O.I. 17/3/2021
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
& M
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
18/03/21@10.33AM	REVISED TO CECILIA LOW VIA MERIMEN.
	Kenneth confirmed LS \$4850 (Red \$8169.44, 63%)

Date/Time, File Pass to?

☐: Prell. Report

1) 28/07 Typist

☐: Final Report

Date/Time, File Return to?

Days Of Repair: 7Resurvey No. of Trip: 1

Survey Fee:

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$

Transportation:

\$ + RS. \$

Parking

Others

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LAI YEW SENG PTE LTD
7 TOA PAYOH LOR 8 #01-1247
TOA PAYOH INDUSTRIAL PARK
SINGAPORE 319059
TEL: 62549851
ATTN:

Estimate No: MC1901819
Date: 12 Mar 2021
Policy No: M0008313
Veh Reg No: GBE116A
Make/Model: NISSAN CABSTAR 3.0
5M/T ABS 2DR 2WD
EURO 5

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/03/2021
TP Veh Reg No: GX1685H

Not Notified

11 Days

Money After Paint

7 days

Estimate Repair Cost to Vehicle No :GBE116A

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 FRONT WINDSCREEN MOULDING TOP LH & RH	2 PC	216.00	✓
2 FRONT WINDSCREEN MOULDING LH & RH	2 PC	176.00	✓
3 FRONT WINDSCREEN MOULDING BOTTOM	1 PC	41.60	✓
4 WIPER PANEL	1 PC	525.50	✓
5 FRONT PANEL	1 PC	1,580.90	✓
6 FRONT PANEL LOGO CABSTAR	1 PC	46.00	✓
7 FRONT GRILLE	1 PC	670.60	?
8 FRONT GRILLE EMBLEM	1 PC	64.00	?
9 FRONT GRILLE CLIP	6 PC	30.60	?
10 FRONT GRILLE CENTRE BRACKET	1 PC	42.00	X
11 HEADLAMP LH & RH	2 PC	1,037.00	✓
12 HEADLAMP LOWER COVER LH & RH	2 PC	178.00	✓
13 FRONT BUMPER (WITH REINFORCEMENT)	1 PC	1,155.10	✓
14 FRONT BUMPER BRACKET LH & RH	2 PC	122.00	?
15 REAR GATE ASSEMBLY	1 PC	1,459.60	✓
16 REAR GATE STICKER NISSAN	1 PC	80.10	✓
17 TAILAMP LH & RH	2 PC	532.60	✓
		7,957.60	
	Less 10%	795.76	7,161.84
18 AIR CON CONDENSER BLOWER MOTOR	1 PC	587.00	X
19 AIR CON CONDENSER HEATER UNIT (WITH COOLING COIL)	1 PC	1,376.10	?
		1,963.10	1,963.10
Special Nett			
20 INNER SEAL	1 PC	20.00	✓
21 SEALANT	1 PC	40.00	✓
22 ERP SEALANT	1 PC	15.00	X
23 FRONT DOOR LH COMPANY REG. STICKER -CHECK PRICE	1 PC	0.0000	X
24 FRONT DOOR LH COMPANY STICKER LYS -CHECK PRICE	1 PC	0.0000	X
25 REAR GATE STICKER 70KM/H -CHECK PRICE	1 PC	0.0000	✓
26 REAR GATE STICKER 13 PAX -CHECK PRICE	1 PC	0.0000	✓
27 REAR GATE PLATE -CHECK PRICE	1 PC	0.0000	?
28 REAR GATE PLATE RIVET -CHECK PRICE	22 PC	0.0000	✓
29 NUMBER PLATE	2 PC	70.00	40.00
30 NUMBER PLATE REAR REINFORCEMENT BAR	1 PC	0.0000	X
31 REVERSE SENSOR SET	1 PC	200.00	?

M/S : LAI YEW SENG PTE LTD
 7 TOA PAYOH LOR 8 #01-1247
 TOA PAYOH INDUSTRIAL PARK
 SINGAPORE 319059
TEL: 62549851
ATTN:

Estimate No: MC1901819
Date: 12 Mar 2021
Policy No: M0008313
Veh Reg No: GBE116A
Make/Model: NISSAN CABSTAR 3.0
 5M/T ABS 2DR 2WD
 EURO 5

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/03/2021
TP Veh Reg No: GX1685H

Estimate Repair Cost to Vehicle No :GBE116A

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		345.00	345.00
LABOUR			
32 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	✓
33 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	✓
34 LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	1 EA	120.00	✓
35 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	300.00	2501
36 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES. FRONT	1 PC	60.00	✓
37 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	✓
38 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD WIPER PANEL, FRONT PANEL. TO KNOCK & REPAIR FRONT DOOR LH, CORNER PANEL LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	✓
39 TO SPRAY WIPER PANEL, FRONT PANEL, CORNER PANEL LH & RH, FRONT DOOR LH	1 PC	800.00	7201
		2,280.00	2,280.00
Total			S\$ 11,749.94
Add GST @ 7%			822.50
Total Amount Payable			S\$ 12,572.44

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FIVE HUNDRED SEVENTY TWO AND CENTS FORTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/03/2021 18:18 (SGT)
Date of Accident 10/03/2021 13:40 (SGT)
Exact Location of Accident Loyang Ave, Singapore
Additional Location Information LOYANG AVE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE116A
INSURED POLICYHOLDER
Is company? Yes
Name Of Registered Owner LAI YEW SENG PTE LTD
Company Reg No 2XXXXX711E
Email Address RAJ@LAIYEWSENG.COM.SG
Mobile Phone No (Phone) +65-90275950
Alternative Phone No (Office) +65-62549851

VEHICLE PARTICULARS

Manufacturer Nissan
Model CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle


INSURANCE COMPANY

Name of Insurance Company Etiqa
Type of Coverage Comprehensive
Fleet Policy No
Policy Number M0008313
Cover Note Number 13/08/2020 - 12/08/2021

DRIVER

Name of Driver GOVINDARAJ GAJENDRAN
Passport No/FIN GXXXX196N
Date Of Birth 15/05/1989
Occupation Outdoor

Date of accident: 10/03/21 Time: 1:40PM Location: LOYANG AVE
My Vehicle A: GBE116A Vehicle B: GX 168SH Vehicle C: UNKNOW (Car)
SKETCH PLAN D: SHA 4666C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS AT LOYANG AVE TRAFFIC JUNCTION AT 1:40PM AND STATIONED
2ND VEHICLE AT LANE 4. I MOVED THE VEHICLE WHILE THE
TRAFFIC LIGHT TURNS GREEN, AND VEHICLE 'C' FROM LANE 3
MERGE INTO LANE 4 WITHOUT PUTTING A SIGNAL LIGHT BUT
I HAS GIVEN WAY TO HIM. ACCIDENTLY VEHICLE C HIT VEHICLE D,
I HAS NOTIFIED THE INCIDENT AND MANAGED TO STOP THE
VEHICLE. BUT VEHICLE B FROM BEHIND ME UNABLE TO STOP
AND HIT MY VEHICLE AND THEN I ALSO HIT VEHICLE C.
IN THIS ACCIDENT MY VEHICLE AT 3RD POSITION. VEHICLE B
DO NOT WANTS TO SHARE WITH ME HIS PARTICULARS.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:


Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AH LIM MOTOR COMPANY