

ASS. REC. BY:

REF: CS/MSG21003426/AGqf3

Special Instruction:

Surveyor: ADRIANASSIGNMENT (Office)From (Person): KOH MONG SAO of MSIG Date/Time: 16 Mar 2021 13:48

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLU 8296H Insured: SGX 2558Kat Workshop m/s Hua Meng Spray Painting Workshop (HQ) Tel: 67478064, 67465519of No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki BukitPolicy No: 29146646AT2 Claim No: 634528

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/03/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement: _____

Date/Time: 16-03-21 1.56P.M Person Contacted: JING YEE Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SLU 8296H- ☒
	SGX 2558K- NA/AIG13001751/m2 DOA :25/01/2013