

Claim Handling

Task Transfer

Exit

Accident MT/1124669

LOS

SAL

SUB

Policy No.

5112393946-01

Certificate No.

Policyholder Name

ODT (SINGAPORE) PTE LTD

Product Code

COMMERCIAL VEHICLE INSURA

Contact No.(Mobile)

96542485

Email Address

KFK

No

Yes

NCD Protection

No

Vehicle No.

GBJ8151T

GST Registration No.

Policyholder NRIC

201301798N

Cover Type

Comprehensive

Contact No.(Office)

Contact No.(Home)

Special Remark

eCode

No

TCA

No

Yes

eCode Reason

NCD Entitlement(%)

10

Private Hire

No

Accident Details

Report Date

17/03/2021 10:29

Date of Accident

15/03/2021

Reporting Centre

NATIONAL ASSESSMENT CENTRE

Accident Location

TURNING TO AMK ST 11

Accident Report Within 24 hrs

Yes

Time of Accident hh:mm

18:20

Orange Force

No

Accident Type

Collision - Cross Junction

Country of Accident

Singapore

ICM No.

Total Excess Applicable

Excess Type

Per Accident

Windscreen Excess

100.00

OD Standard Excess

600.00

YIED OD Excess

0.00

Additional Excess

Total OD Excess Applicable

600.00

TP Standard Excess

0.00

YIED TP Excess

0.00

Total TP Excess Applicable

0.00

Driver is Covered?

Covered

Benefits

GST Registered Information

GST Registered

No

GST Registration No.

Modification History

17/03/2021 10:33:49 System changed GST Registered from Yes to No
17/03/2021 10:33:49 System changed GST Registration No. from 201301798N to null
17/03/2021 10:33:49 System changed GST Registration Date from 17/01/2013 to null

GST Registration Date

GST Status Verified

Yes

Policyholder Mailing Address

Address 1

BLK 114 #11-351

Address 2

ANG MO KIO AVENUE 4

Address 3

KEBUN BARU HEIGHTS

Address 4

SINGAPORE 560114

Address Type

Singapore address

Post Code

560114

Unit No.

11-351

Related Policy Number

5112393946-01

OI Driver Info

Driver Name

Unnamed Driver

Unnamed driver Name

YU SHUYUE

Register Date of Driver License

11/03/2016

Contact No.(Mobile)

98362276

Address 1

BLK 114 #11-351

Address 4

SINGAPORE 560114

Unit No.

11-351

Does he own a Singapore Registered car?

Yes

No

Driver Type

Unnamed Driver

Driver NRIC

S7367421B

Driver Age

47

Contact No.(Office)

Address 2

ANG MO KIO AVENUE 4

Address Type

Singapore address

Post Code

560114

Driver Vehicle No.

Driver Insurer Company

Driver DOB

20/04/1973

Driving Experience

5

Contact No.(Home)

Address 3

KEBUN BARU HEIGHTS

Declaration

Breathalyser or Blood Test Reading?

0 mg

Any injury?

Yes

No

Modification History

Investigation

Claim 002 OD-MD

Claim

Case Officer Yap Chee Ling

Claim Type

OD-MD

Contact No.(Mobile)

NIL

Email Address

Claim Description

GBJ8151T / SLH5692K ON 15 Mar 2021

Preferred Workshop Contact No.

Require Finalisation

Yes

Date Registered

17/03/2021 14:02

Report Taken By

SHAN HUI

Print AK letter

Modification History

Insured Name

ODT (SINGAPORE) PTE LTD

Contact No.(Home)

OI Vehicle Number

GBJ8151T

Insured Liability

Partially at Fault

Preferered Repair Option

income to assign workshop

Claim Close Date

Workshop Repairer

Insured NRIC

201301798N

Contact No.(Office)

TP Vehicle Number

SLH5692K

Name of Preferred Workshop

GIA report

Received

Date Received

17/03/2021 00:

Total Loss but Repaired

OD Excess Collected by Workshop

Special Claim Creation Approval

https://gicclaim.income.com.sg/gcs/icm/eclaim/damageAssessmentSave.do

1/3

Approval

Reason

Remarks

damage assessment

Attachment

Vehicle Info

Vehicle Make

NISSAN

Vehicle Model

NV200

Engine Capacity

0.74

Date of Registration

04/09/2019

Classis No.

VM20129887

Towing Required *

☒ Yes

☐ No

Vehicle in IDAC *

☒ Yes

☐ No

Parallel Import *

☒ Yes

☐ No

Type of Tender *

Own Damage

Assessor Name *

SIMON

Survey Current Status

IDAC/Workshop Name

NATIONAL ASSESSMENT CENTR

IDAC/Workshop Location

51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss *

☐ Yes

☒ No

Market Value(\$)

Scrape Value(\$)

Economical Repair Value(\$)

REMARK:NO OF REPAIR DAYS:8 DAYS.1X AIRCON LIQUID PIPE - UNCONFIRM.1X AIR DUCT - REPLACE.1X AIR CLEANER - UNCONFIRM.2X AIRCON CONDENSER SIDE AIR DI

Remark

Remark for Supplementary

Damage Listing

No.	Part No.	Description	Qty *	Repair Coc
1	32200101	NUMBER PLATE (FRONT)	1	Replace
2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
3	16000101	BUMPER (FRONT)	1	Replace
4	16005901	BUMPER SPONGE (FRONT)	1	Replace
5	16006701	BUMPER TOWING COVER (FRONT)	1	Replace
6	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace
7	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace
8	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace
9	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm
10	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm
11	27100101	GRILLE (FRONT)	1	Replace
12	27100801	GRILLE EMBLEM (FRONT)	1	Replace
13	12900301	APRON PANEL (FRONT)	2	Replace
14	27700101	HEAD LAMP (LEFT)	1	Replace
15	27700102	HEAD LAMP (RIGHT)	1	Unconfirm
16	41300101	SUPPORT PANEL (FRONT)	1	Replace
17	149001	BONNET	1	Replace
18	14903401	BONNET LOCK (LOWER)	1	Replace
19	14902201	BONNET HINGE (LEFT)	1	Replace
20	14902202	BONNET HINGE (RIGHT)	1	Replace
21	112023	AIR CON CONDENSER	1	Replace
22	112060	AIR CON FAN	1	Unconfirm
23	344001	RADIATOR	1	Replace
24	344005	RADIATOR COWLING	1	Unconfirm
25	344008	RADIATOR FAN	1	Unconfirm
26	344007	RADIATOR EXPANSION TANK	1	Replace
27	141001	BATTERY	1	Unconfirm
28	243014	ENGINE LOWER COVER	1	Replace
29	19600501	CHASSIS MEMBER (FRONT LEFT)	1	Repair
30	19600502	CHASSIS MEMBER (FRONT RIGHT)	1	Repair
31	25400102	FENDER (FRONT LEFT)	1	Repair
32	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace
33	25400103	FENDER (FRONT RIGHT)	1	Repair
34	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Replace
35	124001	ALTERNATOR	1	Unconfirm
36	268001	GEAR BOX	1	Unconfirm
37	268006	GEAR BOX MOUNTING	1	Unconfirm

Find a Part

root

Not Applicable

ABS

ABSORBER

ACCELERATOR

ACTUATOR

ADVERTISEMENT STICKER

AIR BAG

AIR BLOWER

AIR BOX

AIR CHAMBER BOX

AIR CLEANER

AIR COMPRESSOR

AIR CON

AIR CON (VAN)

AIR COOLER

AIR DISTRIBUTOR

AIR FILTER

AIR FLOW

AIR GRILLE

AIR HORN

AIR INTAKE

AIR RESONATOR BOX

AIR THROTTLE BODY AND SENSOR

ALARM

ALTERNATOR

ALUMINIUM PANEL - SIDE

AMPLIFIER

ANTENNA

ANTI ROLL

APRON

ARCH

ARM REST

ASH TRAY

AUTO CLUTCH

AUTO COOLER PIPE

AUTO CRUISE MOTOR

AUTO TRANSMISSION

AXLE

BACK REST (M/C)

BACK SEAT

BALANCER

BATTERY

BEADING (M/C)

BELT COVER (M/C)

BELT TENSIONER

BODY

BODY (M/C)

BOLT CAP (M/C)

BOLT HEAD COVER (M/C)

BONNET

BOOT

BOX (M/C)

BOX BRACKET (M/C)

BOX CARRIER (M/C)

BOX DOOR

38	24301903	ENGINE MOUNTING (FRONT)	1	Unconfirm
39	24301905	ENGINE MOUNTING (REAR)	1	Unconfirm
40	24301906	ENGINE MOUNTING (RIGHT)	1	Unconfirm
41	26600101	FUSE BOX (BOTTOM)	1	Unconfirm
42	26600102	FUSE BOX (CENTRE)	1	Unconfirm
43	26600103	FUSE BOX (TOP)	1	Unconfirm

Save

Submit