



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21003437/Gvf3n2 Date: 01/07/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGS 9717Z	Veh. Inspected	SKR 4090M	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009404/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	16/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5X	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11014483	Colour	WHITE	
Odometer	128340 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GOODYEAR	6 mm	
L/H Front Tyre	215/60 R16	GOODYEAR	6 mm	
R/H Rear Tyre	215/60 R16	GOODYEAR	6 mm	
L/H Rear Tyre	215/60 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/03/2021	Inspection Date	16/03/2021	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	