

ASS. REC. BY:

PRs

ASSIGNMENT

From:

Date:

Veh No:

JPL4670

Yr Regn:

2013

Estimated Cost:

Type: M.Cár / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Yamaha BSLC c.c. 134

at Workshop m/s

Colour:

Black

A/C: Insured / Std / NI / NA

of

Sp. Reading

1430

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

PMYKE70250D0029509

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:


F:

70/90-17

R:

80/90-17

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal.

5 mm

R/Bal.

5 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal.

5 mm

L/Bal.

5 mm

Est. Repairs: 3 days Res.: Yes or No

D.O.A. 12/3/21

D.O.I.

17-03-21

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at

W/S

Spm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

New Bike RM 6868 - RM 7118

\$2000 - \$3000

Date/Time, File Pass to?



Preli. Report

Days Of Repair: 3

1)



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) 19/3/21-Typist

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Absence (\$

Survey Fee:

Transportation:

3 + RS. SI

Photos

Other:

Report Form: PRS

Lump Sum / 10000

TOTAL