

Ass. No. BY: Sun Pin.

CS/CTI 21003 44/64 fJ.

chn

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: CB 6666T
 at Workshop m/s A T Auto Consultant (HQ)
 of _____
 Insured: GBK 9549T
 Policy No. DMCVSNA00127532000
 Claims No. SNM21D201399C02
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: CB6666T Yr Regn: 17/07/2012
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yutong ZK6107H Auto 6693.
 Colour: Green A/C: Insured / Std / NI / NA
 Sp. Reading: 657533 T/Radio: Insured / Std / NI / NA
 Eng/No: -
 C/No: LZYTBT060B1033752
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Tyre Size: F: 11 R 22.5
 R: 11 R 22.5
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11/03/2021 D.O.I. 13/04/2021
 Survey held at AT Auto.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/4/2021 @ 11.22AM	REVISED TO ADELINE CHNG VIA MERIMEN.
	MV: Pr: 0 NR:
27/04/21 @ 11.44am	Sun Pin finalised with Alan LS \$7950, 6 days. (Red \$9886.05, 55%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 28/04 Typist
 Date/Time, File Return to?
 2) _____
 Report Form: MER-TP
 Final Sum: 7950

Days Of Repair: 6
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Insp (\$)
 : _____ (\$)
 Survey Fee:
 Transportation: _____ \$
 Photos: _____
 Other: _____
 Total: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/03/2021 12:20 (SGT)
Date of Accident 11/03/2021 06:05 (SGT)
Exact Location of Accident 1 Sungei Kadut Ave, Singapore 729680
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number CB6666T

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner GOH TRANSPORT SERVICES CO. PTE LTD
Company Reg No 1XXXXX033N
Email Address yoey@gohtpt.com.sg
Mobile Phone No (Phone) +65-94810369
Alternative Phone No (Home) +65-94810369

VEHICLE PARTICULARS

Manufacturer Yutong
Model Zk6107h
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Bus

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance
Type of Coverage Comprehensive
Fleet Policy No
Policy Number SD20V16339/VBS/R00
Cover Note Number -

DRIVER

Name of Driver MOHAMED YAZID BIN HAJI
NRIC No SXXXX514H
Date Of Birth 13/02/1981
Occupation Outdoor

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Jurong East Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-1800899999
 Alt. Police Station Phone No (Fax) +65-66655791
 Police Station Address No. 92 Boon Lay Way Singapore 609962
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number GBK9549T
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

INJURED PERSONS DETAILS

INJURED 1

Name of injured person RAJENDRAN CHOKKANATHAN
 Address -
 Address Complement -
 Post Code -
 Approximate Age Years Old -
 Injuries Sustained -
 Injured person in which vehicle? CB6666T
 Were seat belts worn? Yes
 Was this injured conveyed to hospital by ambulance? No

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time : 11/3/21 06:00am
Accident Location : Along Sungai Kadut Street 1

Please refer to the attached police report.

Reporting Only Own Damage Third Party Claim at other workshop (OD/TP)

DECLARATION

(We declare the foregoing particulars are true in every respect.


IMPORTANT NOTE:

THIS REPORT IS VALID FOR FOURTEEN (14) DAYS FROM THE DATE OF ACCIDENT.


Policyholder's Signature




Driver's Signature



A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
 HP: 8386 8989 Email: atautoconsultant@gmail.com
 Co. Reg. No. : 53368526E

Date of Estimate: 01.04.2021
Vehicle No: CB6666T
Owner: GOH TRANSPORT SERVICES CO. PTE LTD
Date of Accident: 11.03.2021
Make & Model: YUTONG ZK6107H
Chassis No : LZYTBD60B1033752

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ESTIMATE FOR ACCIDENT VEHICLE NO CB6666T

PARTS

1	1	Luggage door nos 2 RH X R	\$2,800.00
2	1	Luggage door nos 2 handle/lock LH X	\$250.00
3	1	Luggage door nos 3 RH / CHY	\$2,800.00
4	1	Luggage door nos 3 handle/lock LH / CHY	\$250.00
5	1	Luggage door reflector / CHY	\$59.00
6	1	Rear wheel panel RH / PB	\$2,900.00
7	1	Rear engine vent panel X R	\$2,600.00
8	1	Mid side top panel (repair) X R	\$0.00
SUB TOTAL			\$11,659.00
LESS 5 %			\$582.95
DISCOUNTED SUB TOTAL			\$11,076.05

S. NETT ITEM

1	1	Rear wheel cover chrome original RH / BT	\$360.00
2	1	Rear tyre / CWF	\$750.00
SUB TOTAL			\$1,110 \$010.00
LESS 0 %			\$0.00
DISCOUNTED SUB TOTAL			\$1,110 \$010.00

LABOUR

1	Panel beating for replace and repair affected parts		\$1,500.00 1,200
2	Spray painting on affected area for 3 colours (8 panels) /		\$3,600.00 2,800
3	Apply putty and anti-corrosion to affected parts		\$500.00 100
4	R/R luggage handle/lock mechanism L/H		\$300.00 50 100
5	Wiring		\$50.00 /
SUB TOTAL (LABOUR)			\$5,950.00

LIS
 After paint photo
 Sun PM (L114)
 13/04/2021

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	033N
Vehicle Details	
Vehicle No.:	CB6666T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Apr 2021
Vehicle Make:	YUTONG
Vehicle Model:	ZK6107H AUTO
Primary Colour:	Green
Secondary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	ISBE425022007664
Chassis No.:	LZYTBD60B1033752
Maximum Power Output:	-
Open Market Value:	\$122,843.00
Original Registration Date:	17 Jul 2012
First Registration Date:	17 Jul 2012
Transfer Count:	0
Actual ARF Paid:	\$6,143.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 12 Apr 2021

OK