

ASS. REC. BY:

REF: LPL/21003461/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lump Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PMQ 30182 Yr Regn: 11, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic cc 1597

Colour

M. Blue

A/C: Insured / Std / Nil / NA

Sp. Reading

14240

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/Nr:

NRHFC5650K4001051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R16

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Hankook

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

14/3/21

D.O.L.

22/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Parties

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 6459 Mobile: 9687 4031
Email: yeeautopte@td@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: LONPAC INSURANCE BHD
300, BEACH ROAD
#17-04/07, THE CONCOURSE
SINGAPORE 199555

Estimate No: ES2100032
Date: 22 Mar 2021
Policy No:
Veh Reg No: SMQ3018L
Make/Model: HONDA CIVIC 1.6 VTI
CVT
Chassis No: MRHFC5650KT001051
Engine No: R16B25511162
Reg. Date: 07/11/2019

ATTN: Motor Claim Department *Not Authorized*

Your Ref No: - *Running B4 pain*
Claim Type: Third Party
Accident Date: 14/03/2021 *2 days*
TP Veh Reg No: GBD5874S

Estimate Repair Cost to Vehicle No :SMQ3018L

Description	U/Price	Quantity	List Price S\$	Amount S\$
Spare Parts				
1 FRONT BUMPER	<i>Rollway</i> 955.80	1 PC	955.80	✓
2 FRONT BUMPER CLIPS	40.00	1 SET	<i>me</i> 40.00	✓
3 FRONT BUMPER FOG LAMP - LH	328.10	1 PC	<i>in</i> 328.10	X
4 FRONT BUMPER FOG LAMP COVER - LH	55.10	1 PC	55.10	7
5 FRONT BUMPER FOG LAMP COVER CHROME MOULDING - LH	85.90	1 PC	<i>me</i> 85.90	✓
6 FRONT BUMPER REINFORCEMENT	365.50	1 PC	<i>R</i> 365.50	X
7 FRONT BUMPER SIDE RETAINER - LH	36.30	1 PC	36.30	7
8 FRONT BUMPER SIDE RETAINER - RH	36.30	1 PC	<i>in</i> 36.30	X
9 FRONT FENDER - LH	544.00	1 PC	<i>R</i> 544.00	X
10 FRONT FENDER LAMP - LH	75.50	1 PC	75.50	7
11 FRONT FENDER SPLASH SHIELD - LH	245.30	1 PC	<i>in</i> 245.30	X
12 FRONT FENDER SPLASH SHIELD CLIP	40.00	1 SET	<i>me</i> 40.00	X
13 FRONT GRILLE	285.50	1 PC	<i>in</i> 285.50	X
14 FRONT HEADLAMP - LH	825.10	1 PC	<i>in</i> 825.10	X
15 FRONT HEADLAMP LOWER BRACKET - LH	65.90	1 PC	<i>in</i> 65.90	X
			3,984.30	3,984.30
Labour				
16 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	<i>2000</i>
17 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00	<i>2000</i>
18 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	<i>152</i>
			1,660.00	1,660.00

Total S\$ 5,644.30

Add GST @ 7% 278.90

Total Amount Payable S\$ 5,923.20

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED TWENTY THREE AND CENTS TWENTY ONLY

For Yee Auto Pte Ltd

[Signature]
AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/03/2021 17:27 (SGT)
Date of Accident 14/03/2021 11:15 (SGT)
Exact Location of Accident 441A Pasir Ris Drive 6, Singapore 511441
Additional Location Information BLK 441A PASIR RIS DRIVE 6 MULTI-STOREY CARPARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMQ3018L

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner SEET WEI REN, IVAN
NRIC No SXXXX883D
Email Address ivanjames87@gmail.com
Mobile Phone No (Phone) +65-81269576
Alternative Phone No (Home) +65-81269576

VEHICLE PARTICULARS

Manufacturer Honda
Model Civic
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company NTUC
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5119558909
Cover Note Number -


DRIVER

Name of Driver SEET WEI REN, IVAN
NRIC No SXXXX883D
Date Of Birth 29/12/1987
Occupation Indoor

SKETCH PLAN

(A) SMD3018L

(B) GBD5874S



Blk 441 A
Pasir Ris
Multi Storey
Carpark

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/3/21 at 11:15 am. I was travelling my vehicle (A) SMD3018L at Blk 441 A Pasir Ris Multi Storey Carpark. As I was park my vehicle and there was nobody in my vehicle. After I came back, I saw the vehicle (B) GBD 5874S leave a note in front my vehicle and i contact with the driver, when he was reversing to the carpark lot he suddenly hit my vehicle front left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

LA
Policyholder's Signature
Date & Time:

LA
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: