

LRC

AIG

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.03.2021

Time: 10:01:45

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305458927
REGN NO : SHD4089C
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.10.2019
DATE/TIME IN : 16.03.2021 15:50
ACCIDENT DATE : 16.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

Table with 6 columns: Part No, Description, Qty, Unit, Price, Amount. Includes handwritten notes like 'del', 'rec', 'Xnn', 'R/R', 'cut'.

SUB-TOTAL : 2,136.52

JOB NATURE

Table with 4 columns: Job No, Description, Price, Amount. Includes handwritten notes like '700', '500', '30', '80.00'.

SUB-TOTAL : 1,610.00

LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Handwritten notes: 'Tanjong WP', '9224 5749', '17/3/21', 'Resurvey after repair', '30 days', 'Tanjong (Kluantan)'.