

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	R	ef:	CC4/ASM21003486/Kga3q2		
	8 SHENTON WAY AXA TOWERSING	D	ate:	15/04/2021		
	ATTN:KITTY		С	ode:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 5783C	Veh. Inspected		SMK 6522J	
	Policy No.	GA319835	Coverage (\$)		0.00	
	Claim No.	S1M035K4	Excess (\$)		0.00	
	Assign From		Assign Date		17/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	RU11316089	Colour		METALLIC PEARL WHITE	
	Odometer	17551 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		8 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		8 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		8 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		8 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	14/03/2021	Inspection Date		17/03/2021	
	Survey held at	urvey held at T & B MOTOR REPAIRS SERVICES PTE LTD				
	BLK 20 SIN MING ROAD #01-28 SINGAPORE 575678					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	STIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					
	ESTIMATED NORI	WAL PERIOD FOR REPAIR:	3	VVOIKI	ing Days	