



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	15/03/2021 10:40 (SGT)
Date of Accident	14/03/2021 11:18 (SGT)
Exact Location of Accident	506 Bukit Batok Street 52, Singapore 650506
Additional Location Information	BLK 506 BUKIT BATOK STREET 52 CAR PARK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5808Z
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SMRT TAXIS PTE LTD
Company Reg No	1XXXXX369K
Email Address	TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi

### INSURANCE COMPANY

Name of Insurance Company	First Capital
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-20095484MFSH
Cover Note Number	-

### DRIVER

Name of Driver	LIM THIAM HOE
NRIC No	SXXXX812A
Date Of Birth	31/07/1972
Occupation	Outdoor

Date Of Driving Pass	24/09/1993
Driving experience	27 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-80000000
Alt. Phone Number	-
Email Address	TARC@smrt.com.sg
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	UNKNOWN
Gender	Female

#### PASSENGER 2

Name	UNKNOWN
Gender	Female

#### PASSENGER 3

Name	UNKNOWN
Gender	Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG THE CAR PARK DRIVE WAY WITH 3 PASSENGERS ON BOARD WHEN SUDDENLY I NOTICED THE VEHICLE GBF3154P FROM THE OPPOSITE DIRECTION ENCROACHED INTO MY TRAVEL PATH TOWARDS MY DIRECTION. IMMEDIATELY I STOP MY TAXI HOWEVER THE VEHICLE GBF3154P DID NOT SLOWED DOWN OR STOP AND CONTINUED ENCROACHED INTO MY TRAVEL PATH AND COLLIDED ONTO THE FRONT RIGHT PORTION OF MY TAXI.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3154P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	AMY TAN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


### Sketch Plan



A - SHB 5848Z  
B - GRP 3154P

## This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

~~I/We declare the foregoing particulars are true in every respect.~~



15/03/21 10.08

du 15/3/22



## Case Details

**Case Reference Number :**  
TAX/03/21/2044

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**  
SHB5808Z

**Company Type :** SMRT Taxis Pte Ltd

**Estimation ID :** EST-14241-ID

**Assigned By :** Taxi Claims Manager  
Team

**Insurance Company Name :** China Taiping Insurance (Singapore) Pte Ltd

**Accident Date and Time :** 14/03/2021 03:18 PM

**Vehicle Age(In Months) :** 15

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	521.00	521.00	25.00	390.75	Replace	1	390.75	Replace	✓ CHY
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	✓ NAC
One Time Key In	Main			COVER, FR BUMPER RH	1	30.20	30.20	25.00	22.65	Replace	1	22.65	Replace	✓ NIS
One Time Key In	Main			GRILLE, RADIATOR	1	178.60	178.60	25.00	133.95	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			LAMP ASSY, FOG, RH	1	237.10	237.10	10.00	213.39	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			SEAL, HOOD TO FR END	1	85.50	85.50	25.00	64.13	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			MOULDING, FRONT BUMPER SIDE, RH	1	95.60	95.60	25.00	71.70	Replace	1	71.70	Replace	✓ SCH
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	80.10	80.10	25.00	60.07	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			ABSORBER, FR BUMPER	1	80.20	80.20	25.00	60.15	Replace	0	0	Check	✓ X SVC

Total Spare Part Cost 14,177.40

Surveyor Total 3,983.19

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 14,177.40

Final Sur Total 3,983.19

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	716.60	716.60	25.00	537.45	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	132.70	132.70	25.00	99.52	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	246.10	246.10	25.00	184.57	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			EXTENSION SUB-ASSY, RH	1	120.10	120.10	25.00	90.07	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			GRILLE SUB-ASSY	1	422.50	422.50	25.00	316.88	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			COVER ASSY, ENGINE	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			HOOD SUB-ASSY	1	983.10	983.10	25.00	737.33	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	58.90	58.90	25.00	44.17	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	58.90	58.90	25.00	44.17	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			CABLE ASSY, HOOD	1	54.90	54.90	25.00	41.17	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	78.90	78.90	25.00	59.18	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			SUPPORT S/A RH	1	245.10	245.10	25.00	183.82	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,637.60	2,637.60	10.00	2,373.84	Replace	1	2,373.84	Replace	✓ OK
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	3,772.50	3,772.50	10.00	3,395.25	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			WIPER WASHER INLET	1	67.00	67.00	25.00	50.25	Replace	0	0	Check	✓ X SVC

Total Spare Part Cost 14,177.40

Surveyor Total 3,983.19

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 14,177.40


Final Sur Total 3,983.19






SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WIPER WASHER JAR	1	219.10	219.10	25.00	164.32	Replace	1	164.32	Replace	✓ / 824
One Time Key In	Main			HOSE, WINDSHIELD WASHER	1	16.80	16.80	25.00	12.60	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			MOTOR AND PUMP ASSY, WINDSHIELD WASHER	1	292.40	292.40	10.00	263.16	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	977.80	977.80	25.00	733.35	Replace	1	733.35	Replace	✓ / CP4
One Time Key In	Main			LINER, FR FENDER, RH	1	202.50	202.50	25.00	151.88	Replace	1	151.88	Replace	✓ / def
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	✓ / Ne
One Time Key In	Main			PAD, FR WHEEL RH	1	59.60	59.60	25.00	44.70	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER , RH	1	979.40	979.40	25.00	734.55	Replace	0	0	Check	✓ X SVC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			WHEEL, DISC FRONT	1	1,879.40	1,879.40	25.00	1,409.55	Replace	1	0	Repair	✓ X R
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,300.70	1,300.70	25.00	975.53	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	✓ X SVC
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	93.90	93.90	25.00	70.43	Replace	0	0	Not Give	✓ X SVC
Total Spare Part Cost									14,177.40	Surveyor Total 3,983.19				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									14,177.40	Final Sur Total 3,983.19				

Labour's Cost Detail





S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,014.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO REPSRAY FRONT HOOD	378.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
5	Main	TO RESPRAY APRON PANEL RH	180.00	0	
6	Main	TO RESPRAY FRONT DOOR RH	378.00	0	
7	Main	TO RESPRAY RIM	180.00	50	
Total:			2,052.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	
6	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
Total:			836.00	130.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	14,177.40	3,983.19
Total Labour Cost	1,014.00	400.00
Total Spray Painting	2,052.00	450.00
Other	836.00	130.00
Overall Total	18,079.40	4,963.19
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	4,963.19
Surveyor Approved Amount		4,963.19
No of Repair Days*	8	3 3 dys
Remarks	-	P/P, Before paint photo.

Surveyor Name

Sun Pin (LKK)

Signature



Save

Clear

Survey Date

16/03/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	369K
<b>Vehicle Details</b>	
Vehicle No.:	SHB5808Z
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Mar 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Maroon
Manufacturing Year:	2019
Engine No.:	2ZR2F34032
Chassis No.:	JTDKB3FU703089241
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	20 Dec 2019
First Registration Date:	20 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2027
PARF Rebate Amount:	\$10,897.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	19 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$21,601.00
<b>Total Rebate Amount:</b>	<b>\$32,498.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Mar 2021

OK