

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                          |  |
|---|--|---|-----------------|--------------------------|--|
|   | UNITED OVERSE  | AS INSURANCE LTD  | Re              | f: CS/UOI21003510/Kqd3e2 |  |
|   | 3 ANSON ROAD #<br>SPRINGLEAF TOV   | 28-01<br>VER SINGAPORE 079909   | Da              | te: 04/05/2021           |  |
|   |  |   | Co              | de: UOI2                 |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                 |                          |  |
|   | Insured Veh.   | SLG 9738S   | Veh. Inspected  | SLN 961K                 |  |
|   | Policy No.   |   | Coverage (\$)   | 0.00                     |  |
|   | Claim No.  | M11D12362104  | Excess (\$)     | 0.00                     |  |
|   | Assign From  | JOSEPHINE WONG  | Assign Date     | 17/03/2021               |  |
| 2.  | . Vehicle Particulars & Condition  |   |                 |                          |  |
|   | Make & Model   | B.M.W. 216D (A)   | c.c             | 1496                     |  |
|   | Engine No.   | HIDDEN  | Year of Reg.    | 2017                     |  |
|   | Chassis No.  | WBA2E320605H46089   | Colour          | WHITE                    |  |
|   | Odometer   | 65485 KM  | Steering        | IN ORDER                 |  |
|   | Brakes   | IN ORDER  | Modification    | STANDARD ALLOY RIM       |  |
|   | General  | GOOD  |                 |                          |  |
| 3.  | 3. Conditions of Tyres   |   |                 |                          |  |
|   |  | Size  | Make            | Balance                  |  |
|   | R/H Front Tyre   | 205/60 R16  | PIRELLI         | 7 mm                     |  |
|   | L/H Front Tyre   | 205/60 R16  | PIRELLI         | 7 mm                     |  |
|   | R/H Rear Tyre  | 205/60 R16  | PIRELLI         | 7 mm                     |  |
|   | L/H Rear Tyre  | 205/60 R16  | PIRELLI         | 7 mm                     |  |
| 4.  | Description of Damages   |   |                 |                          |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  |   |                 |                          |  |
|   | DAMAGES SEE DETAILS.   |   |                 |                          |  |
| 5.  | General Information  |   |                 |                          |  |
|   | Accident Date  | 15/03/2021  | Inspection Date | 23/03/2021               |  |
|   | Survey held at   | WEGA ENGINEERING PTE LTD  |                 |                          |  |
|   |  | BLK 176 SIN MING DRIVE #04-16 SIN MING AUTOCARE .<br>SINGAPORE 575721 |                 |                          |  |
| 5a.   | Remarks  |   |                 |                          |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                          |  |
| 5b.   | Estimate Days of Repair  |   |                 |                          |  |
|   | ESTIMATED NORI   | MAL PERIOD FOR REPAIR:  | 3 V             | Vorking Days             |  |