

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

M11D12362104

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Veh No: SUN 961K Yr Regn: 04, 17  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make:

BMW

216d

c.c

1496

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

65485

T/Radio:

Insured / Std / NI / NA

Eng/No:

WBA2E 32060514 46089

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/3/21

D.O.I.

23/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
015R1

Date / Time

Action / Instruction

Kenneth confirmed LS \$2200, 3 days (Red \$13110, 86%)

Date/Time, File Pass to?

11/26/04 Typist

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / +B. (\$

2200

# WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721  
Tel: 6452 1493 Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

United Overseas Insurance Ltd  
3 Anson Road, #28-01 Springleaf  
Tower Singapore 079909

Date : 16/3/2021

Vehicle No : SLN961K  
Chassis No : WBA2E320605H46089  
Make/Model : BMW 216D SE AUTO  
Year : 2017

*Not Notified*  
*L1 Day 8*  
*Primary After Paint*  
*3 days*

| S/N | Qty | Description                             | Unit Price  | Amount      |     |
|-----|-----|-----------------------------------------|-------------|-------------|-----|
| 1   | 1pc | FRONT BONNET                            |             |             |     |
| 2   | 1pc | FRONT BONNET HIAGE RH                   | \$ 1,045.00 | \$ 1,045.00 | X   |
| 3   | 1pc | FRONT BONNET HIAGE LH                   | \$ 137.50   | \$ 137.50   | X   |
| 4   | 1pc | FRONT BUMPER                            | \$ 137.50   | \$ 137.50   | X   |
| 5   | 1pc | FRONT HEADLAMP RH                       | \$ 1,140.00 | \$ 1,140.00 | ✓   |
| 6   | 1pc | FRONT FENDER RH                         | \$ 1,078.00 | \$ 1,078.00 | ✓   |
| 7   | 1pc | FRONT HEADLAMP BRACKET RH ( TOP PANAL ) | \$ 649.00   | \$ 649.00   | X   |
| 8   | 1pc | FRONT BUMPER BRACKET RH                 | \$ 61.00    | \$ 61.00    | X   |
| 9   | 1pc | FRONT FOG LAMP COVER RH                 | \$ 53.00    | \$ 53.00    | X   |
| 10  | 1pc | FRONT FOG LAMP RH                       | \$ 104.00   | \$ 104.00   | ✓   |
| 11  | 1pc | FRONT SPORT RIM RH                      | \$ 245.00   | \$ 245.00   | ?   |
| 12  | 1pc | FRONT TYRE RH                           | \$ 1,473.00 | \$ 1,473.00 | } X |
| 13  | 1pc | FRONT KNUCKER ARM RH                    | \$ 225.00   | \$ 225.00   |     |
| 14  | 1pc | FRONT WHEEL HUP RH                      | \$ 758.00   | \$ 758.00   |     |
| 15  | 1pc | FRONT WHEEL BEARING RH                  | \$ 589.00   | \$ 589.00   |     |
| 16  | 1pc | FRONT LOWER ARM RH                      | \$ 280.00   | \$ 280.00   |     |
| 18  | 1pc | FRONT ABSORBER RH                       | \$ 487.00   | \$ 487.00   |     |
| 19  | 1pc | FRONT TIE ROD RH                        | \$ 484.00   | \$ 484.00   |     |
| 20  | 1pc | FRONT TIE ROD INNER RH                  | \$ 166.00   | \$ 166.00   |     |
| 21  | 1pc | FRONT TORSION BAR LINK RH               | \$ 122.00   | \$ 122.00   |     |
| 22  | 1pc | FRONT DRIVE SHAFT ASSY RH               | \$ 125.00   | \$ 125.00   |     |
|     |     |                                         | \$ 2,676.00 | \$ 2,676.00 |     |

## Labour Charges

- To check wiring and system function
- To wheel alignment / tyre balancing
- To remove and refix undercarriage
- To respray accident front portion
- To knocking and welding front portion
- To apply rust proofing to affected area
- To replace front tyre
- To check for function and alignment headlamp
- To conduct re-programme and setting of ecu system to clear fault code

|    |             |       |
|----|-------------|-------|
| nn | \$ 120.00   | 201   |
| nn | \$ 120.00   | X     |
| nn | \$ 600.00   | X 400 |
|    | \$ 1,000.00 |       |
| nn | \$ 1,000.00 | 300   |
| nn | \$ 150.00   | X     |
| nn | \$ 55.00    | X     |
| nn | \$ 80.00    | X     |
|    | \$ 150.00   | ?     |

Grand Total

**\$ 15,310.00**

Wega Engineering Pte Ltd

Authorised Signature  
Leong Chee Kwong  
Mobile No: 84917768

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                                   |
|---------------------------------|-----------------------------------|
| Date of Submission              | 15/03/2021 17:54 (SGT)            |
| Date of Accident                | 15/03/2021 14:30 (SGT)            |
| Exact Location of Accident      | 9 Raffles Place, Singapore 048619 |
| Additional Location Information | Republic Plaza MSCP               |
| Country/State of Loss           | Singapore                         |

## DETAILS OF OWN VEHICLE

|                             |         |
|-----------------------------|---------|
| Vehicle Registration Number | SLN961K |
|-----------------------------|---------|

### INSURED/POLICYHOLDER

|                          |                      |
|--------------------------|----------------------|
| Is company?              | No                   |
| Name Of Registered Owner | Quah Sien Hui        |
| NRIC No                  | SXXXX719H            |
| Email Address            | santaaa@yahoo.com    |
| Mobile Phone No          | (Phone) +65-93803607 |
| Alternative Phone No     | +65-93803607         |

### VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | BMW                       |
| Model                                                                        | 216d                      |
| Variant                                                                      | -                         |
| Exact purpose for which vehicle was being used at time of accident           | Private use               |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Private car               |

### INSURANCE COMPANY

|                           |                 |
|---------------------------|-----------------|
| Name of Insurance Company | Sompo           |
| Type of Coverage          | Comprehensive   |
| Fleet Policy              | No              |
| Policy Number             | D20MTPV01004420 |
| Cover Note Number         | -               |

### DRIVER

|                |               |
|----------------|---------------|
| Name of Driver | Quah Sien Hui |
| NRIC No        | SXXXX719H     |
| Date Of Birth  | 19/11/1980    |
| Occupation     | Indoor        |

 Accident report SL03213F0007



4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.


**5 Any false reporting may be referred to the Police for investigation.**

6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.


7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8 Consent under the Personal Data Protection Act (PDPA)**


- I understand, acknowledge, agree and consent that
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore for one or more of the above Purposes

  
15 MAR 2021  
16:15 PM  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
Jenny Lim

**Sketch Plan**





## Describe Circumstances of the Accident

On 15 MAR 2021, 2:30pm, I was driving to work and as usual park wanted to go to my season parking at Republic Plaza to park my car. As I was going up the slope to level 2, a honda yellow Jazz was on its way down to level 1. Our cars collided at the second level where my right bumper and the yellow jazz right back bumper collided. Immediately I look down and noticed that the yellow jazz crossed over the centre yellow line ~~to~~ over to my way of lane. We then proceeded to level 2 parking lots to take pictures of the damage. Both my car and the yellow jazz do not have in cam videos in our car. But I noticed that Republic Plaza have a few cameras on the level 2 car park and it will be useful to request for videos for the accident.

## Declaration

We declare the foregoing particulars are true in every respect.