

REF:CS3/LPC20013711/Aqd3-1

Special Instruction:

L/S : \$17,900.00

Third Parties:

Claimant:

Surveyor: PAR AUTOMOTIVE

Workshop: SIN HOCK LEE MOTOR

From (Person): ONG LI LI of LPC ASSIGNMENT (Office)
Estimated Cost: _____ Date/Time: 17/03/2021
Bill to: _____

OD TP Re-inspection / Evaluation

To Inspect Vehicle No: SJN 9965P Insured: SDQ 407Z

at Workshop m/s SIN HOCK LEE MOTOR

of Blk 51 Ubi Avenue 1#01-09 Paya Ubi Ind

Policy No: _____ Claim No: 20/20/20/VP05/023991

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08/12/2020
(Client's Record)

19/03/2021@ 10AM

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, ____ days (Red S ____/____%; Original ¹⁶____ days)

Date/Time: 19/03/21 Submit Final Fig LS \$13400, 13 days (Red \$4500 / 25 %; Original 16 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

1) Date/Time 19/03/21 File Pass to Typist

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____