

08/11/13) wef

ASS. REC. BY: Paul

REF:

CS/CT121003539/R4P3

0213

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKN 8824Hat Workshop m/s. PERFORMANCEof 303, ALEXANDRA RDInsured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 59K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKN 8824H Yr Regn: 2014 JULYType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 316I 1.6 AT c.c. 1598Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 137209 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA3A16070NS37589Gen. Cond: Good / Fail / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 225/40R19R: 225/40R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/02/21 D.O.I. 22/04/21Survey held at PERFORMANCEDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 21K

Finalised amount of \$ 7,711.85 / 5 days of repair is confirmed

red: 3904.8;33%

11616.65

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 57849
Date Estimated : 17/03/2021
Prepared By : Brandon Chan Eng Meng

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Danny Chan Chia Aun (Chen Jia'an)
55 Mimosa View

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 805635

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN8824H	WBA3A16070NS37589	25/07/2014	316iA/4	0

DESCRIPTIONVALUE

To replace rear bumper, rear bumper carrier, rear trunk lid
, attachment item cause by accident.

1700 3,400.00

To spray paint rear bumper & rear trunk.

1826 1,925.00

To check electrical wiring system and lighting at the
rear section for proper function.

168 177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

168 177.00

To transfer lock mechanism from old to new bootlid
including conduct check on new bootlid central locking system
for proper function.

504 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries

? 150.00

Total Labour 1:

6,476.00

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID <i>bf</i>	1	1,241.10	1,241.10
RR BUMPER BOTTOM REINFORCEMENT <i>?</i>	1	73.05	73.05
REAR BUMPER CENTRE GUIDE <i>?</i>	1	56.05	56.05
REAR BUMPER CARRIER (ECE) <i>?</i>	1	470.25	470.25
REAR BUMPER PANEL PRIMED BASIS <i>cm</i>	1	1,184.75	1,184.75
RR BUMPER FLAP TOWING EYE PRIMED <i>?</i>	1	43.70	43.70
REAR PDC HOLDER SET <i>?</i>	1	25.75	25.75
(S/L) LH PROTECTION FOIL <i>?</i>	1	10.75	10.75
(S/L) RH PROTECTION FOIL <i>?</i>	1	10.75	10.75
PLAQUE 74MM <i>nm</i>	1	71.95	71.95
TRUNK LID GASKET <i>nm</i>	1	76.40	76.40

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57849
Date Estimated : 17/03/2021
Prepared By : Brandon Chan Eng Meng

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN8824H	WBA3A16070NS37589	25/07/2014	316iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER LH REFLECTOR <i>mis</i>	1	37.90	37.90
RR BUMPER RH REFLECTOR <i>*?</i>	1	37.90	37.90
REAR LH LIGHT IN TRUNK LID <i>scr</i>	1	274.40	274.40
REAR RH LIGHT IN TRUNK LID <i>?</i>	1	274.40	274.40
DECOUPLING RING PDC TORQUE CONVERTE <i>ne</i>	4	5.15	20.60
ULTRASONIC SENSOR BLACK <i>?</i>	4	239.25	957.00
(DG/SL) ADHESIVE SET K6 <i>ne</i>	1	53.05	53.05

Total Parts : 4,919.75

Claims OD / 3rd Party Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/04/21 @ 1040 Excess S\$ _____

Surveyor's Name Rahul Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,476.00
Parts	:	4,919.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	797.70
Grand Total	:	12,193.45

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/02/2021 17:06 (SGT)
Date of Accident	10/02/2021 12:04 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BT TIMAH ROAD (BEFORE MAKEPACE RD)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN8824H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	DANNY CHAN CHIA AUN
NRIC No	SXXXX031J
Email Address	DANNYCHANCA@GMAIL.COM
Mobile Phone No	(Phone) +65-98378880
Alternative Phone No	+65-98378880

VEHICLE PARTICULARS

Manufacturer	BMW
Model	316i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	Hong Leong
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MP313186
Cover Note Number	MP313186

DRIVER

Name of Driver	CHEONG SZE CHI
NRIC No	SXXXX225E

Date Of Driving Pass	13/10/1998
Driving experience	22 YEARS AND 4 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98378882
Alt. Phone Number	-
Email Address	CHERYLCHEONG@YAHOO.COM
Address	55 MIMOSA VIEW
Address complement	-
Postcode	805635
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENT ATTACH

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB4132S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LEE WEE SENG
NRIC No	SXXXX455G
Contact Number	-
Address	-
Address complement	-

Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	FRONT
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHEONG SZE CHI
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BACK AND NECK
Injured person in which vehicle?	-
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

1. VEHICLE NO.: SKN8824H
2. INSURER CO.: HL

3. ACCIDENT
DATE & TIME: 10/02/21 @ 1204

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;


(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be cited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time 10/02/21



Driver's Signature (if driver is not the policyholder) / Date
& Time 10 February 2021


Witnessed by Reporting Centre
Personnel Jaylyn Iamk 10/02/21

Sketch Plan



Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SKN 88244 (HL)

Date & Time: 10/02/2021 @ 1204 (clear/dry)

I follow front vehicles to slow down & stop. A moment later, felt an impact and realised motor lorry 6BB 41325 had hit onto the back of my stopped vehicle.

*I felt some discomfort on my back & neck area and will seek for medical treatment later on.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 10/02/21

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

- () Claim Own Policy () Claim Third Party () Reporting Only
- () Claim OD/TP at other workshop ()

Apply for PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	031J
Vehicle No.:	SKN8824H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2021
Vehicle Make:	B.M.W.
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	A167J734N13B16A
Chassis No.:	WBA3A16070NS37589
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,343.00
Original Registration Date:	25 Jul 2014
First Registration Date:	25 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$25,881.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jul 2024
PARF Rebate Amount:	\$16,822.00
COE Expiry Date:	24 Jul 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$63,001.00
COE Rebate Amount:	\$20,492.00
Total Rebate Amount:	\$37,314.00

The information contained herein is correct as at 23 Apr 2021

OK

BMW 3 Series 316i

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)



Our Accreditation:



Price	\$59,800		
Depreciation ⓘ	\$14,490 /yr View models with similar depre	Reg Date	16-Jul-2014 (3yrs 2mths 22days COE left)
Mileage	79,800 km (11.8k /yr)	Manufactured ⓘ	2014
Road Tax ⓘ	\$742 /yr	Transmission	Auto
Dereg Value ⓘ	\$37,227 as of today (change)	OMV ⓘ	\$31,404
COE ⓘ	\$63,001	ARF ⓘ	\$25,966
Engine Cap	1,598 cc	Power	100.0 kW (134 bhp)
Curb Weight ⓘ	1,405 kg	No. of Owners ⓘ	2
Type of Vehicle	Luxury Sedan		

Features

BMW 1.6L TwinPower Turbo Engine, 134Bhp, 8 Speed. Auto Start/Stop, iDrive With Bluetooth. Driving Experience Control - Eco Pro, Comfort Or Sports Mode. [View specs of the BMW 3 Series Sedan \(2012-2019\)](#)

Accessories

Sports Rims, Electric Leather Seats, Multi-Function Steering, BMW i-Drive, Climate Control, Rear Aircon.

Description

PML Unit! AA Trust Certified Quality Pre-Owned Vehicle! Full Agent Serviced And Maintained Since Day 1 With Records! New Battery And Tyres Changed In 2019! Tip Top Condition! No Repairs Needed! Guaranteed Accident-Free! Owner Upgrading! STA Welcome! Flexible Bank/In House Loan Available! Trade-In Most Welcome! Hurry Contact Our Friendly Salesman For More Details! Strictly By Appointment.

Category

PARF Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources



SHORTLISTED

HISTORY

Compare




sgCarMart Used Car Warranty

repair bill. Ask your dealer for a warranty on this car. [Learn more](#)



Price Chart

Summary



Click on the point to view the vehicle

♡ Shortlist

⊕ Compare

⚠ Report Error

⋮ More

Seller Information

AA Trust Automotive

★ PREMIUM DEALER 2021 ★

63 vehicles for sale. 69 sold in past 3 mths



140 Paya Lebar Road #10-09

AZ @ Paya Lebar

Tel: 63369906

[Search cars nearby](#)