

ASS. REC. BY:

REF: CS3/MSG20013023/Qvf3 -1

Special Instruction:

Surveyor: SUN PIN

ASSIGNMENT (Office)

From (Person): Christina Wong of MSIG Date/Time: 18/3/2021 2:04 PM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 1188A Insured: YP 6385U

at Workshop m/s Lian Heng Painter Company Tel: 6453 5779

of BLK 11 Sin Ming Industrial Estate Sector B, #01-87

Policy No: 30001412585 Claim No: 250086

Sum Insured: Excess:

Make of Veh: D.O.A. 23/11/2020
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25-11-20 5.28P.M Person Contacted: NOMY Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	INS: BLK 160 SIN MING DRIVE #06-10
	GBG 1188A- X
	YP 6385U- X
4/12/20	Submit PRS, repair range \$3000-\$4000 (5 days)