

ASS. REC. BY:

Steve

REF:

CS/AIG21003549/ET03

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMN 7331X

Yr Regn:

27/8/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Atrage

c.c 1193

Colour:

Red

A/C: Insured / Std / NI / N

Sp. Reading

26281

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

MMBSTA 13AKH 001929

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

18/3/21

D.O.A.

18/3/21

Survey held at

cycle &amp; callag

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-60K

Confirm final figure at \$13,470.52, 16days before GST

red:3145.68;18%

16

Date/Time, File Pass to?



Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Rep. Form:

Comp Sum / U.C. 13470.52



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11941/TAN BOON KAI, DARYL (CHEN WENKA) Reg No/Reg Date SMN7331X / 27/08/201 Date In/Mileage 18/03/2021/ 0 Chassis No MMBSTA13AKH001929 Engine No 3A92UHT2279 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	18/03/2021/ 15:51	QUK	282 / Kevin Leong	64169		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							4950.00
REPALCE REAR <sup>1</sup> BUMPER, BOTH REAR <sup>4</sup> FENDER, BOOT, END <sup>1</sup> PANEL, BODY KIT & AFFECTED AREA				7	X 450		3150
REPAIR ON REAR SPARE TYRE PANEL & REAR LH FENDER							
E PNT98000							2450.00
PAINT WORK ON REAR <sup>1</sup> BUMPER, BOOT, END <sup>1</sup> PANEL, SPARE TYRE PANEL, BOTH REAR <sup>2</sup> FENDER & BODY <sup>1</sup> KIT				6	X 350		2100
E PNT88000							240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR							
M SUNDRY							80.00
TO APPLY WINDSCREEN SEALANT							
E PNT88000							120.00
REMOVE & INSTALL REAR PARKING ASSIST							
E PNT88000							120.00
TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR							
E PNT88000							120.00
TO REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR							
E PNT88000							80.00
TO REMOVE & INSTALL BODY KIT							
M SUNDRY							120.00
TO APPLY SEALANT ON AFFECTED AREA							
M SUNDRY							40 80.00
PERFORM RUST PREVENTION							
A 54900099							30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							220.00
TO SUPPLY REVERSE SENSOR							
M SUNDRY							40 50.00
TO SUPPLY 'MIVEC' EMBLEM							
M SUNDRY							40 50.00

# Estimate

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11941/TAN BOON KAI, DARYL (CHEN WENKA) Reg No/Reg Date SMN7331X / 27/08/201 Date In/Mileage 18/03/2021/ 0 Chassis No MMBSTA13AKH001929 Engine No 3A92UHT2279 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/03/2021/ 15:51	QUK	282 / Kevin Leong	64169			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO SUPPLY 'C & C' EMBLEM								30 50.00
M SUNDRY								
SUNDRIES								450.00
A 13900099								
REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR								
M	LAMP ASSY, COMB, RR LH	/ CRA			1.00	337.00	23.00	259.49
M	LAMP ASSY, COMB, RR RH	/ CRA			1.00	337.00	23.00	259.49
M	LAMP ASSY, LICENSE PLATE	X			1.00	51.00	23.00	39.27
M	REFLECTOR LH				1.00	23.00	23.00	17.71
M	REFLECTOR RH				1.00	23.00	23.00	17.71
M	BRACKET, RR BUMPER, LH	/ BR			1.00	28.00	23.00	21.56
M	BRACKET, RR BUMPER, RH	/ BR			1.00	28.00	23.00	21.56
M	FACE, RR BUMPER	/ OO			1.00	751.00	23.00	578.27
M	PANEL, QTR, OTR RH	/ OO			1.00	767.00	23.00	590.59
M	PANEL, RR COMB LAMP HSG, RH				1.00	60.00	23.00	46.20
M	PANEL, RR COMB LAMP HSG, LH				1.00	60.00	23.00	46.20
M	PANEL, RR END	/ OO			1.00	427.00	23.00	328.79
M	GLASS, RR WINDOW	X APC			1.00	544.00	23.00	418.88
M	STOPPER, WINDSHIELD GLASS	/ APC			2.00	3.00	23.00	4.62
M	SPACER, RR WINDOW	/ APC			3.00	9.00	23.00	20.79
M	WEATHERSTRIP, TRUNK LID	/ CRA			1.00	157.00	23.00	120.89
M	PANEL, TRUNK LID	/ OO			1.00	795.00	23.00	612.15
M	HINGE, TRUNK LID, LH				1.00	203.00	23.00	156.31
M	HINGE, TRUNK LID, RH				1.00	203.00	23.00	156.31
M	LATCH, TRUNK LID	X			1.00	218.00	23.00	167.86
M	STRIKER, TRUNK LID LATCH	X			1.00	20.00	23.00	15.40
M	GARNISH, RR END PANEL				1.00	336.00	23.00	258.72
M	MARK, THREE-DIA	/ APC			1.00	70.00	23.00	53.90
M	MARK, ATTRAGE	/ APC			1.00	21.00	23.00	16.17
M	BOARD, TRUNK ROOM FLOOR				1.00	195.00	23.00	150.15
M	TRIM, RR END	/ CUT			1.00	66.00	23.00	50.82
M	UNPAINTED BODYKITS	/ BR			1.00	1643.00	20.00	1314.40
M	PANEL, QTR, OTR LH	/ OO			1.00	759.00	23.00	584.43

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

## Invoice Name &amp; Address

AIG Asia Pacific Insurance Pte.  
Ltd.  
MOTOR CLAIM DEPT  
78 SHENTON WAY #09-16  
AIG BUILDING  
SINGAPORE 079120  
Contact No 6419 1892

## Owner Name &amp; Vehicle Info

Cust No/Name KCV11941/TAN BOON KAI, DARYL (CHEN WENKA)  
Reg No/Reg Date SMN7331X / 27/08/201  
Date In/Mileage 18/03/2021/ 0  
Chassis No MMBSTA13AKH001929  
Engine No 3A92UHT2279  
Make/Model MIT/19MY ATTRAGE 1.2 CVT  
Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/03/2021/ 15:51	QUK	282 / Kevin Leong	64169

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M MUD GUARD,RR LH	1.00	41.00	23.00	31.57
M MUD GUARD,RR RH	1.00	41.00	23.00	31.57

BR (Bumper inner plate)

Steve CLKK)

18/3/21

3.99%

00-NM AL

Excess - ?

16 days

Estimate

My Bel Sky

- LKK Auto Consultants would notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

	Nett	15,721.78
7% GST on	15721.78	1100.52

Total Payable 16,822.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT:

Date of Submission	18/03/2021 13:15 (SGT)
Date of Accident	18/03/2021 07:18 (SGT)
Exact Location of Accident	KPE, Singapore
Additional Location Information	ENTERING KPE TUNNEL FROM PUNGGOL
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN7331X

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN BOON KAI, DARYL
NRIC No	SXXXX061D
Email Address	HEARTSABLAZED@GMAIL.COM
Mobile Phone No	(Phone) +65-91111182
Alternative Phone No	+65-91111182

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900151413
Cover Note Number	-

### DRIVER

Name of Driver	TAN BOON KAI, DARYL
NRIC No	SXXXX061D
Date Of Birth	12/05/1988
Occupation	Indoor



Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

23/08/2008  
12 YEARS AND 7 MONTHS  
Male  
(Phone) +65-91111182  
+65-91111182  
HEARTSABLAZED@GMAIL.COM  
BLK 273B PUNGGOL PLACE #10-872

822273

Yes

No

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Chain Collision  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No  
3  
No  
-  
Yes  
2  
No

#### PASSENGER 1

Name  
Gender

ELORA TAN  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

Yes  
Yes  
No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number

SLT1159Y  
Hyundai  
-  
-  
Red  
Private car  
TAN HONG QUAN  
(Phone) +65-98519459

Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	AGI
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2ND CAR
	-

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMP9381C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	GAUTAM GYAN PRAKASH
Contact Number	(Phone) +65-98370425
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	3RD CAR
No. Of Passenger (Including Driver)	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

#### Sketch Plan






**Describe Circumstances of the Accident**

Enter KPE tunnel 1st lane. Traffic slowed and front car came to a sudden stop. My car was able to stop in time. 2 cars behind me collided into my car.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Name of Policyholder** : Tan Boon Kai Daryl  
**Period of Insurance** : 27 Aug 2019 To 26 Aug 2021  
**Engine No.** : 3A92UHT2279  
**Chassis No.** : MMBSTA13AKH001929

**Vehicle No.** : SMN7331X  
**Policy No.** : 1900151413  
**Endorsement No.** :  
**Issued Date** : 03 Sep 2019

#### ABOUT THE COVER

**Make/Model** : MITSUBISHI ATTRAGE 1.2 CVT  
**Engine Capacity/Tonnage** : 1,193.00 CC  
**Driver Restriction** : NA  
**Person or Classes of Persons Entitled to Drive\*** :  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2019  
**Insuring with COE/PARF** : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

**Limitation as to use\*** :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

**Loss of Use 1500cc - 1600cc**

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

#### EXCESS

**Section 1**  
**Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0**

**Section 2**  
**Property Damage - \$0**

**Windscreen : \$100**

**Named Driver and Excess (where applicable)**

Tan Boon Kai Daryl - \$600 (Own Damage)

#### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 406650 67461000
4. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

#### IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan: United Overseas Bank Limited**

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623206

FULCOMICP2 - JN

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
AUTHORISED REPRESENTATIVE

SSCI-MG