

108/11/13) wef

ASS. REC. BY: Form

REF:

CS/CT121003558/R19d3

677
67B

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV132SZat Workshop m/s: PERFORMANCEof 303, MCKENDRA RDInsured: CTIPolicy No. DMCVSNW00061532003Claims No. SNM21D201489C02

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 94K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLV132SZ Yr Regn: 2017 / DECType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 216I GT LED c.c. 1499Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 46418 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA20920605E91563Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/03/21 D.O.I. 23/03/21Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 41K

30/03/21 Rasul finalised with Jing Xuan final fig \$6526.35, 4 days (Red \$1049.50, 14%)

31/03/21@12.36pm revised to Tan Kah Leong via Merimen.

Date/Time, File Pass to?

☐ : Preli. Report

1) 31/03 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)Report Format: MER-TP

Lump Sum / I.B.I: (\$ _____)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57848
Date Estimated : 17/03/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ng Khong Voon
196D West Coast Road

Singapore 127379

- ACCOUNT - 40000

Cash Sales - Service
Singapore

China Taipei

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV1325Z	WBA2D920605E91563	22/12/2017	216i G TOURER	0

DESCRIPTION

To replace front right door and wing mirror assembly.

1275 1,700.00

To painting front right door and wing mirror cover.

1001 1,113.00

To check electrical wiring system

150 177.00

To transfer lock mechanism from old to new door including
conduct check on new door power window system for proper
function. (1 door).

951 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries

80.00

Total Labour 1: 3,719.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
FRT RH DOOR <i>bt</i>	1	1,142.60	1,142.60
RH MIRROR GLASS HEATED WIDE ANGLE <i>ms</i>	1	687.20	687.20
RH COVER MIRROR BASE <i>ms</i>	1	28.80	28.80
RH OUTSIDE MIRROR COVER CAP PRIMED <i>ms</i>	1	115.30	115.30
RH SUPPORTING RING <i>ms</i>	1	58.95	58.95
RH LOWER HOUSING SECTION <i>ms</i>	1	46.10	46.10
RH WIRING HARNESS EXT. MIRROR HEATE <i>cut</i>	1	77.10	77.10
Exterior mir <i>ms</i>	1	496.10	496.10
RH ADDITIONAL TURN INDICATOR LAMP <i>ms</i>	1	59.65	59.65
FRT RH DOOR BRAKE ?	1	74.60	74.60
FRT DOOR EDGE PROTECTION <i>ms</i>	1	158.65	158.65
RH SEAL A PILLAR ?	1	48.35	48.35
DRIVE OUTSIDE MEMORY MIRROR <i>ms</i>	1	441.95	441.95
RH MIRROR ELECTRONICS <i>ms</i>	1	410.35	410.35

Total Parts : 3,845.70

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 57848
Date Estimated : 17/03/2021
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV1325Z	WBA2D920605E91563	22/12/2017	216i G TOURER	0

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 23/03/21 @ 1130 Excess S\$ _____

Surveyor's Name RKam Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	3,719.00
Parts	:	3,845.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	529.53
Grand Total	:	8,094.23

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/03/2021 11:51 (SGT)
Date of Accident 13/03/2021 15:30 (SGT)
Exact Location of Accident Pandan Gardens, Singapore
Additional Location Information 406 PANDAN GARDENS CARPARK
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV1325Z

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG KHONG VOON
NRIC No SXXXX677B
Email Address khong-voon.ng@hotmail.com
Mobile Phone No (Phone) +65-96602053
Alternative Phone No +65-96602053

VEHICLE PARTICULARS

Manufacturer BMW
Model 216i
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company Direct Asia
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MT/00557934/02
Cover Note Number -

DRIVER

Name of Driver CHIAM BAO YING, LOUISA
NRIC No SXXXX153E
Date Of Birth 07/04/1982
Occupation Indoor

Of Driving Pass
ing experience
nder
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

20/05/2009
11 YEARS AND 10 MONTHS
Female
(Phone) +65-91827754
-
LOUISA_CHIAM@HOTMAIL.COM
196D WEST COAST ROAD
-
127379
No
Spouse
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface
Side Swipe
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name
Gender
FRANCIS ZHAN
Male

PASSENGER 2

Name
Gender
ISAAC NG
Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
GBG4393D
-
-
-

Vehicle Colour
Vehicle Category
Name of Driver
NRIC No
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
Commercial vehicle
KOH YAM KOON
SXXXX086B
(Phone) +65-83326106
-
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: 88V 1352
ACCIDENT DATE: 13/03/2021 @ 15:30

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOT THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/3/21
13/3/21

CHARN'S CUSTOMCRAFT
Reporting Centre Personnel's Signature
Name:
NR C/IN No.:

016 9271 P

Date: 13 March 2021
Time: 330pm
Address: 406 Pandan Gardens carpark

I was driving into the carpark and slowing the car down to let the passenger alight when a truck (GBG 4393D) parked head-in reversed and crashed into my right-side mirror

OWN DAMAGE () 3RD PARTY CLAIM (✓) REPORTING ONLY () OWN WORKSHOP (✓)

I/We declare the foregoing particulars are true in every respect.

15. 11. 20

DATE & Time: 15 May 2021

NRIL/IN No.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	677B
Vehicle No.:	SLV1325Z
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Mar 2021
Vehicle Make:	B.M.W.
Vehicle Model:	216i GT LED
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	31055106B38A15A
Chassis No.:	WBA2D920605E91563
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$28,741.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$32,238.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2027
PARF Rebate Amount:	\$24,178.00
COE Expiry Date:	21 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$28,535.00
Total Rebate Amount:	\$52,713.00

The information contained herein is correct as at 24 Mar 2021

OK

BMW 2 Series 216i Gran Tourer

Overview Financial Accessories Similar Research Photos Map

Price \$93,888

Depreciation ⓘ \$11,410 /yr
View models with similar depre

Reg Date 30-Nov-2017
(6yrs 8mths 5days COE left)

Mileage 75,000 km (22.6k /yr)

Manufactured ⓘ 2017

Road Tax ⓘ \$684 /yr

Transmission Auto

Dereg Value ⓘ \$55,829 as of today (change)

OMV ⓘ \$30,858

COE ⓘ \$44,002

ARF ⓘ \$35,202

Engine Cap 1,499 cc

Power 75.0 kW (100 bhp)

Curb Weight ⓘ 1,480 kg

No. of Owners ⓘ 1

Type of Vehicle MPV

Features

BMW Twin Power Turbo 3 Cylinder Engine With 102bhp, 180Nm Of Torque. 0-100km/h In 11.9s, Front Wheel Drive, 6 Speed Transmission, 17" Sport Rims, LED. View specs of the BMW 2 Series Gran Tourer (2016-2021)

Accessories

Steering Wheel Controls, Knockdown Rear Seats, Leather Seats, ISOFIX, Solar Film, In Car Cam.

Description

Cheapest BMW 216 MPV 7-seater In The Market, 1 Owner Only, Fully Maintained And Warranty With Performance Motor. Lowest Loan Interest, High Loan Available, Original Paint Work And 100% No Accident. Clad In Grey With Tan Leather Upholstery. Be Pampered With The Ample Space Of Head And Leg Room, LED Headlights With LED DRL, Front Electric Seats With Driver Memory.

Category

PARF Car, Premium Ad Car

Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources




sgCarMart Used Car Warranty

Get \$0 future car repair bill. Ask your dealer for a warranty on this car. Learn more




Car Valuation - Free

Find out the market value of your existing car for free. Get started



Price Chart



Click on the point to view

Shortlist

More

Seller Information