

ASS. REC. BY:

REF: CS3/ASM21003587/R1vf3

Special Instruction:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): YU DOMINIC YISHAN

of AXA

Date/Time: 18/3/2021 11:16 PM

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 3679M

Insured:

SHB 4079S

at Workshop m/s

Master Car Spray Services

Tel:

9856 8137

of Block 40 Toh Guan Road East #01-67 Enterprise Hub, Singapore 608582

Policy No:

Claim No:

S1M0356U

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11-03-2021

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 19-03-21 12.274P.M

Person Contacted:

PAULINE

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJC 3679M- X
	SHB 4079S- CS3/FCI19019458/Hcf3e2 DOA:16/10/2019
23/3/21	Send IA (PRS) via Smart Claim
23/3/21	Submit PRS, repair range \$3,000-\$4,000 (4 days)